

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 14.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Koheer	33KV	Sangareddy	00.45	11.20	10.35		BD PIN BINDING CONNECTION WORK	Koheer	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 14.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thatipamula	Sriram Thanda	11KV	Suryapet	13.30	15.20	01.50	E/L	Insulator failed	-
2		Munagala	Kokkereni-2	11KV	Huzurnagar	03.05	07.15	04.10	EL	11 KV LINE SNAPPED	-
3		Pamangundla	Pittampally	11KV	Nalgonda	12.00	13.00	01.00	EL	Jumper cut	-
1	SDP	Potharam	Vangaramayapally	11KV	Husnabad	14.40	15.40	01.00		Insulator fail	-
2		Gagillapur	Vallampatla	11KV	Husnabad	11.57	13.02	01.05		Line problem	-
1	RR N	Subhash Nagar	Jeedimetla	11KV	Medchal	03.00	04.30	01.30		11KV 11KV Cable fault at Mallikarjuna Temple	-
2		UMCC	Mahadevpuram	11KV	Medchal	16.05	16.25	00.20		AB Cable End Kit failed in SS(Backfeeding arranged from 11KV Crusher feeder)	-