

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988	1	1	1	1	1	1			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>2</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 23.02.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Achampet	Uppunuthala	33KV	Nagarkurnool	09.16	18.25	09.09	E/L	2Nos 33KV Insulator replacement near SWR School at Achampet	Uppunuthala	Only Singal Phase Supply Given From 33KV Veltoor feeder at 10:50Hrs
1	NLG	Miryalguda	Tripuraram	33KV	Miryalguda	0:00	10:00	10:00		Breaker and CT blast at 220 KV SS	Tripuraram	No

TSSPDCL - LMRC / Corporate office

Date: 23.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Khajipur	11KV	Narayanapet	08.27	09.20	00.53		Due to 11KV Disc failed at Khajipur vg	No
2		Mohammadabad	Venkatreddypally	11KV	Narayanapet	12.50	13.25	00.35		Due to crow fallen on 11KV line	No
1	NLG	Aipoor	Mukkudu devulapally	11KV	Suryapet	9:25	10:25	1:00	EL	Insulator failed	No
1	SDPT	Narayanraopet	Rajannagudi	11KV	Siddipet	14:20	16:00	1:40		Bird fallen on the line	No
2		Kondapaka	Vishwanathpally	11KV	Gajwel	08.30	09.50	01.20		Jumper cut	No
3		Bekkal	Kutigal	11KV	Husnabad	06.40	08.20	01.40		Tree branch fallen on the line	No
4		Bejjanki	Kallepally	11KV	Husnabad	07.40	10.40	03.00		11 KV Line cut	No
1	RR N	Petbasheerabad	St.Aann's	11KV	Medchal	15:30	15:50	0:20		11KV Line AB Switch opened at Paramitha Hospital (tree fallen on 11KV Line)	No
2		Ravalkole	IDA Ravalkole	11KV	Medchal	14.05	15.55	01.50		11KV UG Cable failed at Kashimbhai Thanda (2No Crusher in off)	No