

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	5	3	5	3	5			
2	NLG	144	988		5		5		5			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>11</b>	<b>3</b>	<b>11</b>	<b>3</b>	<b>11</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>14</b>	<b>3</b>	<b>14</b>	<b>3</b>	<b>14</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 26.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Jaklair	33KV	Narayanapet	11.45	15.50	04.05	E/L	No Visible Fault	Narayanapet	-
2		Makthal	Gudeballore	33KV	Narayanapet	11.10	11.35	00.25	E/L	Tree branch follen on the line	Narayanapet	Alternate Supply Arranged From 33KV Krishna at 11:35Hrs
3		Wanaparthu	Buddaram	33KV	Wanaparthu	09.14	15.53	06.39	E/L&O/L	Conductor Snapped & 4No's Pin Binding Replaced Between Wanaparthu & Gopalpet	Wanaparthu	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 26.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gudeballe	CHECKPOST	11KV	Narayanapet	09.20	12.00	02.40		11KV conductor cut near checkpost	-
2		Kondapur	KISTAPUR	11KV	Narayanapet	10.15	12.00	01.45		squirrel fallen on DTR at kistapur vlg	-
3		Kondapur	HANMANPALLY	11KV	Narayanapet	13.00	16.35	03.35		11kv line cut and fallen on LT line at cheruvu	-
4		DAMARGIDDA	SAJNAPUR	11KV	Narayanapet	08.05	08.59	00.54		11KV LINE CUT	-
5		MOGALMADKA	ASHANPALLY	11KV	Narayanapet	15.46	16.57	01.11		SQUIRREL CLIMBED THE 11 KV LINE	-
1	NLG	Kudakuda	Komatikunta	11KV	Suryapet	09.28	11.05	01.37	EL	Insulator failed	-
2		Gaddipally	Ponugodu	11KV	Huzurnagar	09.10	10.30	01.20	EL	11 KV LINE SNAPPED	-
3		Ragnathpur	Ragnathpur Agl	11KV	Bhongir	08.45	12.30	03.45	EL/OL	11KV Line snapped near Raghunathpur Village	-
4		Juloor	Peddagudem	11KV	Choutuppal	06.45	08.06	01.21	EL/OL	11 kv Pin insulator failed near Peddagudem village	-
5		Arror	Lingarajupally	11KV	Choutuppal	07.15	08.56	01.41	EL/OL	11 kv Line snapped at Nimmala Swamy well near Lingarajupally village	-
1	MDK	Bollaram-II	Rupa	11KV	Patancheru	13.25	14.40	01.15		BD due to Tree branches fallen on the line	-
1	RR N	Devarayamjal	Kottapet	11KV	Medchal	09.00	11.00	02.00		11KV Line Cut & Replaced at Thurkonikunta, Devarayamjal	-
1	HYD N	I.D.P.L	Bala Nagar	11KV	VI	13.05	14.20	01.15	OL-Bph	AB Cable B/O at Fathe Nagar Bridge	-
2		Pragatools	Giri Nagar	11KV	VI	14.20	15.38	01.18	OL-Rph	HT Line snapped at Vishal School	-