

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	3	3	3	3	3			
2	NLG	144	988		2		2		2			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	7	3	7	3	7	0	0	
	Grand Total	1082	6468	3	9	3	9	3	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.02.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Hanwada	33KV	Mahabubnagar	00.40	01.30	00.50	E/L&O/L	Cable Problem	Hanwada	Alternate Supply Arranged From 132KV SS Maddur at 01:30Hrs.
2		Marikal	Ekilaspur	33KV	Narayanapet	13.56	14.06	00.10	E/L	No Visible Fault	Ekilaspur	Waddeman Loads are Diverted
3		Wanaparthy	Buddaram	33KV	Wanaparthy	07.50	08.12	00.22		Jumper Damaged Near 220KV SS Wanaparthy	Buddaram	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Pallerla	Parsapur	11KV	Narayanapet	09.14	15.40	06.26		11 KV line cut at Hanmiya Tanda	No
2		Kolpur	KOLPUR	11KV	Narayanapet	11.20	12.45	01.25		11KV line cut at kolpur vlg	No
3		MOGALMADKA	ANNASAGAR	11KV	Narayanapet	12.15	12.36	00.21		HT/LT CROSSING, LOOSE LINE GADPA VILLAGE	No
1	NLG	Ch.Annaram	Ch.Annaram	11KV	Nalgonda	12:05	18:25	6:20	EL	11 KV Jumper Cut	No
2		Panthangi	Panthangi Agl	11KV	Choutuppal	13.43	15.19	01.36	EL	DTR 11KV Insulator Failed	No
1	MDK	EPIP-III	Ufoam	11KV	Sangareddy	6:20	7:20	1:00		Tree branch fallen on the line	No
1	SDPT	Gambeerpur	Shiljinagar	11KV	Siddipet	8:10	9:11	1:01		B/D Bird Touch Lc No 2759	No
1	RR N	Subhash Nagar	Suchitra	11KV	Medchal	7:15	7:45	0:30		11KV Pin Insulator Failed at Teja wines backside	No
1	RR E	Uppal	Navbharath	11KV	Habsiguda	18:10	19:30	1:20		Tree Branches fallen on 11kv line at Mahendra show room & jumper cut at DsL Opp	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
------	--------	-----------------------	-------------------------	-----	-------------------------	------	----	----------	---------------------	--------------------	---------------------------