

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		7		7		7			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	1	3	1	3	1			
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	4	4	4	4	4	0	0	
	Grand Total	1082	6468	4	11	4	11	4	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.01.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Maldakal	33KV	Gadwal	14.30	17.55	03.25	LV's Pol Out	2 Nos Pin Insulator Replacement at Chelgunpally Village	Maldakal	No
2		Ieeza	Mitta Doddy	33KV	Gadwal	12.42	14.40	01.58	E/L	Cover Fallen on the Condcutor	Mitta Doddy	No
3		Balanagar	Dilip Rolling Mills	33KV	Mahabubnagar	23.35	03.30	03.55	E/L	Break down R Phase LA Fail & conductor snapped near by 132KV Balanagar	Dilip Rolling Mills	No
1	NLG	Suryapet	Nuthankal	33KV	Suryapet	4:40	9:50	5:10	EL	Jumper cut	Nuthankal	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Amith Cotton	11KV	Jadcherla	22.40 (05.01.21)	10.20 (06.01.21)	11.40		11KV Insulator Failure Near Cebelco Company Side.	No
1	NLG	Yararam	Kamepally	11KV	Devarakonda	12:10	12:45	0:35	EL	11 KV Jumper Cutt	No
2		Thungathurthy	Vempaty	11KV	Suryapet	09.30	11.45	02.15	EL	Jumper cut	No
3		Raghunadapalem	Nakkagudem	11KV	Huzurnagar	03.15	07.30	04.15	EL	11 KV LINE SNAPPED	No
1	HYD N	Osm. University	Mettuguda	11KV	V	07.05	09.00	01.55	EL	Cable fault at Mettuguda Church (2Nos. DTRs kept off)	(at 08:15 Hrs partial fdr charged)
2		Gunrock	Tirumalagiri	11KV	C-VI	17:50	19:15	1:25	EL	No Visible Fault	Arranged B/F on 11KV Lal Bazar fdr
1	HYD S	Falaknuma	Jangam Mett OH	11KV	III	16.18	17.20	01.02	EL	Insulator flash over at Post Office	No
2		Kandikal Gate	Khazipura	11KV	III	16:20	17:35	1:15	EL,OL	Flexi fallen on lines at Karebia Masjid	No
3		Miralam	Mustafa Nagar	11KV	III	16:36	17:36	1:00	EL,OL-Bph	Pin Insulator flash over at Siddiq Plaza	No
4		Kandikal Gate	Naseeb Nagar	11KV	III	16:20	17:20	1:00	EL,OL	Tree branches fallen on lines at Naseeb Nagar	No
1	HYD C	Tolichowki	Kala Banglaw	11KV	VII	17.05	18.28	01.23	EL,OL	No Visible Fault	Arranged B/F on 11KV Military fdr