

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		17		17		17			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>23</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	23	5	23	5	23			
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT			2	21	2	21	2	21			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>7</b>	<b>45</b>	<b>7</b>	<b>45</b>	<b>7</b>	<b>45</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>68</b>	<b>7</b>	<b>68</b>	<b>7</b>	<b>68</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 07.01.2021

## Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Kankurthy	33KV	Narayanapet	01.55	03.05	01.10	E/L	Due to No Visible fault found		Alternate Supply Arranged From 33KV Mogalmadka
2		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	03.30	08.20	04.50	E/L	Tree branch follen on the line		Alternate Supply Arranged From 132KV SS Wanaparthy
3		leeza	Mitta Doddy	33KV	Gadwal	06.20	13.25	07.05	E/L	Replacement of Female Contacts Near Mittadoddy		No
4		leeza	Madelabanda	33KV	Gadwal	05.57	10.13	04.16	E/L	Flash Over Insulator Replaced Near leeza Bus Stand		No
5		Alampur	Alampur	33KV	Gadwal	03.34	05.24	01.50	E/L&O/L	AB Switch Problem at Bheemavaram SS		No
1	SDPT	Habshipur	Thimmapur	33KV	Siddipet	05.31	09.45	04.14		B/D for 132KV Siddipet Line Conductor cut & fall on 33KV LineThimmapur		-
2		Siddipet	Rangadhampally	33KV	Siddipet	05.30	13.40	08.10		B/D for EL Tripping		-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 07.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Renivetta	11KV	Narayanapet	02.50	07.30	04.40		Due to Tree Branch fallen on 11 KV line	-
2		Maddur	Khajipur	11KV	Narayanapet	03.05	08.05	05.00		Due to Tree Branch fallen on 11 KV line	
3		Pallerla	Parsapur	11KV	Narayanapet	05.00	08.10	03.10		Due to 11KV insulator failed	
4		Gokulnagar	Nandigama	11KV	Narayanapet	03.30	09.30	06.00		Due to Tree Fallen on 11KV line	
5		Kothapally	Nidjintha ®	11KV	Narayanapet	02.40	07.30	04.50		Due to pole damaged at Nidjintha village	
6		Bijwar	PEDDAJATRAM	11KV	Narayanapet	09.30	10.40	01.10		Due to inulator failure at cheruvukatta	
7		Gudeballore	SATAYASAI & LIFT	11KV	Narayanapet	03.20	07.53	04.33		Due totree branch fallen on 11KV line	
8		Gudeballore	MURHARIDODI	11KV	Narayanapet	04.20	07.53	03.33		Due to tree branch fallen on 11KV line	
9		Uttoor	PAGIDIMARRY	11KV	Narayanapet	05.20	09.15	03.55		Due to 11kv cond cut at agaram agl	
10		KANKURTHY	LOKURTHY	11KV	Narayanapet	05.30	07.40	02.10		DUE TO DISC FAILURE, AT LOKURTHY AGL	
11		KANKURTHY	DAMARGIDDA	11KV	Narayanapet	05.30	07.35	02.05		DUE TO 11KV CONDUCTOR CUT , AT UDMALGIDDA AGL	
12		KANKURTHY	KANKURTHY	11KV	Narayanapet	05.30	06.35	01.05		DUE TO TREE FALLEN ON THE CONDUCTOR, AT KANKURTHY VILLAGE	
13		APPAKPALLY	11KV JAJAPUR	11KV	Narayanapet	04.45	07.00	02.15		DUE TO DISC FAILURE, AT LOKURTHY AGL	
14		APPAKPALLY	11KV SATYASAI WATER WORKS	11KV	Narayanapet	04.45	07.10	02.25		DUE TO DISC FAILURE, AT LOKURTHY AGL	
15		33/11 KV DAMARGIDDA SS	11 KV WATERGRID FEEDER	11KV	Narayanapet	06.40	09.30	02.50		DUE TO DISC FAILURE, AT LOKURTHY AGL	
16		MOGALMADKA	11 KV ANNASAGAR FEEDER	11KV	Narayanapet	04.00	06.15	02.15		DUE TO 11KV CONDUCTOR CUT , AT ANNASAGAR AGL	
17		MOGALMADKA	11KV ASHANPALLI FEEDER	11KV	Narayanapet	07.13	09.53	02.40		DUE TO DISC FAILURE, HT/LT AT NARSAPUR VILLAGE	
18		KYATHANPALLY	WATHUGUNDLA	11KV	Narayanapet	05.00	08.40	03.40		DUE TO 11KV LINE TO PHASE TO PHASE	-
19		KYATHANPALLY	KYATHANPALLY	11KV	Narayanapet	03.30	07.25	03.55		DUE TO DISC FAILURE, AT KANDENPALLY VILLAGE	-
20		33/11 KV PERAPALLA SS	11KV SHASHANPALLY FEEDER	11KV	Narayanapet	03.30	06.50	03.20		DUE TO 11KV CONDUCTOR CUT , ATKOTHAPALLY THANDA	-
21		NARAYANPET	11 KV VIP FEEDER	11KV	Narayanapet	02.45	05.30	02.45		DUE TO TREE FALLEN ON THE CONDUCTOR, NEAR POST OFFICE	-
22		33/11 KV CHINNAJATRAM SS	11 KV ANTHWAR FEEDER	11KV	Narayanapet	00.34	07.54	07.20		DUE TO DISC FAILURE, AT LINGAMPALLY VILLAGE	-
23		33/11 KV CHINNAJATRAM SS	11KV WATER GRID FEEDER	11KV	Narayanapet	06.45	08.50	02.05		DUE TO DISC FAILURE,	-
1	NLG	Yerkaram	Das Thanda	11KV	Suryapet	06.51	07.56	01.05	E/L	Insulator flashover	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDPT	Musthabad x Road	Gadicherpally	11KV	Siddipet	07.30	10.15	02.45		B/D for Tree Branches fall on 11KV Line	-
2		Chinnagudavally	Chinnagudavally	11KV	Siddipet	04.50	11.25	06.35		B/D for OL/EL Tripping	-
3		Machapur	Machapur	11KV	Siddipet	04.30	11.00	06.30		B/D for Conductor cut LC No.11028	-
4		Gurrallagondi	Malyal	11KV	Siddipet	05.40	08.22	02.42		B/D for Insulator fail	
5		Gurrallagondi	Laxmidhevipally	11KV	Siddipet	07.14	08.45	01.31		B/D for Insulator fail LC No.11390	
6		Dubbak	Chellapur	11KV	Siddipet	07.15	10.14	02.59		B/D for 11KV Conductor cut	
7		Dubbak	Chervapur	11KV	Siddipet	09.15	11.50	02.35		B/D for Disc fail	
8		Peddachekode	Achamaipally	11KV	Siddipet	08.30	13.00	04.30		B/D for Tree Branches fall on 11KV Line LC No.4760	
9		Ramakkapet	Ramakkapet	11KV	Siddipet	05.55	12.43	06.48		B/D for Dick fail & Insulator fail	
10		Mirdoddy	Andhey	11KV	Siddipet	07.15	15.30	08.15		B/D for Tree Branches fall on 11KV Line LC No.23425	
11		Peddachepayl	Lingupally	11KV	Siddipet	05.00	12.00	07.00		B/D for Disc fail LC No.37377	
12		Akbarpet	Bhoompally	11KV	Siddipet	05.10	11.40	06.30		B/D for 11KV Conductor cut	
13		SINGATAM	ANANTHARAOPALLY	11KV	Gajwel	04.03	10.29	06.26		3-Ph DTR WIRE CUT	
14		NACHARAM	NACHARAM AGL	11KV	Gajwel	01.00	13.00	12.00		11KVA DISK FAILED 3-Ph BREAKDOWN (1-Ph RUNNING)	
15		THIMMAREDDYPALLY	THIMMAREDDYPALLY AGL (LC NO:	11KV	Gajwel	01.45	08.25	06.40		BREAKDOWN AUTO RECTIFIED	
16			INDUSTRIAL FEDEER	11KV	Gajwel	16.45	17.25	00.40		11KVA DTR FAILED	-
17		RAMPUR	RAMPUR	11KV	Gajwel	05.00	10.20	05.20		INSULATOR FAILED	-
18		Koheda	Theegalakuntapally	11KV	Husnabad	05.30	09.30	04.00		Insulator Fail	-
19		Gurjakunta	Gurjakunta Agl	11KV	Husnabad	05.50	09.00	03.10		Insulator Fail	-
20		Guruvannapet	Guruvannapet	11KV	Husnabad	03.50	06.40	02.50		11 KV line cutting	-
21		Bekkal	Kondapur	11KV	Husnabad	06.00	14.20	08.20		Pole Damage	-
1	RR N	Subhash Nagar	Bank Colony	11KV	Medchal	00.14	01.10	00.56	BD	11KV Disc failed at Venkanna Hills	-
2		Jeedimetla-III	USP Oraganic	11KV	Jeedimetla	12.15	15.35	03.20	BD	AB Cable failed at Stand Glash Company , Phase-I	-
1	RR E	Moula-Ali	Mirzalguda	11KV	Sainikpuri	04.45	07.20	02.35		11Kv Disk and 11Kv Insulaotr failed near Ganesh Temple at ZTS Chowrastha (Artisian Janaiah)	-
2		Kushaiguda	NN Colony	11KV	Sainikpuri	05.00	06.30	01.30		11KV line AB Switch Jumper cut at Kushiaguda Industry (AE)	-
3		Nacharam	Nagarjuna	11KV	Habsiguda	01.03	02.20	01.17		11KV Disk failed at Sifco company	-
4		Nacharam	Nagarjuna	11KV	Habsiguda	05.10	06.30	01.20		Cable G.I Wire touched to phase line at Raheja company	-
1	HYD N	Prashanth Nagar	Andhra Jyothi	11KV	VI	04.50	06.10	01.20	OL-Rph	11KV Conductor snapped at Rajiv Gandhi Nagar	-
2		Patigadda	Sindhi Colony	11KV	V	05.05	06.25	01.20	EL	Pin Insulator flash over at Sindhi Colony	-
3		Vasanthapuri	Sheshapadu	11KV	V	05.07	06.57	01.50	EL	No Visible Fault (Due to Rain)	-
4		James Street	C.T.C	11KV	V	05.20	06.30	01.10	EL	No Visible Fault (Due to Rain)	-
5		Monda Market	Palika Bazar	11KV	V	05.20	08.20	03.00	EL,OL	Disc Insulator flash over at Chapala Bawi	-
6		Hakimpet	Allenby Lines	11KV	C-VI	05.25	07.50	02.25	EL	No Visible Fault (Due to Rain)	-
7		Marredpally	Ramser Café	11KV	C-VI	05.30	06.50	01.20	OL-Yph	UG Cable fault at Sri Sai Enclave	-
8		James Street	P.G Road	11KV	V	05.30	06.36	01.06	EL,OL	No Visible Fault (Due to Rain)	-
9		Gymkhana	Balamrai	11KV	C-VI	17.20	19.20	02.00	EL	Sparking AB Switch at Paigah Colony	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	E.N.T	Troop Bazar	11KV	IX	04.40	06.10	01.30	OL-R&Bph	Tree branches fallen on lines at Koti Main Road	-
2		Karwan	Tallagadda UG	11KV	IX	05.10	06.25	01.15	EL,OL-R&Bph	Tree branches fallen on lines at Pochamma Temple	-
3		Osm. Hospital	Puranapool OH	11KV	IX	05.40	07.15	01.35	EL,OL	Star wire fallen on lines at Kurma Sangam	-
4		Malakpet	Farath Nagar	11KV	VIII	11.18	12.59	01.41	All Indication	Cable fault	Arranged B/F on 11KV Bibika Alwa feeder
1	HYD C	Golconda	Mothi Mahal	11KV	VII	02.10	04.00	01.50	EL,OL-Bph	No Visible Fault (Due to Rain)	-
2		Industrial Area	Mother Dairy	11KV	II	04.50	06.05	01.15	EL,OL-Bph	No Visible Fault (Due to Rain)	Arranged partial loads on 11KV L.N Nagar fdr
3		Toli Chowki	Hakeemsha	11KV	VII	04.52	07.15	02.23	EL,OL-Yph	No Visible Fault (Due to Rain)	-
4		Vittalwadi	Gandhi Kuteer	11KV	II	22.05	23.10	01.05	EL,OL-Bph	No Visible Fault	-