

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 2 | | 2 | | 2 | | | |
| 7 | RR(E) | 168 | 403 | | 1 | | 1 | | 1 | | | |
| 8 | Hyd | 194 | 1044 | | 1 | | 1 | | 1 | | | |
| | Total | 606 | 3055 | 0 | 4 | 0 | 4 | 0 | 4 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | 1 | | 1 | | 1 | | | |
| 2 | NLG | 144 | 988 | | 1 | | 1 | | 1 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | 5 | | 5 | | 5 | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 0 | 7 | 0 | 7 | 0 | 7 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 0 | 11 | 0 | 11 | 0 | 11 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 13.01.2021

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | MBNR | Marikal | Malkapur | 11KV | Jadcherla | 09.50 | 14.50 | 05.00 | | 11Kv Jumper Cut Near Malkapur (Vi). | - |
| 1 | NLG | Ambala | Parupally | 11KV | Bhongir | 05.45 | 11.05 | 05.20 | EL | 100 kva DTR failed | - |
| 1 | SDP | Laxmidevipally | Laxmidevipally | 11KV | Siddipet | 15.10 | 18.40 | 03.30 | | Insulater failure | - |
| 2 | | Kodakandla SS | Kodakandla | 11KV | Gajwel | 09.12 | 12.10 | 02.58 | | 11 KV line Cutting | - |
| 3 | | Gowraram SS | Pathur | 11KV | Gajwel | 13.00 | 16.00 | 03.00 | | Tree Branch Fallen | - |
| 4 | | Mulugu SS | Bailampur feeder | 11KV | Gajwel | 12.30 | 18.30 | 06.00 | | CT Calmp Burning | - |
| 5 | | Mulugu SS | Mulugu AGL | 11KV | Gajwel | 16.30 | 17.30 | 01.00 | | Jumper cut | - |
| 1 | RR N | Prashanth Hills | Mithula Nagar | 11KV | Jeedimetla | 09.35 | 14.15 | 04.40 | EL/OL | AB Cable Endkit failed & Replecment at Beside Sub-Staion | - |
| 2 | | Subhash Nagar | Jairam Nagar | 11KV | Medchal | 09.55 | 11.50 | 01.55 | EL | 100KVA DTR Failed and 11KV Conductor snapped and replaced at Rukmini Estate | - |
| 1 | RR E | Mallapur-2 | Ashok Nagar | 11KV | Habsiguda | 10.15 | 11.25 | 01.10 | | 11KV line cut at Tent House T/F | - |
| 1 | HYD N | Zamistanpur | Sanjeevapuram | 11KV | V | 13.48 | 14.52 | 01.04 | All Indication | Faulty DTR Distribution Box at Sunnambatti | - |