

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988	1		1		1				
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	5	2	5	2	5	0	0	
	Grand Total	1082	6468	2	7	2	7	2	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.01.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ganganpally	Nandine	33KV	Gadwal	18.25	23.42	05.17	EL	Jumper cut at Railway gate	Nandine	Alternate Supply Arranged from 33KV Venkatapur feeder at 23:42Hrs
1	NLG	Haliya	Peddavoorra	33KV	Miryalaguda	9:15	11:15	2:00	E/L,O/L	Stay wire toucing the 33KV line at Peddavoorra (V)	Peddavoorra	No

TSSPDCL - LMRC / Corporate office

Date: 18.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kondapur	Hanmanpally	11KV	Narayanapet	12.18	14.15	01.57		Squirrel fallen on the line, Insulator failed	No
1	SDPT	Ganeshpally	Angadikistapur	11KV	Gajwel	8:00	8:30	0:30		Bird fallen on the LT line	No
2		Kokkonda	Singannaguda	11KV	Gajwel	15.30	16.00	0:30		11KV Line cut	No
3		Advimajeed Pally	Kotyal	11KV	Gajwel	03.25	09.25	06.00		11KV Line cut	No
4		Kokkonda	Singannaguda	11KV	Gajwel	11.00	12.00	01.00		Bird burned in the insulator	No
1	RR N	Subhash Nagar	Saibaba Nagar	11KV	Medchal	9:40	10:25	0:45		No visible fault	No
2		Kandlakoya	KV Reddy Nagar	11KV	Medchal	18.35	19.36	01.01		Tree fallen on the 11KV Line at TATA Project	No