

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	4	3	4	3	4			
2	NLG	144	988		2		2		2			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>11</b>	<b>4</b>	<b>11</b>	<b>4</b>	<b>11</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 21.01.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparth	Narsaipally	33KV	Wanaparth	07.10	09.40	02.30	E/L	Jumper Cut near 220KV Wanaparth	Narsaipally	-
2		Wanaparth	Buddaram	33KV	Wanaparth	07.08	08.14	01.06	E/L	Jumper Cut near 220KV Wanaparth	Buddaram	-
3		Gadwal	leeza	33KV	Venkatapuram	14.01	15.22	01.21	O/L	Tree Fallen on the 33KV Line at Uppal Road	leeza	-
1	MDK	Zaheerabad	Old Allana	33KV	Zaheerabad	12.40	15.35	02.55		BD due to Jumper cut	Old Allana	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 21.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mohammadabad	Mohammadabad	11KV	Narayanapet	06.42	08.25	01.43		11KV insulator failed at Annapuranna Rice Mill	-
2		Mohammadabad	Venkatreddypally	11KV	Narayanapet	11.03	11.40	00.37		Due to AB Switch Post of insulator failed at sangaipally village	-
3		Krishna	CHEGUNTA	11KV	Narayanapet	08.00	13.00	05.00		Due to 11KV conductor cut at chegunta village	-
4		Mogalmadka	Mogalmadka Rural	11KV	Narayanapet	07.30	09.45	02.15		DUE TO HT/ LT( MOGULA CHERUVU, MOGALMADKA RURAL	-
1	NLG	Ravulapally	Ravulapally	11KV	Suryapet	12.40	13.40	01.00	E/L	Conductor Snapped	-
2		Vemulakonda	Vemulakonda	11KV	Choutuppal	07.50	09.45	01.55	EL/OL	11 kv Line snapped near Vemulakonda village	-
1	SDP	Kondamrajapally	Katha	11KV	Siddipet	10.56	15.06	04.10		B/D Dtr Lux Problem Lc No 3025	-
2		THIGUL	THIGUL AGL	11KV	Gajwel	08.21	08.57	00.36		CONDUCTUR SNNAPED	-
1	RR N	Laxmapur	Narayanpur	11KV	Medchal	14.45	15.15	00.30		11KV Jumper Cut and replaced at Narayanpur Village	-
1	RR E	Keesara	Cheryala	11KV	Keesara	15.16	15.53	00.37		Tree fallen on 11kv line at Cheryala village	-
1	HYD N	Chilalguda	Dandu Pentaiah	11KV	V	18.05	19.26	01.21	EL,OL-Rph	3Way RMU Cable fault near Gandhi Hospital	Arranged B/F on 11KV MCH Park feeder (2No. DTR's Kept Off)