

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 25.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nandanam	Nagiridaypally	11KV	Bhongir	12.10	14.25	02.15	EL	11kv Insulator Failed	-
1	SDP	Medipally	Ibrahimnagar	11KV	Siddipet	11.00	19.00	08.00		B/D-insulators failed-Now rectified	-
2		Mettu SS	Bandaruapally	11KV	Gajwel	08.50	11.00	02.10		11 KV Disk Fail	-
1	RR N	Thumkunta	Thumkunta	11KV	Medchal	07.05	09.21	02.16		Tree Branch fallen on the 11KV Line at Bhupathi Reddy House, Thumkunta	-
2		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	14.00	15.15	01.15		11KV Cable Jointed at Baisaki Dhabha	-
1	HYD N	Seethaphalmandi	Srinivas Nagar Colony	11KV	V	02.15	04.35	02.20	EL,OL-Rph	Cable fault	Arranged B/F on 11KV S.P College fdr