

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	7	1	7	1	7	0	0	
	Grand Total	1082	6468	1	10	1	10	1	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.01.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	HABSIPUR	Peddachikkodu	33KV	SIDDIPET	12.40	13.40	01.00		TRIIPED On E/L & O/L BREAKDOWN		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.01.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	GOTUR	PUSALPHAD	11KV	Narayanapet	12.00	12.20	00.20		BREAKDOWN DUE TO 11KV JUMPER CUT FALLEN ON CROSS ARM , PUSALPAD VG	-
2		KANUKURTHY	KANUKURTHY	11KV	Narayanapet	09.15	09.58	00.43		BREAKDOWN DUE TO TREE BRANCHES FALLEN ON 11KV LINE, KANKURTHY VG	-
1	NLG	Penpahad	Macharam	11KV	Suryapet	12.22	14.55	02.33	E/L	Insulator failed	-
2		Nakkalapally	Shapally	11KV	Nalgonda	11.40	12.50	01.10	E/L	Jumper cut	-
3		Narayanapur	Melacheruvu	11KV	Choutuppal	00.00	08.10	08.10	EL/OL	100 kva DTR failed at SS-21 Chekka.Narsimha well near Melacheruvu village.	-
1	SDP	PAMULAPARTHY	VASUDHA EXPRESS FEEDER	11KV	Gajwel	13.30	15.30	02.00		11KV LINE CUT	-
2		VANTIMAMIDI	CHINNATHIMMAPUR FEEDER	11KV	Gajwel	11.00	12.45	01.45		11KV LINE CUT	-
1	RR N	Thurkapally	Yadaram	11KV	Medchal	16.20	17.00	00.40		No Fault	-
1	RR E	Balaji Nagar	Mahankali	11KV	Keesara	12.53	13.33	00.40		Tree Branches fallen on 11KV line at TVS Showroom Backside	-
1	HYD N	Vasanthapuri	Sheshapahad	11KV	V	12.15	13.20	01.05	EL	Pin Insulator flash over at Bondalgadda	-