

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044	2	2	2	2	2	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		8		8		8			
3	MDK	107	933									
4	SDPT			1	7	1	7	1	7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>26</b>	<b>4</b>	<b>26</b>	<b>4</b>	<b>26</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 01.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Pebbair	33KV	Wanaparthi	05.55	10.13	04.18	E/L	Pin Baining Failed & Replacement near at Srinavaspur SS	Pebbair	No
1	SDPT	Siddipet	Thornal	33KV	Siddipet	16:30	18:50	2:20		B/D Line Touch	Thornal	No
1	HYD S	220kV Shivrampally	Chandhulal baradari	33KV	Falaknuma	05.44	05.50	00.06		Tripped on EL OL Due to Cable damaged by HMWSSB dept at Bahadurpua X Road.	Chandhulal baradari	220kV Shivrampally-33kV chandhulal baradari OH
1	HYD C	132KV Asifnagar	Kulsumpura	33KV	Asifnagar	01.43	01.47	00.04		Tripped on EL cable fault located at Indian Petrolbunk opp MJ classic furniture Asifnagar X road towards Mehdipatnam road.	Kulsumpura	132kV Imlibun-33kV Goshamahal

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Utkoor	Kollur	11KV	Narayanpet	08.40	10.05	01.25		11KV Line cut at Utkoor checkpost	No
1	NLG	Marriguda	Marriguda Town	11KV	Devarkonda	14:15	15:25	1:10	EL	11 KV Line cut	No
2		Phanigiri	Malipuram	11KV	Suryapet	05.10	09.55	04.45	EL	Conductor snapped	No
3		Thirumalagiri	Old Indl. Feeder	11KV	Suryapet	03.40	08.10	04.30	EL	Poles damaged and Conductor snapped	No
4		Ravulapally	Manapuram	11KV	Suryapet	04.30	07.50	03.20	EL	Conductor snapped	No
5		Nuthankal	Chilpakuntla	11KV	Suryapet	02.10	05.50	03.40	EL	Poles damaged and Conductor snapped	No
6		Akupamula	Akupamula	11KV	Huzurnagar	06.00	07.40	01.40	EL	11 KV LINE SNAPPED	No
7		Chamapur	Chamapur	11KV	Bhongir	08.30	09.10	00.40	EL	11kv Insulator Failed near Chamapur Village	No
8		Gundala	Gangapur	11KV	Bhongir	5:30	9:00	3:30	EL	11kv Disc Failed near SS-6	No
1	SDPT	Mustabad X road	Gadicherlapally	11KV	Siddipet	2:00	6:00	4:00		B/D INSULATOR FAILED	No
2		Kammarlapally	Kothapally	11KV	Siddipet	01.30	08.00	06.30		B/D LC 11kv Pole Damage Lc No 8420	No
3		Ramakkapet	Lachapet	11KV	Siddipet	17.20	18.30	01.10		B/D Tree Fall Down	No
4		KARKAPATLA	KARKAPATLA	11KV	Gajwel	15.15	17.30	02.15		INSULATOR FAILED	No
5		Gagillapur	Vallampatla	11KV	Husnabad	13.03	14.25	01.22		Bird fell on line	No
6		Arjunpatla Town	Arjunpatla Town	11KV	Husnabad	17.20	18.47	01.27		disc failed	No
7		Dhoolmitta	Lingapur	11KV	Husnabad	17:00	18:00	1:00		Tree branch fell on line	No
1	RR N	Laxmapur	Narayanpur	11KV	Medchal	9:50	10:45	0:55		11KV Line AB Switch Opened at Buddi Laxmaiah Bhavi	No
2		GP Pally	Maisammaguda	11KV	Medchal	10.15	10.50	00.35		11KV Line Cut & Replaced at Maisammaguda	No
3		Kandalkoya	Anajanna Temple	11KV	Medchal	18.30	19.05	00.35		Line AB Switch opened at Saigeetha Asramam backside, Bird fallen on 11KV Line	No
1	RR E	Yapral	Pedso	11KV	Sainikpuri	21:12	22:45	1:33		11KV Disc failed at Swarnandra Phase-I	No
2		Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	21.00	22.54	01.54		11KV Disc failed at Hedward Hospital	No
3		Chakripuram	SV Nagar	11KV	Keesara	21.50	00.20	02.30		11KV Insulator Failed at R.NO-5 SV Nagar	No
4		Chakripuram	Shilpa Nagar	11KV	Keesara	21.40	00.00	02.20		11KV Insulator Failed at Annamya Colony	No
5		N.N Colony	Bhavana Rushi	11KV	Keesara	21:40	0:15	2:35		11KV 2 Nos of Pin Insulator Failed at Sidharth Colony	No
1	HYD N	Macha Bollaram	Ayyappa Nagar	11KV	C-VI	20.40	23.30	02.50	A/R tripped	No Visible Fault (Due to Rain)	No
1	HYD C	Mothi Mahal	Risala Bazar	11KV	VII	20.55	22.20	01.25	EL,OL-Yph	Pin Insulator flash over at Risala Bazar PS	No