

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	3	1	3	1	3	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 03.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Palamakula	Narmetta	33KV	Siddipet	07.45	09.30	01.45		B/D deu to bird		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Munagala	Turkagudem-2	11KV	Huzurnagar	07.40	09.40	02.00	EL	11 KV jumper cut	-
2		Eduloor	G.B.Gudem	11KV	Nalgonda	05.30	08.10	02.40	EL	11 KV Line Jumper Cut	-
1	SDPT	Kokkonda SS	Singannaguda	11KV	Gajwel	10.05	10.50	00.45		Insulator Fail	-
1	RR N	UMCC	Mahadevpuram	11KV	Medchal	01.40	02.20	00.40	BD	11KV Line AB Switch Opened at Mahadevpuram(AB Switch Sparked)	-
2		Shameerpet	Leo Meridian	11KV	Medchal	02.00	10.30	08.30	BD	Idle Charged(33KV Cable End Kit failed at Upparapally	-
3		Athiwelly	PHI	11KV	Medchal	08.45	10.45	02.00	BD	11KV Disc failed at PHI Company	-
1	HYD N	Gunrock	Anjaiah Nagar	11KV	Bowenpally	03.00	04.04	01.04	EL,OL	Cable fault at Market Yard	Arranged B/F on 11KV Park View Enclav fdr