

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	8	0	8	0	8	0	0	
	Grand Total	1082	6468	0	10	0	10	0	10	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 04.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 04.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kandoor	Choudaipally	11KV	Jadcherla	13.20	14.20	01.00		HT/LT Near old Vaddepally(V)	-
1	NLG	Golankonda	Golankonda	11KV	Bhongir	10.20	12.50	02.30	E/L	11kv Line snapped at D.Srinu well near Golankonda (V)	-
2		Sangem	Dhubbala	11KV	Choutuppal	10.47	14.45	03.58	E/L	11KV Post off insulator failed at kondem well near Dhubbala (V)	-
3		Kattangur	Bollepally	11KV	Nalgonda	09.10	12.10	03.00	E/L	11KV wire cut at near ambativagu	-
4		Eduloor	Munukuntla	11KV	Nalgonda	02.00	07.10	05.10	E/L	Thatikomma fallen on 11KV line	-
1	SDPT	Guruvannapeta	Posanpally	11KV	Husnabad	11.50	13.35	01.45		BD, Line Cut	-
2		Guruvannapeta	Posanpally	11KV	Husnabad	14.10	18.00	03.50		BD, Line Cut	-
3		Gouravelly	Gudatipally	11KV	Husnabad	09.15	13.20	04.05		BD, Tree fallen on the line	-
1	RR N	Shameerpet	33KV Leo Meridian	11KV	Medchal	17.20	18.30	01.10	BD	No fault	-
2		Sampanbole	LGM Pet AGL	11KV	Medchal	07.30	10.50	03.20	BD	Bird fallen on the 11KV Line at LGM Pet Village	-