

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	1	3	1	3	1			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	10	5	10	5	10	0	0	
	Grand Total	1082	6468	6	14	6	14	6	14	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 05.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Rajapur	33KV	Jadcherla	20.28	21.08	00.40	EL	Isolator open at Rangareddy gutta	Rajapur	Alternate Supply Arranged From G R Cable feeder at 21:08Hrs.
2		Maddur	Vepoor	33KV	Narayanpet	19.05	20.30	01.25	EL	Jumper Opening at Renivatla Road	Vepoor	Alternate Supply Arranged From 33KV Hanwada feeder at 20:30Hrs.
3		Wanaparthy	Revally	33KV	Wanaparthy	15.00	15.10	00.10	E/L&O/L	Cable Burnt at 220KV SS Wanaparthy	Revally	Alternate Supply Arranged From Peddakothapally at 15:10Hrs.
1	MDK	Pashamailaram	APL IV	33KV	Sangareddy	13.07	15.20	02.13		B/D Due to Conductor Snapped	APL IV	-
1	SDP	Thukkapur	Dommata	33KV	Gajwel	11.20	13.10	01.50		Lighting Errested Blasted	Dommata	-
1	RR N	Malkaram	Ratnalayam	33KV	Medchal	13.40	15.55	02.15		No visible fault	Ratnalayam	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 05.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Utkoor	Kollur	11KV	Narayanpet	03.30	08.20	04.50		Breakdown due to insulator fail at kollur vlg	-
1	NLG	Narsingbatla	Narsingbatla	11KV	Nalgonda	11.00	15.35	04.35	EL	Line AB switch open	-
2		Thipparthi	Gangannapalem	11KV	Nalgonda	11.40	15.35	03.55	EL	11KV jumper cut	-
3		Angadipeta	P.A.Pally Town	11KV	Devarakonda	07.00	10.00	03.00	EL	11 KV Insulator Failed	-
4		Cheedella	Cheedella	11KV	Suryapet	07.10	11.05	03.55	EL	Jumper cut	-
5		Mandollagudem	Peddakondur	11KV	Choutuppal	07.05	08.06	01.01	EL	11kv Line Snapped near Mandollagudem Village	-
1	MDK	Inole	Peddakanjarla	11KV	Sangareddy	16.37	17.20	00.43		B/D Due to Conductor Snapped	-
1	SDP	Pregnapur SS	Industrial	11KV	Gajwel	14.13	15.25	01.12		Bird Fallen on 11 KV line	-
2		Akunoor	Dommata	11KV	Husnabad	09.45	14.50	05.05		HT/LT Fallen in line	-
3		Komuravelly	Komuravell 24 Hrs	11KV	Husnabad	17.45	21.25	03.40		Jumper open	-
1	RR N	Gowdavelli	Gowdavelli	11KV	Medchal	15.10	16.40	01.30		11KV UG Cable failed	-
2		Borampet	Cocacola	11KV	Jeedimetla	13.35	15.42	02.07		Lizard fallen on line	-
1	HYD S	Moosarambagh	Moosarambagh	11KV	VIII	23.10	00.29	01.19	All Indication	Ready Mix Concrete Vehicle dashed to Pole near SBI Bank	Arranged B/F on 11KV Sripuram Colony feeder
2		Moosarambagh	SBI Colony	11KV	VIII	23.10	00.29	01.19	EL,OL	Ready Mix Concrete Vehicle dashed to Pole near SBI Bank	Arranged B/F on 11KV Sripuram Colony feeder