

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	4	2	4	2	4			
7	RR(E)	168	403		13		13		13			
8	Hyd	194	1044		13		13		13			
	Total	606	3055	2	30	2	30	2	30	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	1	5	1	5	1			
2	NLG	144	988		2		2		2			
3	MDK	107	933	5	5	5	5	5	5			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	10	9	10	9	10	9	0	0	
	Grand Total	1082	6468	12	39	12	39	12	39	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 07.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Ghanapur	33KV	Mahabubnagar	20.19	21.00	00.41	E/L&O/L	Due to Rain		Alternate Supply Given From 33KV Kodur From 220/132KV SS Palkonda at 21:00Hrs.
2		Mahabubnagar	Machanpally	33KV	Mahabubnagar	20.19	21.00	00.41	E/L&O/L	Due to Rain		Alternate Supply Given From 33KV Kodur From 220/132KV SS Palkonda at 21:00Hrs.
3		Midjil	Velugomula	33KV	Jadcherla	21.55	04.30 (08.07.21)	06.35	E/L&O/L	Due to Rain		NO
4		Balanagar	Thommidirekula	33KV	Jadcherla	00.30	01.10	00.40	E/L	33KV Line Snapped		Alternate Supply Arranged From 132KV SS Alwal 33KV Keshampet at 1:10Hrs
5		Balanagar	Navadurga	33KV	Jadcherla	20.51	21.35	00.44	E/L&O/L	Banner Touched to the Line Near Balanagar Town		NO
1	MDK	Sadasivpet	Koheer	33KV	Sangareddy	18.15	20.05	01.50		BD due to Tree fallen on line		-
2		Pashamailaram	APL IV	33KV	Sangareddy	20.57	23.05	02.08		BD due to after petrolling no fault found		-
3		Pashamailaram	MSN	33KV	Sangareddy	20.57	21.15	00.18		BD due to cable kit		132KV pashamailaram at 21.15
4		Narayankhed	Kalher	33KV	Jogipet	17.30	20.30	03.00		BD due to Tree fallen on line		-
5		Borpatla	Chandapur	33KV	Jogipet	22.25	01.15 (08.07.21)	02.50		BD due to after petrolling no fault found		-
1	RR N	132KV Medchal	33KV Devarayamjal	33KV	Medchal	07.50	09.50	02.00	BD	33KV Pin Insulator failed & Replaced at Kandlakoya		-
2		132KV Malkaram	33KV Ratnalayam	33KV	Medchal	11.48	14.15	02.27	BD	No fault		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 07.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maganoor	Wadwat	11KV	Narayanpet	06.30	08.15	01.45		Due to jumper touching to 11kv line at wadwat(V)	-
1	NLG	B.Ramaram	Jalalpur	11KV	Bhongir	23.35	01.10	01.35	EL/OL	16 kva DTR Failed near Peddaparvathapur village	-
2		Pamukunta	Singaram	11KV	Bhongir	09.00	10.20	01.20	EL/OL	11 kv Post off Insulator failed near Singaram village.	-
1	MDK	Sadasivpet	Town III	11KV	Sangareddy	19.05	22.40	03.35		BD due to Conductor snapped	-
2		Isnapur	Patodia	11KV	Sangareddy	19.40	20.55	01.15		BD due to Insulator failed	-
3		EPIP-II	Padmapower	11KV	Sangareddy	20.58	23.15	03.17		Due to tree fallen	-
4		Patancheru Town	MIA-I	11KV	Patancheru	18.55	20.30	01.35		BD due to Insulator failed	-
5		Kistareddypet	Bheeramguda	11KV	Patancheru	20.10	21.30	01.20		BD due to Insulator failed	-
1	SDPT	Nagapuri	Nagapuri	11KV	Husnabad	00.00	07.20	07.20		Due to tree fallen	-
1	RR N	Dulapally	KK Society	11KV	Medchal	20.58	22.10	01.12	BD	11KV Line AB Switch Opened at Vasantha Tools(No fault)	-
2		Jagathgiringutta	Shirdi Hills	11KV	Medchal	20.40	22.35	01.55	BD	11KV Line AB Switch Opened at RGK Block No 23	-
3		Madinaguda	BK enclave	11KV	Kukatpally	15.00	17.30	02.30	EL	11kv 2Nos Pin insulator Failure At Sai Nilayam Maktha	-
4		Somashila	Paparaidu	11KV	Kukatpally	21.35	22.55	01.20	EL	11kv Pin Insulator Failure At Paparaidunagar	-
1	RR E	Moula-Ali	Gayathri Nagar	11KV	Sainikpuri	16.35	18.15	01.40		11Kv Disk failed at Sai Sadan Appartment (Artisan Janaiah)	-
2		VP Nagar	RK Puram	11KV	Sainikpuri	17.00	18.10	01.10		Tree branches fallen on 11Kv line at RK Puram Raithu Bazar (LM Chandra Shekar)	-
3		Janapriya	Vampuguda	11KV	Sainikpuri	16.45	18.20	01.35		11Kv Pin Insulator failed Vampuguda Village (AE/OP)	-
4		Yapral	Pradhampuri	11KV	Sainikpuri	16.40	17.30	00.50		Tree branches fallen on 11Kv line at Maithri Enclave (LM Murali)	-
5		Yapral	Pedso	11KV	Sainikpuri	17.15	18.35	01.20		11Kv line cut at Pedso Phase-I (AE/OP)	-
6		Sainikpuri	Kalyan Garden	11KV	Sainikpuri	16.30	19.12	02.42		Tree fallen on 11Kv line at Kalyan Garden (AE/OP)	-
7		Sainikpuri	Vijaypuri	11KV	Sainikpuri	16.36	18.26	01.50		11Kv Pin Insulator failed Sainikpuri (AE/OP)	-
8		Vayapuri	RKH Colony	11KV	Sainikpuri	22.55	00.24	01.29		Line AB Switch open and Back Feeding given from 11KV Officers colony	-
9		NGRI	Habsiguda	11KV	Habsiguda	09.17	10.48	01.31		11KV UG Cable damaged due to Metro work at St.No.06 Habsiguda	-
10		NGRI	St.No.08	11KV	Habsiguda	14.46	16.11	01.25		11KV Jumper cut at SS Yard Opposite & Coconut tree branches fallen on 11KV line at Survey of India	-
11		Chakripuram	Simhapuri Colony	11KV	Keesara	18.35	20.00	01.25		Tree branches fallen on 11KV Line at Simhapuri Colony	-
12		Chakripuram	Shilpa Nagar	11KV	Keesara	18.35	20.00	01.25		Tree branches fallen on 11KV Line at Annamaiah Colony & Line AB Switch opened	-
13		RGK	Bharatha Rathna	11KV	Keesara	16.40	20.10	03.30		HT/LT line touched to Kasaram at St Andrew School	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	I.I.C.T	Deccan	11KV	V	16.20	18.05	01.45	EL	Tree branches fallen on lines at Andal Mixture shop & Pin Insulator flash over at Med Plus	-
2		Alwal	Bhupathi Rao Nagar	11KV	C-VI	21.13	23.32	02.19	OL	Tree branches fallen on lines at More Super Market	-----
3		Gunrock	Bowenpally	11KV	C-VI	22.30	23.50	01.20	EL	No Visible Fault	-----
4		Kalyan Nagar	Sriram Nagar	11KV	IV	22.40	00.39	01.59	EL,OL-R&Bph	Jumper cut at near SS	Partial loads added on 11KV B.S.Puri feeder
5		Marredpally	Military Hospital	11KV	C-VI	22.25	01.13	02.48	EL	No Visible Fault	Arranged B/F on 11KV Srinagar Colony fdr
1	HYD S	Moosaram Bagh	Moosaram Bagh	11KV	VIII	15.33	16.56	01.23	All Indication	Jumper cut at Suprabath Hotel	Arranged B/F on 11KV Sripuram Colony fdr
2		Jiyaguda	Goshala	11KV	IX	16.21	17.45	01.24	EL,OL	UG Cable fault at Sheela Plastic	-
3		Devibagh	Siddiq Gulshan	11KV	III	21.20	23.04	01.44	EL,OL,	Opened AB Switch at Murali Nagar	4nos DTR kept off
4		Kandikalgate	G.M Chowni	11KV	III	23.57	01.06	01.09	EL	Breaker problem at SS	Arranged B/F on 11KV Raviendra Naik Nagar fdr
5		Malakpet	Malakpet	11KV	VIII	22.55	01.07	02.12	OL-Rph	Cable fault near SS	Arranged B/F on 11KV Shankar Nagar fdr
1	HYD C	Lumbini Park	Lokayuktha	11KV	I	20.54	23.36	02.42	EL	I/C Cable fault at SS	Arranged B/F on 11KV Basherbagh fdr
2		Industrial Area	Mother Dairy	11KV	II	21.15	00.45	03.30	EL,OL	Tree branches fallen on lines at Telugu Baptist Church	(21:32 Hrs) Partial feeder charged OK
3		Fever Hospital	C.C Sharoof Hospital	11KV	II	23.04	01.38	02.34	All Indication	Pin insulator flash over at Kishan Reddy House	(00:30 Hrs) Partial feeder charged OK & remaining loads added on 11KV Fever Hospital feeder