

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	12	0	12	0	12	0	0	
	Grand Total	1082	6468	1	15	1	15	1	15	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 10.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	132KV Medchal	Petbasheerabad	33KV	Medchal	06.59	10.37	03.38	BD	No fault	Petbasheerabad	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Narketpally	Thakallapadu	11KV	Nalgonda	06.10	09.15	03.05	E/L	11 KV Jumper Cut	-
2		Eduloor	Parada	11KV	Nalgonda	09.10	11.45	02.35	E/L	11 KV Jumper Cut	-
3		Palem	Ogodu	11KV	Nalgonda	15.25	16.20	00.55	E/L	11 KV Jumper Cut	-
4		Jalalpuram	Jalalpuram	11KV	Suryapet	02.45	07.40	04.55	E/L	Jumper cut	-
5		Akupamula	Kodandampuram	11KV	Huzurnagar	05.15	07.30	02.15	EL	11 KV LINE SNAPPED	-
6		Munagala	Barakathgudem	11KV	Huzurnagar	06.00	07.40	01.40	EL	11 KV JUMPER CUT	-
7		Repala	Repala	11KV	Huzurnagar	04.00	06.20	02.20	EL	11 KV LINE SNAPPED	-
8		Suddala	Theriyala	11KV	Bhongir	01.10	12.10	11.00	EL	11 kv Disc failed at Aadi sailu well near Anantharam village.	-
1	SDPT	Katkur	Mothkulapally	11KV	Husnabad	07.00	10.30	03.30		Insulator failure, same rectified	-
2		Dharmaram	Nandaram	11KV	Husnabad	18.40	20.26	01.46		Line cut, same rectified	-
3		Nagapuri	Dudekulapally	11KV	Husnabad	09.50	12.40	02.50		Insulator failure, same rectified	-
4		Maddur	Maddur Agl	11KV	Husnabad	07.30	08.20	00.50		Insulator failure, same rectified	-
1	RR N	Laxmapur	Narayanpur	11KV	Medchal	09.00	09.45	00.45	BD	11KV Jumper Cut & Replaced at Cheruvu, Narayanpur	
2		Uddamarry	Sneha Farm	11KV	Medchal	00.30	07.00	06.30	BD	11KV Conductor snapped and replaced at near by SS	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Gymkhana	Vasavi Nagar	11KV	C-VI	01.50	06.50	05.00	EL	Cable fault at Gayatri Apts	At 03:20 Hrs partial arranged B/F on 11KV Jyothi Colony feeder