

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	6	1	6	1	6			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		7		7		7			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>17</b>	<b>1</b>	<b>17</b>	<b>1</b>	<b>17</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1	15	1	15	1	15			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>34</b>	<b>3</b>	<b>34</b>	<b>3</b>	<b>34</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 13.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Mission Bhagiratha	33KV	Jadcherla	11.45	12.10	00.25	E/L&O/L	Jumper Cut at Gollapally	Mission Bhagiratha	Alternate Supply Arranged form 132KV SS MBNR to 33KV SS Jadcherla 12:10Hrs
1	SDPT	Thunikibollaram	Vantimamidi	33KV	Gajwel	0:00	9:15	9:15		LT Line cut	Vantimamidi	No
1	RR N	132KV Malkaram	33KV Ratnalayam	33KV	Medchal	1:40	2:20	0:40		33KV Cable End Kit failed in Shameerpet SS		Backfeeding arranged from 33KV LGM Pet feeder from 132KV LGM Pet SS

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nakrekal	Nomula	11KV	Nalgonda	7:00	8:15	1:15		11KV Insulator failed	No
2		Kethapally	Kasanagodu	11KV	Nalgonda	08.30	09.30	01.00		11KV Jumper cut	No
1	SDPT	DOMMATA	SURAMPALLY	11KV	Gajwel	16:20	17:15	0:55		11KV DISC FAILED	No
2		DUDEEDA	SELAMPU	11KV	Gajwel	8:00	8:30	0:30		11KV WIRE CUT	No
3		MULUGU	MULUGU AGL	11KV	Gajwel	7:00	11:00	4:00		11KV INSULATOR FAILED	No
4		MULUGU	BAIALMPUR	11KV	Gajwel	7:00	13:30	6:30		11KV SIDE/ SIDE LINE TOUCH	No
5		ERRAVALLY	MARKOOK POLICE STATION	11KV	Gajwel	0:20	7:40	7:20		11KV DISC FAILED	No
6		KARKAPATLA	KARKAPATLA	11KV	Gajwel	22:50	8:10	9:20		11KV DISC FAILED	No
7		JAGADEVPUR	JAGADEVPUR TOWN	11KV	Gajwel	0:20	1:40	1:20		THE TREE FEEL ON THE LINE	No
8		GOWRARAM	TOWN-1	11KV	Gajwel	22:05	6:00	7:55		AB SWITCH OPEN	No
9		GOWRARAM	MAILARAM	11KV	Gajwel	23:10	8:50	9:00		POSTOFFICE INSULATOR FAILED	No
10		GOWRARAM	SHUTDOWN	11KV	Gajwel	13:00	14:00	1:00		SHUTDOWN	No
11		AKKANAPET	PAKILNAYAK THANDA	11KV	Husnabad	5:20	8:10	2:50		TREE BRANCH FALLEN ON THE LINE	No
12		GANDIPALLY	GANDIPALLY	11KV	Husnabad	1.25	5.50	4.15		DUE TO HEAVY RAIN	No
13		Gurjakunta	Vechareni	11KV	Husnabad	4.50	11.15	6.25		INSULATOR FAILED	No
14		Nagapuri	Gandikunta	11KV	Husnabad	7.05	9.35	2.30		LINE CUT	No
15		Chityal	Thadoor	11KV	Husnabad	15.10	16.35	1.25		INSULATOR FAILED	No
1	RR N	Rajabollaram	Harshad Foultry	11KV	Medchal	5:20	6:26	1:06		CT PT Problem in Soap Factory	No
2		Athiwelly	PHI	11KV	Medchal	09.50	19.18	09.28		11KV Cable failed and replaced in SS	No
3		Aliabad	HBL	11KV	Medchal	11.40	12.50	01.10		11KV Line AB Switch Opened at Aliabad X-Road ( 11KV Disc failed )	No
4		Aliabad	Majeedpur	11KV	Medchal	12.40	13.30	00.50		11KV Pin Insulator Failed & replacement at Sangeeth Function Hall Backside	No
5		Kandlakoya	Kandlakoya	11KV	Medchal	17.40	18.25	00.45		11KV Pin Insulator failed at Sutaruguda Road	No
6		Prashanthi Hills	Prashanthi Hills	11KV	Kukatpally	11:26	12:30	1:04		11kv Disc Failure At Seven Hills Apt	No
1	RR E	Saketh	Saketh	11KV	Sainikpuri	1:10	3:02	1:52		11KV Polimer Insuletor fail at Saibaba Nagar	No
2		Kushaiguda	Kapra	11KV	Sainikpuri	11.15	14.00	02.45		11KV Cable failed at Myblo Home Apport.	Back feeding Kapra feeder load add to Yella Reddyguda feeder
3		Street no8	Green hills	11KV	Habsiguda	16.26	17.50	01.24		Tree fallen on 11kv line at Delhi sweet house	No
4		Chengicherla	Chengicherla	11KV	Keesara	00.25	01.45	01.20		11KV line cut at MLR colony	No
1	HYD N	I.D.P.L	SIFCO	11KV	VI	16.10	17.45	01.35	OL-Bph	Tree branches fallen on lines & Disc Insulator flash over at Plot No.B-87 & TATA Company	No
2		Alwal	Chandrapuram	11KV	C-VI	21:22	22:45	1:23	EL,OL	Pin Insulator flash over & Brass Patti cut at Mangapuram Colony	No
1	HYD C	Industrial Area	R.O.M	11KV	II	16.40	18.10	01.30	EL,OL	Tree branches fallen on lines & Disc Insulator flash over at Nava Telangana	No
2		Bathkammakunta	Shivam	11KV	II	18.57	20.06	01.09	EL	Tree branches fallen on lines at Vishal Super Market	No
3		Bathkammakunta	Ayyappa Temple	11KV	II	20.40	22.18	01.38	EL	Disc Insulator flash over at Sri Sai Apts	No
4		Golconda	Darga Cable	11KV	VII	21:55	1:10	3:15	EL,OL-Rph	Disc Insulator flash over at D-Mart	No
5		Asif Nagar	Padmanabha Nagar	11KV	VII	22.05	23.40	01.35	EL,OL-Rph	Pin Insulator flash over & Brass Patti cut at Mega Susheel Apts	No