

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	3	7	3	7	3	7			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		17		17		17			
	Total	606	3055	3	25	3	25	3	25	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988		10		10		10			
3	MDK	107	933		2		2		2			
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	20	2	20	2	20	0	0	
	Grand Total	1082	6468	5	45	5	45	5	45	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 18.07.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Mogalmadka	33KV	Narayanpet	19.35	20.00	00.25	EL	Due to Rain	Mogalmadka	-
2		Ghanapur	Lattupally	33KV	Wanaparthi	05.55	07.42	01.47	E/L	2 No Insulator Failed	Lattupally	-
1	RR N	132KV Malkaram	33KV Ratnalayam	33KV	Medchal	08.10	11.10	03.00		No fault	33KV Ratnalayam	Backfeeding arranged from 33KV LGM Pet Feeder
2		132KV Medchal	33KV Medchal-I	33KV	Medchal	17.00	19.24	02.24		Y Phase Jumper cut and replaced at Four pole structure	33KV Medchal-I	-
3		132KV Medchal	33KV Aliabad	33KV	Medchal	16.54	20.10	03.16		Y Phase Jumper cut in SS	33KV Aliabad	Backfeeding arranged from 33KV Aliabad (132KV LGM Pet)

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.07.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kodgal	Goplapur	11KV	Jadcherla	05.20	10.15	04.55		11 KV Insulator Failed near kodgal vaagu.	-
2		Kothamolgara	Elkicherla	11KV	Jadcherla	04.40	11.00	06.20		11 KV Jumer Cut near Battupally.	-
1	NLG	D.Nagaram	D.Kothapally	11KV	Suryapet	08.40	12.45	04.05	E/L	11Kv Insulator failed	-
2		Kudakuda	lylapuram	11KV	Suryapet	04.30	09.00	04.30	E/L	11Kv Disk failed	-
3		Kondamadugu	Kepal Indl	11KV	Bhongir	13.30	14.15	00.45	E/L	11kv Disc failed at Saibaba temple near Kondamadugu (V)	
4		Paladugu	Panakabanda	11KV	Bhongir	04.10	07.35	03.25	E/L	11kv Disc Failed near Srinivas Well Musipatla (V)	
5		Nakrekal	Bheemavaram	11KV	Nalgonda	04.45	05.40	00.55	E/L	Tree Branches Fallen on the 11Kv Line	
6		Jununthala	Pallepahad	11KV	Devarakonda	04.15	08.20	04.05	E/L	11Kv Insulator failed	
7		Marriguda	Y.G.Pally	11KV	Devarakonda	05.04	09.00	03.56	E/L	11Kv Insulator failed	-
8		Marriguda	Kondur	11KV	Devarakonda	05.30	07.20	01.50	E/L	11Kv Jumper	-
9		Maillabai	Devathpally	11KV	Devarakonda	05.07	08.15	03.08	E/L	11Kv Jumper	-
10		Pochampally	Chinna Mandapuram	11KV	Devarakonda	04.30	08.10	03.40	E/L	11Kv Jumper	-
1	MDK	Sangareddy Rural	Balaji	11KV	Sangareddy	16.36	18.05	01.29		BD due to Disk Failure	-
2		Bollaram-II	Vipla	11KV	Patancheru	19.17	20.20	01.03		BD due to Tree branches fallen on the line	-
1	SDPT	Indoor	Town PS	11KV	Siddipet	16.13	17.42	01.29		OL&EL (B/D11 KV wire burning)	
2		Akkannapet	Akkannapet Rural	11KV	Husnabad	13.10	16.00	02.50		Insulator failure, same rectified	
3		Guruvannapet	Guruvannapet	11KV	Husnabad	14.50	18.40	03.50		Tree fallen on line, same rectified	
4		Nacharam SS	Anthagiripally	11KV	Gajwel	12.35	17.20	05.15		Jumper Cut	
5		Cheelasagar SS	Chelasagar AGL	11KV	Gajwel	09.30	13.15	03.45		HT/LT line Cut	
6		Cheelasagar SS	Anna Sagar	11KV	Gajwel	17.20	18.00	00.40		11KV line fallen by tree brances	
1	RR N	Subash Nagar	Jairam Nagar	11KV	Medchal	02.08	03.56	01.48	BD	11KV Line AB Switch Opened at Sarojini Hospital(No fault)	-
2		Subash Nagar	Ramraj Nagar	11KV	Medchal	16.51	17.59	01.08	BD	Tree Fallen on 11KV Line at Alwal Road	-
3		Subash Nagar	Jeedimetla	11KV	Medchal	17.03	18.10	01.07	BD	Tree Fallen on 11KV Line at Pista House,Jeedimetla	-
4		Shemshiguda	Last bus stop	11KV	Kukatpally	17.20	18.40	01.20	EL/OL	11kv AB Cable end kit failure near road no 1 at Venkatapapaiah nagar	-
5		Shemshiguda	NTR Nagar	11KV	Kukatpally	17.21	18.45	01.24	OL	Tree branch fallen on the 11kv line at Main road	-
6		Gowdavelly	IDA Gowdavelly	11KV	Medchal	17.00	17.58	00.58	BD	LT Pole damaged by Car at Gaynapur	-
7		Bachupally	Maa villas	11KV	Kukatpally	17.05	18.05	01.00	EL/OL	Out going 11KV Cable falt at Maa villas	-
1	RR E	Aushapur	Aushapur	11KV	Keesara	13.40	14.20	00.40		11KV line cut & Insulator fail at Anurag collage	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Road No.13	Road No.1	11KV	X	16.35	18.11	01.36	EL	Faulty Cable at Virinchi Hospital	-----
2		Jana Priya	Shastry Nagar	11KV	IV	16.42	17.56	01.14	EL,OL	Tree branches fallen on lines at P.R.Nagar	-----
3		N.I.M.S.	Nagarjuna Hills	11KV	X	16.40	18.30	01.50	EL,OL	Cable fault	Arranged B/F on 11KV Venkateshwara Hills fdr
4		Pragatools	Asbestos Hills	11KV	VI	16.35	18.00	01.25	OL-Rph	Tree branches fallen on lines at Asbestos Hills	-----
5		Pragatools	Giri Nagar	11KV	VI	16.46	18.05	01.19	OL-Rph	Tree branches fallen on lines at A.P.Housing Board	-----
6		Pragatools	Nagarjuna Signode	11KV	VI	16.46	18.40	01.54	EL,OL-Rph	Jumper cut & touching to Cross Arm at Gandhi Nagar	-----
7		Pragatools	Pragathi Packs	11KV	VI	16.52	18.55	02.03	OL-Rph	Tree branches fallen on lines at IDA, Gandhi Nagar	-----
8		Chilkaiguda	New Boiguda	11KV	V	16.20	19.35	03.15	EL	Pin Insulator flash over at New Boiguda	Arranged B/F on 11KV Dharna Kanta fdr & 11KV C.C.Nagar fdr
9		Pragatools	R.R.Nagar	11KV	VI	16.43	19.59	03.16	OL-Rph	HT Line snapped at Pancha Sheela Colony	-----
1	HYD S	Falaknuma	Ravindra Naik Nagar	11KV	III	16.05	17.55	01.50	EL	No Visible Fault (Due to Rain)	
2		Kandikal Gate	Saibaba Nagar	11KV	III	16.29	19.35	03.06	EL	Cable fault at Krishna Reddy Colony	
1	HYD C	Industrial Area	R.O.M	11KV	II	07.30	08.53	01.23	EL	Cable fault	Arranged B/F on 11KV Narayanaguda feeder
2		S.D.Hospital	Police Mess	11KV	VII	16.22	17.42	01.20	EL	Tree branches fallen on lines at Anand Residency	-----
3		Hussain Sagar	Adarsh Nagar	11KV	I	16.15	18.00	01.45	EL,OL	Disc Insulator flash over at Adarsh Nagar Park	-----
4		Hussain Sagar	Maruthi Nagar	11KV	I	16.20	18.20	02.00	EL,OL	Tree branches fallen on lines at Khairthabad Flyover	-----
5		Hussain Sagar	L.I.C.	11KV	I	16.17	19.10	02.53	EL,OL	Sectionalizer fault Opp. Secretariat	Arranged B/F on 11KV A.I.R.feeder
6		Asif Nagar	Mehdipatnam OH	11KV	I	17.38	19.16	01.38	EL	Faulty 4Nos. DTRs at Mahdipatnam	Arranged B/F on 11KV Amba Garden feeder