

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	3	20	3	20	3	20			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		21		21		21			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>46</b>	<b>3</b>	<b>46</b>	<b>3</b>	<b>46</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	6	2	6	2	6			
2	NLG	144	988		10		10		10			
3	MDK	107	933									
4	SDPT			1	14	1	14	1	14			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>30</b>	<b>3</b>	<b>30</b>	<b>3</b>	<b>30</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>6</b>	<b>76</b>	<b>6</b>	<b>76</b>	<b>6</b>	<b>76</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 02.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	APL Health Care	33KV	Jadcherla	02.50	09.50	07.00	E/L&O/L	Insulator Failed Near Polepally SEZ	APL Health Care	-
2		Midjil	Velugomula	33KV	Jadcherla	14.50	18.55	04.05	O/L	Top Insulator Fallen on other Phase Near Ranipet(V)	Velugomula	-
1	SDP	Musthyal	Nagapuri	33KV	Husnabad	00.00	06.30	06.30		Break Down ( Tree Branches fallen on power line )	Nagapuri	-
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	00.02	03.10	03.08		33KV Pin Insulator failed at Kompally Back feeding arranged from 33KV Dulapally feeder from 00:15	33KV Kompally	-
2		132KV Medchal	33KV Kompally	33KV	Medchal	04.00	06.40	02.40		33KV Pin Insulator failed at Kompally	33KV Kompally	-
3		132KV LGM Pet	33KV LGM Pet	33KV	Medchal	02.50	06.40	03.50		33KV Pin Insulator failed at Monsanto Company	33KV LGM Pet	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	Kathwar	11KV	Narayanpet	06.30	08.18	01.48		Breakdown due to removing vibrant trees at golapally vlg	-
2		Gundumal	Amilikunta	11KV	Narayanpet	08.20	11.20	03.00		Breakdown due to 11kv line cut at gundumal vlg	-
3		Vennachedu	Janampally	11KV	Narayanpet	04.50	07.58	03.08		Breakdown due to 11kv pole fallen down at kaplapur vlg	-
4		Salkarpet	Jangareddypally	11KV	Narayanpet	03.15	08.25	05.10		Breakdown due to 11kv disc fail at jangareddypally vlg	-
5		Kanukurthy	Kanukurthy 24 Hrs. Feeder	11KV	Narayanpet	13.58	17.00	03.02		Breakdown due to tree branch fallen on 11kv line at kanukurthy vlg	-
6		Kanukurthy	Lokurthy	11KV	Narayanpet	15.40	19.02	03.22		Breakdown due to unknown, supply restored by opening cut point near pidenpally vlg	-
1	NLG	IDA	Bommaipally	11KV	Bhongir	16.45	17.00	00.15	EL/OL	11kv 6no's Poles Damedged near Bommapally Village	-
2		Golankonda	Golankonda	11KV	Bhongir	04.00	08.45	04.45	EL/OL	11 kv Insulator failed at Veragani.Ramaswamy well near Ammanabole village	-
3		Golankonda	Matoor	11KV	Bhongir	07.30	09.05	01.35	EL/OL	11 kv Disc failed at Venkat reddy well near Peddabavi gudem	-
4		Bondugula	Parupally	11KV	Bhongir	02.40	07.00	04.20	EL/OL	11kv Insulator Failed near Parupally Village	-
5		Chada	Kondapur	11KV	Bhongir	16.45	13.45	21.00	EL/OL	2no's 11kv Pole's Damedged near Kondapur Village	-
6		Pallerla	Kurella	11KV	Bhongir	05.50	09.45	03.55	EL/OL	11 kv Disc faied near Keurella vilage.	-
7		Suddala	Pallepahad	11KV	Bhongir	20.30	15.15	17.45	EL/OL	11kv pole Damedged 4 no's Pallephad Village	-
8		D.Nagaram	D.Nagaram Indl	11KV	Choutuppal	10.40	11.50	01.10	EL/OL	11kv Line Snapped near SV Lab	-
9		Puligilla	Kerchupally	11KV	Choutuppal	06.40	09.00	02.20	EL/OL	11 kv Insulator failed at Ram reddy well near Kerchupally vilage.	-
10		Vemulakonda	Goparajupally	11KV	Choutuppal	08.40	10.30	01.50	EL/OL	11kv Disc Failed near Gopirajpally Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDP	Gurrala Sofa	Ramaram	11KV	Gajwel	00.05	05.20	05.15		11 KV Isulator Failed	-
2		Amdhipur	Dillapur	11KV	Gajwel	07.45	09.09	01.24		Pole Damage	-
3		Mulugu	Mulugu	11KV	Gajwel	02.20	07.20	05.00		11 KV Isulator Failed	-
4		Akkannapeta	Gollakunta	11KV	Husnabad	05.50	10.30	04.40		Line Cut	-
5		Akkannapeta	Akkannapeta Rural	11KV	Husnabad	05.55	09.20	03.25		Insulator Fail	-
6		Akkannapeta	Pakkirnaik Thanda	11KV	Husnabad	05.50	09.10	03.20		Insulator Fail	-
7		Thotapally	Anthakkapet	11KV	Husnabad	12.00	15.00	03.00		Line Problem	-
8		Bejjanki	Regulapally	11KV	Husnabad	15.45	16.20	00.35		Tree Fallen on the line	-
9		GandiPally	GandiPally	11KV	Husnabad	03.40	08.30	04.50		11KV Line short	-
10		GandiPally	Nandaram	11KV	Husnabad	08.05	08.45	00.40		Disc Change	-
11		Nagapuri	Dudekulapally	11KV	Husnabad	11.40	12.10	00.30		Heavy Rain	-
12		Chityala	Dommata	11KV	Husnabad	11.40	12.35	00.55		Copper Metal fallen on the DTR	-
13		Bekkal	Kutigal	11KV	Husnabad	02.00	07.00	05.00		Heavy Rain	-
14		Guruvannapeta	Guruvannapeta	11KV	Husnabad	07.15	15.40	08.25		Insulator Fail & Disc Fail	-
1	RR N	Kompally	NCL	11KV	Medchal	06.02	08.34	02.32		11KV Disc failed and replaced at Modi Builders	-
2		Dulapally	KK Society	11KV	Medchal	08.36	09.32	00.56		11KV Line AB Switch Opened at Sunflow Industry(11KV Disc failed at Noor Industry)	-
3		Jagathgirigutta	Shiridi Hills	11KV	Medchal	04.50	14.15	09.25		Breaker Mechanical problem (Limb Blast)(Load Normalized)	-
4		Kandalkoya	Kandalkoya	11KV	Medchal	06.00	06.55	00.55		Bird fallen on the 11KV Line at Nimmala Garden	-
5		GP Pally	Neighbourhood	11KV	Medchal	04.30	07.50	03.20		11KV Disc failed at Nibeerwood	-
6		Town Medchal	Jyothi Nagar	11KV	Medchal	03.10	05.10	02.00		11KV Jumper opened at Fish Market (11KV Line cut )	-
7		Town Medchal	NGO's Colony	11KV	Medchal	06.20	07.05	00.45		Line AB Switch opened at KLR Venture(11KV Disc failed )	-
8		Medchal	IDA Kandlakoya	11KV	Medchal	06.40	08.05	01.25		11KV Conductor snapped and replaced at Delta rubber company	-
9		132KV LGM Pet	33KV LGM Pet	11KV	Medchal	02.50	06.40	03.50		Line AB Switch opened at Monsanto Company(33KV Pin Insulator failed & Replaced)	-
10		GP Pally	Apparel Park	11KV	Medchal	04.30	10.15	05.45		Tree Branches fallen on the 11KV Line at Apperal Park Road	-
11		GP Pally	GP Pally	11KV	Medchal	04.30	09.25	04.55		11KV Pin Insulator failed at aayodhya Chowrasta	-
12		Kandalkoya	Kandalkoya	11KV	Medchal	00.45	02.00	01.15		11KV Line AB Switch Opened at Gubba Storage(No Fault)	-
13		Gowdavelly	Ayodhya	11KV	Medchal	13.10	13.55	00.45		HT Line Cut & Replaced at Ayodhya	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
14	RR N	Devarayamjal	Kottapet	11KV	Medchal	00.00	15.50	15.50		11KV Disc failed and replaced at Agar Khan Hostel, Yamjal (Alternate supply arranged from 11KV Saigeetha Ashramam feeder at 07:30)	-
15		Prashanth Hills	Srinivasa Colony	11KV	Kukatpally	03.45	08.00	04.15		Due to havy Rain	-
16		Prashanth Hills	Brundhavan Colony	11KV	Kukatpally	03.45	05.40	01.55		Due to havy Rain	-
17		Jeedimetla-I	Virchow	11KV	Jeedimetla	03.30	04.45	01.15		11kv lline AB Cable Failed at Cristal Polymers, Phase-I	-
18		Dppally-II	Cable MLR	11KV	Jeedimetla	05.20	13.30	08.10		11kv pole Dameded at MLR Colony	-
19		Dppally	IDA Gagillapur	11KV	Jeedimetla	04.00	08.00	04.00		11kv line Insulater Flash at Sruthi Furniture, Gagillapur	-
20		Dppally	Bowrampet	11KV	Jeedimetla	00.50	02.05	01.15		11kv line Insulater Flash at Bowrampet village	-
1	RR E	Mallapur-2	Ashok Nagar	11KV	Habsiguda	04.10	06.35	02.25		11KV line snapped at Neheru nagar & Breaker Relay problem in SS & given B/F from Noma feeder	-
2		Uppal	Bank Colony	11KV	Habsiguda	12.10	13.05	00.55		11KV Cable failed at Adithya Apartment Beerappagadda	-
3		Yapral	Pedso	11KV	Sainikpuri	00.20	01.30	01.10		11KV Jumper cut at Kindi Basthi (AE/OP)	-
4		Yapral	Pradamapuri	11KV	Sainikpuri	10.05	11.00	00.55		Polimer Disk fail at Neharbaba Colony (AE/OP)	-
5		Cherlapally-V	Ruchi Oil	11KV	Sainikpuri	04.20	05.39	01.19		Post of Insulator failed at Ven Engg Company and line AB switch company at Ruchi oil (AE/OP)	-
1	HYD N	I.D.P.L	SIFCO	11KV	VI	00.25	02.00	01.35	OL-Bph	Tree branches fallen on lines at Plot No.A26	-
2		E.S.I	IAS Quarters	11KV	IV	02.45	04.10	01.25	EL	HT Jumper cut at Gyaneshwar Residency	-
3		H.M.T	A.O.L	11KV	VI	02.55	05.30	02.35	EL	HT Jumper cut at C.M.R Function Hall & faulty Loads of 11KV Sri Sai Colony fdr	-
4		Seethaphalmandi	Gandhi Statue	11KV	V	03.00	05.45	02.45	EL	Pin Insulator flash over at Gandhi Statue	-
5		I.I.C.T	Solex	11KV	V	03.10	05.45	02.35	EL	Tree branches fallen on lines at Big Bazar	-
6		Lalaguda	Shanthi Nagar	11KV	V	03.12	05.52	02.40	EL	Auto Reclousure fault near Fly Over	-
7		Hakimpet	Risala Bazar	11KV	C-VI	04.25	09.20	04.55	EL,OL-Rph	Faulty DTR at Water Tank	At 06:25Hrs partial fdr charged
8		Mothi Nagar	B.S.Puri	11KV	IV	05.02	07.10	02.08	EL,OL-Bph	Disc & Pin Insulators flash over at Mid Land Bakery	-
9		Chilkaiguda	Dandu Pentaiah	11KV	V	05.38	07.55	02.17	EL,OL-Bph	Cable fault	Arranged B/F on 11KV MCH Park fdr
10		Monda Market	Bata	11KV	V	03.30	08.00	04.30	EL	I/C Cable fault	Arranged B/F on 11KV Hyder Basthi feeder

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
11		Chilkaiguda	R.L.H. Corporation	11KV	V	09.02	10.30	01.28	EL	Faulty CT PT at Rajya Laxmi Housing Corportion	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD C	Bathkammakunta	Shivam	11KV	II	02.36	04.06	01.30	OL-Rph	No Visible Fault (Due to heavy rain & Gale)	-
2		Asif Nagar	Military	11KV	VII	02.50	05.37	02.47	EL	Nawabsab DTR fault at Military Area	-
3		Indira Park	Vivek Nagar	11KV	I	02.56	06.07	03.11	EL	Water login in I/C R.M.U near Andhra Bank	-
4		Indira Park	Goshala	11KV	I	02.58	04.25	01.27	EL	No Visible Fault (Due to heavy rain & Gale)	-
5		Toli Chowki	Ameena Masjid	11KV	VII	03.00	04.05	01.05	EL,OL-Rph	Cloth fallen on lines at Sapthagiri Apts	-
6		A.S.R Raju Nagar	LIC Office	11KV	VII	03.00	04.40	01.40	EL	UG Cable End Kit failed at LIC Office	-
7		Chilkaiguda	Golconda X-Road	11KV	II	03.05	06.21	03.16	EL,OL-Yph	Pin Insulator flash over at Sandarshini Hotel	-
8		Narayanaguda	City Central Library	11KV	I	03.05	04.15	01.10	EL,OL-R&Bph	No Visible Fault (Due to heavy rain & Gale)	-
9		Vittalwadi	Gandhi Kuteer	11KV	II	03.35	05.30	01.55	EL	No Visible Fault (Due to heavy rain & Gale)	-
10		Nizam College	Brand Factory	11KV	I	03.48	04.52	01.04	EL,OL-Rph	No Visible Fault (Due to heavy rain & Gale)	Arranged B/F on 11KV Himayath Nagar fdr