

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	6	2	6	2	6			
7	RR(E)	168	403		9		9		9			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	2	18	2	18	2	18	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			2	15	2	15	2	15			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	23	4	23	4	23	0	0	
	Grand Total	1082	6468	6	41	6	41	6	41	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 04.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramannapet	Veliminedu	33KV	Nalgonda	13.49	16.27	02.38	EL/OL	Moniter Lizard on the 33KV line	Veliminedu	-
1	MDK	Gummadidala	Gummadidala	33KV	Patancheru	15.30	16.35	01.05		BD Due to Tree branch fallen on the line	Gummadidala	-
1	SDPT	Habsipur	Pothareddypet	33KV	Siddipet	16.05	16.55	00.50		No Fault Due to Heavy Rain	Pothareddypet	Chittapur 33kv from 16:55
2		Shanigaram	Koheda	33KV	Husnabad	16.15	20.10	03.45		B/D due to insulator failed	Koheda	-
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	14.45	16.41	01.56	BD	No Fault Due to Heavy Rain	33KV Kompally	-
2		132KV Malkaram	33KV Ratnalayam	33KV	Medchal	10.38	12.25	01.47	BD	No Fault Due to Heavy Rain	33KV Ratnalayam	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 04.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Chennavelly	11KV	Jadcherla	11.00	13.00	02.00		11KV Jumper Cut Near Rayapally(V)	-
2		Maddur	Chintaldinne	11KV	Narayanpet	10.35	11.18	00.43		Squarrel Fallen on 11kv line at Chintaldinne(V)	-
1	NLG	Phanigiri	Anantharam	11KV	Suryapet	03.50	08.15	04.25	E/L	11Kv Conductor snapped	-
2		Keethavarigudem	K K thanda	11KV	Huzurnagar	02.05	07.45	05.40	E/L	11Kv Conductor snapped	-
3		Timmareddy gudem	Timmareddy gudem	11KV	Huzurnagar	06.20	08.00	01.40	E/L	11Kv Conductor snapped	-
4		Pamanagundla	Erasanigudem	11KV	Nalgonda	08.35	11.23	02.48	E/L	Thonda fallen on 1-Ph DTR at near Katta	-
5		Damarcherla	Damarcherla Agl	11KV	Miryalguda	10.38	16.05	05.27	E/L	11Kv Insulater failed	-
1	MDK	G.Machunoor	Industiral	11KV	Jogipet	13.22	19.15	05.53		B/D Due to Conductor Snapped	-
1	SDPT	DR.Pally SS	DR Pally	11KV	Gajwel	13:05	15:05	2:00		11Kv line Cut	-
2		DR.Pally SS	Giripally	11KV	Gajwel	16:25	18:11	2:14		11KV pole damaged	
3		Gajwel Pregnapur SS	Town-I	11KV	Gajwel	14:30	15:20	0:50		OL/EL Tripping	
4		Gajwel Pregnapur SS	Town-I	11KV	Gajwel	15:30	16:15	0:45		Umamaheshavara apartment Cable line Short circuted	
5		Gajwel SS	BV Pur	11KV	Gajwel	7:40	11:04	3:24		11KV disk faile	
6		Jagdevpur SS	Jagdevpur Indu	11KV	Gajwel	15.30	18.30	03.00		11KV insulatar faile	
7		Pregnapur SS	Pregnapur Town	11KV	Gajwel	15.40	17.10	01.30		Insulatar fail	
8		Gowrram SS	Gowrram Town Feeder LC.No.11495	11KV	Gajwel	09.40	11.55	02.15		11Kv line Cut	
9		Gowrram SS	Gowrram Town Feeder LC.No.11496	11KV	Gajwel	15.30	17.20	02.10		Tree has fallen the line	
10		Gowrram SS	Gowrram	11KV	Gajwel	17.45	18.55	01.10		AB Switch open due to hevay rain	
11		Gowrram SS	Mailaram	11KV	Gajwel	17.20	17.50	00.30		AB Switch open due to hevay rain	
12		Cheelasagar SS	Annasagar	11KV	Gajwel	14.40	19.00	04.20		11Kv line Cut	
13		Mulugu SS	Nagireddypally	11KV	Gajwel	09.25	13.06	03.41		11KV insulatar faile	
14		Duddeda SS	Selampur	11KV	Gajwel	21.40	10.00	12.20		11Kv line Cut	-
15		Dommata SS	Gajulapally	11KV	Gajwel	7:10	10:34	3:24		DTR core Insulatar faile	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Kandalkoya	Anjanna Temple	11KV	Medchal	14.43	15.50	01.07	EL	25KVA DTR AB Switch Opened at Shivashivani School (25KVA DTR Failed Shivashivani School)	-
2		Aliabad	Aliabad	11KV	Medchal	14.28	17.40	03.12	EL	11KV Jumper opened at Thadam Basti 11KV Pole damaged	-
3		ICICI	SP-I	11KV	Medchal	14.24	17.34	03.10	EL	RMU -3 Company Internal Cable Problem	-
4		Pudur	Pudur	11KV	Medchal	15.10	17.09	01.59	EL	11KV Pininsulator failed at Pudur	-
5		Shameerpet	Nalsar	11KV	Medchal	15.50	16.45	00.55	EL/OL	11KV Poles 2Nos Damaged at Shameerper Cheruvukatta	-
6		Shameerpet	Anthaipally	11KV	Medchal	18.00	19.25	01.25	EL/OL	11KV PinInsulator failed at Upparpally	-
1	RR E	Uppal Kalsa	Vegetable market	11KV	Habsiguda	14.05	16.10	02.05		Cable cut & Fallen on Iron pole at Main road	-
2		Street no 8	Greenhills	11KV	Habsiguda	15.16	15.49	00.33		Post of insulator fail at Brudhavan colony	-
3		Yapral	Pedso	11KV	Sainikpuri	14.02	15.15	01.13		Tree branches fall on 11Kv line at Rigistation Colony (AE/OP)	-
4		RGK	Barshipet	11KV	Sainikpuri	14.05	16.50	02.45		Polimer Disk fail at Mallanna Temple (LM Rajender)	-
5		RGK	Nissa	11KV	Sainikpuri	14.05	17.20	03.15		4 No Tree fall on 11Kv line at Nissa Campus (LM Rajender)	-
6		Janapriya	Vampuguda	11KV	Sainikpuri	14.25	15.35	01.10		Tree branches fall on 11Kv line at Vampuguda Communiti Hall (LM Janardhan)	-
7		Vayupuri	GK Nagar	11KV	Sainikpuri	14.30	16.09	01.39		Coconut Tree branches fall on 11Kv line at Gokul Nagar (L Insp Kashiram)	-
8		Cherlapally-II	Junnuram	11KV	Sainikpuri	15.15	16.15	01.00		11Kv Disk fail at EC Nagar Commity Hall (AE/OP)	-
9		Cherlapally-III	Gail	11KV	Sainikpuri	15.15	16.54	01.39		11Kv Pin Insuletor at Gail Opp Gandhi Nagar Venkateshwara Compony (AE/OP)	-
2	HYD N	Marredpally	Lalitha Nagar	11KV	C-VI	13.55	15.30	01.35	EL,OL-Rph	Pin Insulator flash over at Road No.10	-----
3	HYD C	Hussain Sagar	NTR Marg	11KV	I	23.40	01.00	01.20	EL,OL	Moisture formed in RMU at NTR Marg	Arranged B/F on 11KV Lumbini Park feeder
4		Golconda	Shaikpet Water Works	11KV	VII	05.20	07.45	02.25	EL,OL-Bph	No Visible Fault	Arranged B/F on 11KV Vinobha Nagar feeder