

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	5	1	5	1	5			
7	RR(E)	168	403		14		14		14			
8	Hyd	194	1044		10		10		10			
	Total	606	3055	1	29	1	29	1	29	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		11		11		11			
3	MDK	107	933		1		1		1			
4	SDPT				15		15		15			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	27	0	27	0	27	0	0	
	Grand Total	1082	6468	1	56	1	56	1	56	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 02.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	Medchal	Kompally	33KV	Medchal	05.41	08.01	02.20		No visible fault	Kompally	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nampally	Mandapuram	11KV	Devarakonda	08.04	12.05	04.01	EL	B/D of HT/LT	-
2		Melavai	Devathpally	11KV	Devarakonda	02.48	05.40	02.52	EL	B/D of Tree Filoen	-
3		Tripuraram	Tripuraram Ind	11KV	Miryalaguda	03.00	06.30	03.30	EL	Tree branch fallen	-
4		Pulicherla	Pulicherla	11KV	Miryalaguda	02.36	08.59	06.23	EL	11KV line snapped	-
5		Dirsenapally	Yerrapahad	11KV	Suryapet	12.45	13.45	01.00	EL	Jumper cut	-
6		Shantinagar	Bojjagudem	11KV	Huzurnagar	04.00	08.15	04.15	EL	11 KV LINE SNAPPED	-
7		Gondiryala	Kothagudem	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV DISK FAILED	-
8		Anantharam	Hanumapur	11KV	Bhongir	05.25	07.10	01.45	EL	11 kv Insulator failed Danimma thota near Baswapur village	-
9		Datherpally	Datherpally	11KV	Bhongir	08.00	10.47	02.47	EL	02 no. 11 kv Insulator failed near Datherpally village	-
10		Pamukunta	Jala	11KV	Bhongir	15.20	16.20	00.20	EL	11 KV Line snapped near Sub station 04 th pole	-
11		Ramannapet	Neernemmula	11KV	Choutuppal	01.17	08.50	07.33	EL	11 kv Insulator failed near Neernemmula village	-
1	MDK	Gummadidala	Gummadidala	11KV	Patancheru	06.05	10.15	04.10		BD due to Disk failure	-
1	SDP	Thornal	Thornal	11KV	Siddipet	07.05	09.05	02.00		B/D Insulator Fail Lc No 18223	-
2		Thornal	Appnapally	11KV	Siddipet	07.05	08.35	01.30		B/D Tree Fall Down Lc no 2823	-
3		Kammarlapally	Kothapally	11KV	Siddipet	07.10	09.38	02.28		B/D 11 kv Disk Fail Lc no20598	-
4		Chellapur	Chellapur	11KV	Siddipet	06.40	09.30	02.50		B/D Disk Fail Lc no 16541	-
5		Peddachikode	Kammarlapally	11KV	Siddipet	07.30	09.50	02.20		B/D Insulator Fail Lc No 2848	-
6		Gajwel SS	Jaligama Feeder	11KV	Gajwel	09.30	12.30	03.00		11KV Insulator failed	-
7		Pamulaparthi	Ippalagudem Feeder	11KV	Gajwel	14.52	15.30	00.38		11KV Insulator failed	-
8		Gowraram SS	Gowraram AGL Feeder	11KV	Gajwel	04.45	09.35	04.50		Tree banches has fallen	-
9		Gowraram SS	Gowraram Town-I	11KV	Gajwel	05.50	09.25	03.35		Tree banches has fallen	-
10		Gowraram SS	Gowraram Town-II	11KV	Gajwel	08.40	09.10	00.30		Tree banches has fallen	-
11		Adivimajeedpally SS	Advimajeedpally Feeder	11KV	Gajwel	07.20	10.40	03.20		11KV Insulator failed	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
12	SDP	Chaeelasagar SS	Cheelasagar AGL Feeder	11KV	Gajwel	11.30	14.30	03.00		Disk faile	-
13		Thunkibollaram SS	Dasarlapally Industrial Feeder	11KV	Gajwel	06.00	08.50	02.50		Tree branches has fallen by line	-
14		Chityala	Chityala	11KV	Husnabad	06.10	09.45	03.35		Jumper cut	-
15		Guruvannapet	Posanpally	11KV	Husnabad	05.45	09.40	03.55		Insulator fail	-
1	RR N	Kompally	NCL	11KV	Medchal	04.40	06.49	02.09		No Fault	-
2		Aliabad	Aliabad	11KV	Medchal	05.10	07.05	01.55		Line AB Switch opened at Military Thota(11KV Pole bend)	-
3		Shameerpet	Shameerpet	11KV	Medchal	07.55	10.05	02.10		11KV Disc failed at Ameena College	-
4		Keshavaram	Potharam	11KV	Medchal	07.45	09.30	01.45		25KVA T/F failed at Mynampally Thota	-
5		Devarayamjal	Kottapet	11KV	Medchal	05.20	07.50	02.30		HG Fuse Insulator failed at Reliance Godown	-
1	RR E	AS Rao Nagar	Shaffi Nagar	11KV	Sainikpuri	04.30	05.30	01.00		11KV line AB Switch Opend at Poultry form and 11KV Disk failed at Nehru Nagar Tagore School (AE)	-
2		Vasanthapuri	Raghavendra	11KV	Sainikpuri	01.41	02.46	01.05		11KV Disk failed at Meghana Construction (Artisan Jamal/Beem Rao)	-
3		Vinayak Nagar	RK Nagar	11KV	Sainikpuri	19.03	20.30	01.27		11Kv Disk failed at RK Nagar (L.Insp Veenu Gopal)	-
4		Anand Bagh	PB Colony	11KV	Sainikpuri	18.10	19.58	01.48		11Kv Polymer Insulator failed at near NBH Colony East Anandbagh (L.Insp Veenu Gopal)	-
5		Techpark	AP food	11KV	Habsiguda	04.05	05.58	01.53		Pin insulator fail at GVK company	-
6		Uppal Kalsa	Asian	11KV	Habsiguda	04.00	06.30	02.30		Due to Heavy Rain 11KV Jumper twisted at Ashok leyland company	-
7		Uppal	Bank colony	11KV	Habsiguda	02.30	03.20	00.50		Due to Heavy Rain Tree branches fallen on 11kv line at LFJC college	-
8		NGRi	HBG	11KV	Habsiguda	04.27	06.52	02.25		Due to Heavy Rain Tree branches fallen on 11kv line at street no 8 & also End kit fail & given B/F from Nacharam feeder	-
9		Ramanthapur	Church colony	11KV	Habsiguda	04.31	05.31	01.00		11KV Line Snapped at Nehru nagar	-
10		Mallapur	Sai nagar	11KV	Habsiguda	04.10	07.30	03.20		11KV line Snapped & tree branches fallen on 11kv line at Akashila company	-
11		Mallapur	IDA mallapur	11KV	Habsiguda	04.30	07.20	02.50		11KV line Snapped & fallen on IDA feeder which leading in same tower at Akashila company (Safety purpose)	-
12		Idauppal	Metro	11KV	Habsiguda	04.33	07.53	03.20		Due to Heavy Rain 11KV jumper cut & Insulator fail of OXCO company	-
13		Idauppal	Metro	11KV	Habsiguda	07.55	08.45	00.50		Tree branches fallen on 11kv line near Vodafone	-
14		Singapur	IT park	11KV	Keesara	06.30	08.25	01.55		Insulator fail & Line cut at genpact company	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Lalaguda	Shanthi Nagar	11KV	V	04.10	06.35	02.25	EL,OL-Bph	Pin Insulator flash over at SFI School	-----
2		I.I.C.T	Deccan	11KV	V	05.22	06.45	01.23	EL,OL	No Visible Fault	-----
3		Gunrock	Tirumalagiri	11KV	C-VI	06.30	08.20	01.50	EL	Pin Insulator flash over LIC Building	-----
4		Nehru Nagar	LIC Colony	11KV	C-VI	05.37	10.05	04.28	OL-Yph	Jumper cut at Court Area & tree branches fallen on lines at J.B.S.	At 08:06Hrs partial fdr charged & remaining loads added on 11KV Picket fdr
5		Clock Tower	Natraj	11KV	V	16.18	17.38	01.20	EL,OL-Rph	No Visible Fault	Arranged B/F on 11KV S.P.Road fdr
6		Zamistanpur	Sanjeevaiahpuram	11KV	V	23.35			EL,OL-Yph	No Visible Fault	00:22Hrs partial fdr charged
1	HYD S	Yakuthpura	Saleema Khatoon	11KV	VIII	05.10	06.48	01.38	EL,OL-Rph	AB Cable fault	Arranged B/F on 11KV Khan Nagar feeder
2		Moosarambagh	Moosarambagh	11KV	VIII	05.05	07.15	02.10	EL,OL	Tree branches fallen on lines at Ramalayam Temple	-----
1	HYD C	Chilkaiguda	Golconda X-Road	11KV	II	04.53	06.38	01.45	EL,OL	Pin Insulator flash over at Musheerabad P.S	-
2		Narayanaguda	Chikkadapally	11KV	II	04.50	06.30	01.40	Opened AR	Tree branches fallen on lines at Venkateshwara Temple	-