

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		1		1		1			
3	MDK	107	933	3	1	3	1	3	1			
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	12	3	12	3	12	0	0	
	Grand Total	1082	6468	3	15	3	15	3	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Jogipet	Dakur	33KV	Jogipet	13:55	14:25	0:30		Monkey fallen on the line	Dakur	No
2		Zaheerabad	Buchinelly	33KV	Zaheerabad	12.40	17.00	04.20		Tree branch fallen on the line and Jumper cut	Buchinelly	No
3		R.C.Puram	JK Fenner	33KV	Patancheru	10.30	14.30	04.00		Cable End kit Failure	JK Fenner	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Makthal	NEREDGAMA	11KV	Narayanpet	08.05	09.45	01.40		Breakdown due to 11kv line cut at Neredgama doddi vlg	No
2		Thangadi	KUSMURTHY	11KV	Narayanpet	08.20	11.50	03.30		Breakdown due to Earth fault	No
3		PALLERLA	NANDIPAD	11KV	Narayanpet	11.40	14.55	03.15		Breakdown due to 11kv line cut at Nandipad vlg	No
1	NLG	Kasarabadha	T K Pahad	11KV	Suryapet	9:30	12:20	2:50	E/L	11KV Conductor snapped	No
1	MDK	EPIP-II	Padmapower	11KV	Sangareddy	13:20	13:50	0:30		Tree branches fallen on the line	No
1	SDPT	Gurralagondi	Malyala	11KV	Siddipet	13:10	14:37	1:27		Tree branches fallen on the line	No
2		Dubbak	Lachapet	11KV	Siddipet	08.50	09.50	01.00		Brass patti cut, LC No. 15687	No
3		Komuravelly	Posanpally	11KV	Husnabad	12.50	17.30	04.40		Disc failed	No
4		Gouravelly	Gouravelly rural	11KV	Husnabad	00.00	08.00	08.00		Bird fallen on the line	No
5		Pamulaparhty SS	Ippalagudem	11KV	Gajwel	11.43	13.03	01.20		Disc failed	No
6		Thipparam SS	Muddapur	11KV	Gajwel	12.00	13.52	01.52		Disc failed	No
7		Godugupally SS	Godugupally	11KV	Gajwel	09:58	13:42	3:44		100KVA DTR failed	No
1	RR N	Somasila	Madhavarao nagar	11KV	Kukatpally	1:22	2:30	1:08	OL	11KV outgoing UG cable falt at Madhavarao nagar	No
2		Prashanth Hills	Srinivasa colony	11KV	Kukatpally	19.25	21.10	01.45	EL/OL	Breakar problem at Sub station	No
1	HYD N	Begumpet	ESI Staff Quarters	11KV	IV	02.32	04.05	01.33	A/R tripped	Lug cut at SS	Arranged B/F on 11KV S.R.Nagar fdr