

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		4		4		4			
3	MDK	107	933		1		1		1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	12	0	12	0	12	0	0	
	Grand Total	1082	6468	0	14	0	14	0	14	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 08.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 08.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Badepally	Burgupally	11KV	Jadcherla	09.30	11.20	01.50		Bird Died On The 11KV Line Near Burgupally (Vi).	-
2		K V Pet	Town	11KV	Jadcherla	12.20	15.20	03.00		11Kv Wire Cut Near Raghavendra Colony Back Side.	-
3		EKLASPUR	JINNARAM	11KV	Jadcherla	04.50	07.45	02.55		Due to 11kv Jumper Cut at gajula thanda	-
1	NLG	Arvapally	Thungagudem	11KV	Suryapet	06.00	09.20	03.20	E/L	Insulator flashover	-
2		Annaram	Sangem	11KV	Suryapet	05.30	08.00	02.30	E/L	Conductor snapped	-
3		Puligilla	Kanchanapally	11KV	Choutuppal	06.40	08.55	02.15	EL/OL	10 KVA DTR failed at Parabavi near kanchanapally village.	-
4		Voligonda	Lothukunta	11KV	Choutuppal	09.40	11.20	01.40	EL/OL	11 kv Insulator failed at Durgamma temple near Lothkunta village	-
1	MDK	Pati	Pati	11KV	Patancheru	09.50	10.40	00.50		BD due to Disk failure	-
1	SDPT	Ragothampally	Akaram	11KV	Siddipet	08.25	10.50	02.25		B/D-Line phase to phase-Now Rectified.	-
2		Raghavapur	Peddalingareddypally	11KV	Siddipet	00.00	08.40	08.40		B/D-Disk fail-Now Rectified.	-
3		Komuravelly	Gouraipally	11KV	Husnabad	12.45	13.32	00.47		Insulator failure, same rectified	-
4		DAMARAKUNTA	DAMARAKUNTA	11KV	Gajwel	10.19	11.44	01.25		DTR FAILURE	-
1	RR N	Devarayamjal	Mandaipally	11KV	Medchal	15.40	16.55	01.15		11KV Line cut and replaced at Yeligala Village	-
1	HYD C	Hussain Sagar	I.O.E	11KV	I	17.30	18.50	01.20	EL,OL	Cable fault at Ohri's Hotel	