

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	10	1	10	1	10			
7	RR(E)	168	403		10		10		10			
8	Hyd	194	1044		9		9		9			
	Total	606	3055	1	29	1	29	1	29	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	3	2	3	2	3			
2	NLG	144	988		6		6		6			
3	MDK	107	933	2	2	2	2	2	2			
4	SDPT			2	19	2	19	2	19			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	30	6	30	6	30	0	0	
	Grand Total	1082	6468	7	59	7	59	7	59	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 10.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Amit Cotton Mill	33KV	Jadcherla	11.32	12.48	01.16	E/L&O/L	AB Switch open at Cut point at Industry	Amit Cotton Mill	-
2		Polepally	Gangapur	33KV	Jadcherla	23.39	23.50	00.11	E/L	Due to Wind and Light Rain	Gangapur	Alternate Supply Arranged from 33KV Konded feeder at 23:50Hrs.
1	MDK	Zaheerabad	Hadnoor	33KV	Zaheerabad	15.15	16.47	01.32		BD Tree Branches on line	Hadnoor	-
2		Zaheerabad	New Allana	33KV	Zaheerabad	15.15	16.06	00.51		BD Tree Branches on line	New Allana	-
1	SDPT	Siddipet	Thornal	33KV	Siddipet	19.20	21.00	01.40		Insulator replaced		
2		Meenajipet	Naacharam	33KV	Gajwel	06.43	07.24	00.41		Earth Falt		
1	RR N	132KV Chintal	33KV Subash Nagar	33KV	Medchal	19.00	19.30	00.30	BD	Backfeeding from 33KV Petbasherabad feeder(132KV Medchal)33KV Pin Insulator failed and replaced at SBI bank,Jairam Nagar Charged ok 20:49	33KV Subash Nagar	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kaverammamet	Bandamidipally	11KV	Jadcherla	10.40	11.50	01.10		AB Switch Spark Near Macharam	-
2		MADDUR	PEDIRIPAD	11KV	Narayanpet	07.20	09.15	01.55		Phase to Phase to maddur outskirts	-
3		APPAKPALLY	APPIREDDYPALLY	11KV	Narayanpet	10.38	15.04	04.26		11kv line cut at appireddypally vlg	-
1	NLG	Palem	Palem	11KV	Nalgonda	08.50	12.15	03.25	EL	100KVA DTR failed at SS-31	-
2		Kethepally	Gudiwada	11KV	Nalgonda	08.30	10.00	01.30	EL	11KV jumper cut	-
3		Balemla	Balmela	11KV	Suryapet	08.45	12.20	03.35	EL	Conductor snapped	-
4		Janpahad	Janpahad	11KV	Huzurnagar	00.45	07.30	06.45	EL	11 KV LINE SNAPPED	-
5		Gurralladandi	Ramulugundla thanda	11KV	Bhongir	06.00	09.12	03.12	EL	11 kv Line snapped at Kumara swamy well near Battugudem village.	-
6		Ambala	Modugubavigudem	11KV	Bhongir	01.00	09.00	08.00	EL	11 kv Solid core Insulator failed near Repaka village	-
1	MDK	EPIP-I	ORTIN	11KV	Sangareddy	20.30	21.48	01.18		BD Due to Insulator Failure	-
2		Hathnoora	Town Indl.	11KV	Jogipet	20.00	21.10	01.10		BD Due to AB Switch Sparks	-
1	SNDT	Cherial Town	Cherial Town	11KV	Husnabad	19.35	20.05	00.30		Tree branch fallen on the line	
2		Komuravelli	Komuravelli 7Hrs	11KV	Husnabad	09.30	17.35	08.05		Jumper out	
3		Komuravelli	Komuravelli 24Hrs	11KV	Husnabad	10.35	21.30	10.55		Tree branches fallen on the line	
4		Arjunpatla	Kamalayapally	11KV	Husnabad	18.10	22.10	04.00		Cable wire fallen on the DTR	
5		Akkannapeta	Pakkirnaik thanda	11KV	Husnabad	03.05	10.12	07.07		Brass Metal Cut	
6		Guggilla	Thimmaipally	11KV	Husnabad	17.50	20.50	03.00		Heavy Rain	
7		Samudrala	Baswapur	11KV	Husnabad	21.05	23.59	02.54		problem not find out	
8		Dubbak	Dubbak town	11KV	Siddipet	03.15	07.10	03.55		B/D 11kv jumper cut Lc no 15689	
9		Nangnoor	Akkenapally	11KV	Siddipet	18.50	20.02	01.12		B/D singel phase disk fail Lc no 18063	
10		Thornla	Appanapally	11KV	Siddipet	18.40	23.59	05.19		B/D Rain fall down	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
11	SRI	Chinnagundavelly	Chinnagundavelly	11KV	Siddipet	06.45	11.20	04.35		B/D disk fail Lc no 10234	
12		Chowdaram	Chowdaram	11KV	Siddipet	19.05	23.59	04.54		B/D Rain fall down till now	
13		Kammarlapally	Kammarlapally	11KV	Siddipet	18.20	20.35	02.15		B/D s-phase Lc no 8402	
14		GAJWEL SS	TOWN 1	11KV	Gajwel	11.03	11.58	00.55		COPPERPATTI CUT	
15		GAJWEL SS	TOWN 1	11KV	Gajwel	18.08	18.49	00.41		DISK FAILED	
16		GAJWEL SS	MUTRAJPALLY	11KV	Gajwel	16.07	17.06	00.59		11KV LINE PHASE TO PHASE	
17		GOWRARAM SS	GOWRARAM TOWN 2	11KV	Gajwel	09.20	11.00	01.40		INSULATOR FAILED	
18		KOKKONDA SS	BASWAPUR	11KV	Gajwel	10.40	12.10	01.30		11KV LINE CUT	
19		THIMMAREDDYPALLY SS	THIMMAREDDYPALLY	11KV	Gajwel	12.00	14.20	02.20		11KV LINE CUT	
1	RR N	Gagillapur	Thanda	11KV	Jeedimetla	10.30	11.35	01.05	EL	Line Petroling No Visble Falt	-
2		Chintal	Ganesh Nagar	11KV	Medchal	18.30	19.20	00.50	BD	11KV Pin Insulator failed at Ammabhavani temple	-
3		Dppally	Ganddimaisamma	11KV	Jeedimetla	18.45	23.00	04.15	EL/OL	Due to Havy Rain	-
4		Dppally	Gagillapur	11KV	Jeedimetla	18.45	23.00	04.15	EL/OL	Due to Havy Rain	-
5		Dppally-II	Indo Fab	11KV	Jeedimetla	19.50	22.50	03.00	EL/OL	Due to Havy Rain Tree fallen on the 11KV Line at Dundigal PS	-
6		Pudur	Mallanna Temple	11KV	Medchal	10.05	11.40	01.35	BD	11KV Line Cut & Replaced at Goshaiguda	-
7		ICICI	Bharath Biotech	11KV	Medchal	08.00	10.50	02.50	BD	11KV Pin Insulator failed at Praja Water Plant	-
8		Laxmapur	Narayanpur	11KV	Medchal	11.40	12.40	01.00	BD	No visible fault	-
9		Kistapur	Kistapur	11KV	Medchal	14.00	16.00	02.00	BD	No visible fault	-
10		Aliabad	LGM Pet	11KV	Medchal	17.55	19.25	01.30	BD	No visible fault	-