

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	13	1	13	1	13			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				9		9		9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>24</b>	<b>2</b>	<b>24</b>	<b>2</b>	<b>24</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>31</b>	<b>2</b>	<b>31</b>	<b>2</b>	<b>31</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 12.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thirumalagiri	Thonda	11KV	Suryapet	03.00	06.42	03.42	E/L	11Kv Insulator flashover	-
2		Annaram	Annaram	11KV	Suryapet	10.50	12.20	01.30	E/L	11Kv Conductor snapped	-
3		Palakeedu	Sajipuram	11KV	Huzurnagar	04.00	07.45	03.45	E/L	11Kv Line snapped	-
4		Palakeedu	Bothalapalem	11KV	Huzurnagar	06.00	08.15	02.15	E/L	11Kv Jumper Cut	-
5		Tekulasomaram	Pahilwanpuram	11KV	Choutuppal	01.05	08.30	07.25	E/L	11kv Line snapped near Pahilwanpuram (V)	-
6		Chervupally	Dacharam	11KV	Nalgonda	22.45	08.00	09.15	E/L	11Kv Jumper Cut	-
7		Eduloor	G.B.Gudem	11KV	Nalgonda	08.00	10.35	02.35	E/L	11Kv Line Snapped	-
8		Kattangur	Munukuntla	11KV	Nalgonda	12.45	14.30	01.45	E/L	11Kv Jumper Cut	-
9		Dindi	Dindi Rural	11KV	Devarakonda	12.40	15.12	02.32	E/L	11Kv Jumper Cut	-
10		Singarajpally	Veeraboinapally	11KV	Devarakonda	12.40	13.50	01.10	E/L	11Kv Conductor Snapped	-
11		Chitriyala	Chitriyala	11KV	Devarakonda	11.20	12.32	01.12	E/L	11Kv Insulator failed	-
12		Marriguda	Vattipally	11KV	Devarakonda	10.47	11.45	00.58	E/L	11Kv Conductor Snapped	-
13		Puttamgandi	Vaddipatla	11KV	Devarakonda	14.09	15.25	01.16	E/L	11Kv Conductor Snapped	-
1	MDK	Fasalwadi	Rythu Nagar	11KV	Sangareddy	17.42	19.10	01.28		B/D due to Insulator failure	-
2		Sadasivpet	TSM	11KV	Sangareddy	14.50	16.00	01.10		B/D due to Insulator failure	-
1	SDPT	DOULTHABAD	(LC.NO:7458) SRINIVAS.ALM	11KV	GAJWEL	10:08	11:40	1:32		TREE BRANCHES FELL ON 11 KV LINE	-
2		MD SHAPUR	LINGARAJ PALLY THANDA	11KV	GAJWEL	11:26	17:36	6:10		JUMPER CUT	-
3		DOMMAT	SURAMPALLY	11KV	GAJWEL	7:41	12:04	4:23		CUPPER PATTY CUT	-
4		Gambeerpur	Shilajinagar	11KV	SIDDIPET	09.00	11.20	02.20		B/D (Disk fail) LC.NO.5261	-
5		Mustabad X-Road	Gadicherlapally	11KV	SIDDIPET	05.15	07.35	02.20		B/D Short Circuit	-
6		HUSNABAD	POTLAPALLY	11KV	SIDDIPET	00.00	12.00	12.00		B.D Due to tree branch fallen on line	-
7		GANDIPALLY	GANDIPALLY RURAL	11KV	HUNABAD	00.00	10.48	10.48		B.D Due to Heavy wind tree branch fallen on line	-
8		Komuravelly	Komuravell 24 Hrs	11KV	HUNABAD	11.45	08.09	10.48		B.D, Due to Insulator failed	-
9		Komuravelly	Peddarajupeta	11KV	HUNABAD	12.00	08.09	10.33		B.D, Due to Insulator failed	-
1	RR N	Kompally	Nuziveedu	11KV	Medchal	10.08	11.45	01.37	EL	11KV Line cut and replaced at Nagarjuna Homes	-
2		Subhash Nagar	Jairam Nagar	11KV	Medchal	02.27	02.58	00.31	EL	Tree fallen on the 11KV Line at Chermas	-
3		Devarayamjal	Mandaipally	11KV	Medchal	11.30	13.00	01.30	EL/OL	No Fault	-
4		Laxmapur	MC Pally	11KV	Medchal	11.46	12.35	00.49	EL	Bird fallen on the 11KV Line at Lingapur Thanda	-
1	RR E	Techpark	Raheja	11KV	Habsiguda	06.27	07.25	00.58		Line Patrolling but no visible fault(Dedicated feeder) & Consumer side RMV fault & Feeder Idle charged	-
2		Narapally	P.singaram	11KV	Keesara	00.30	02.30	02.00		Tower copper patti fallen on cross ram at Thenegudam	-
1	HYD S	Ch' Baradari	Gazi Banda	11KV	III	03.20	04.54	01.34	EL	Cable fault	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 33KV Breakdowns

Date: 12.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	K.M.Pally	Chinthapally	33KV	Devarakonda	14.25	16.12	01.47	E/L	33Kv Pin insulator failed because of sqarell touched conductor	Chinthapally	-
1	MDK	Kandi	SKOL	33KV	Sangareddy	17.50	23.45	05.55		B/D due to Insulator failure	SKOL	-