

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988	1	20	1	20	1	20			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>26</b>	<b>3</b>	<b>26</b>	<b>3</b>	<b>26</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>34</b>	<b>3</b>	<b>34</b>	<b>3</b>	<b>34</b>	<b>0</b>	<b>0</b>	

## Circle-wise 11KV Breakdowns

Date: 13.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Kothamolgara	11KV	Jadcherla	06.00	06.50	00.50		11KV Phase To Phase Near Chinna Kappeta (Vi)	-
2		Balanagar	Mothiganapur	11KV	Jadcherla	05.45	12.15	06.30		11KV Disc Fail Near Nandaram Cheru Vu Side.	-
1	NLG	Aipoor	Aipoor	11KV	Suryapet	07.50	09.25	01.35	E/L	Disk failed	-
2		Balemla	Gandi nagar X press	11KV	Suryapet	06.10	07.24	01.14	E/L	Insulator flashover	-
3		Dirsincherla	Yallapuram	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV LINE SNAPPED	-
4		Dirsincherla	Narsiagudem	11KV	Huzurnagar	06.00	08.30	02.30	EL	11 KV LINE SNAPPED	-
5		Keethavarigudem	Velidanda	11KV	Huzurnagar	04.00	07.15	03.15	EL	11 kv jumper cut	-
6		Dondapahad	Vajinepally	11KV	Huzurnagar	05.00	07.30	02.30	EL	11 KV Disk failed	-
7		Munagala	Nelamarry	11KV	Huzurnagar	04.30	07.30	03.00	EL	11 KV LINE SNAPPED	-
8		Ghanpur	Ghanpur	11KV	Devarakonda	02.30	07.10	04.40	EL	Jumper Cut	-
9		Puttamgandi	Peddagummadam	11KV	Devarakonda	01.15	06.30	05.15	EL	11 Kv Conductor Snapped	-
10		Chitriyala	Chitriyala	11KV	Devarakonda	04.15	06.50	02.35	EL	11 Kv Insulator failed	-
11		Mellavai	Revely	11KV	Devarakonda	08.15	13.21	05.06	EL	11KV Pole Damaged	-
12		Puttamgandi	Vaddipatla	11KV	Devarakonda	14.09	15.25	01.16	EL	11 Kv Conductor Snapped	-
13		Kothapally	Peddaminigal	11KV	Devarakonda	05.50	07.10	01.20	EL	11 Kv Conductor Snapped	-
14		Kothapally	Krishnathanda	11KV	Devarakonda	05.50	07.16	01.26	EL	11 Kv Conductor Snapped	-
15		Gollaguda	Ramnagar	11KV	Nalgonda	00.30	01.30	01.00	EL	Jumper Cut	-
16		Matoor	Ragadapa	11KV	Miryalaguda	03.30	07.00	03.30	EL	Tree branches fallen on the line	-
17		Thadkamalla	Molkapatnam	11KV	Miryalaguda	01.00	03.00	02.00	EL	11 Kv Conductor Snapped	-
18		Nidmanoor	Shakapuram	11KV	Miryalaguda	02.50	06.30	03.40	EL	Jumper Cut	-
19		Alair	Ikurthy	11KV	Bhongir	07.02	09.50	02.48	EL/OL	11 kv Insulator failed at Cheruvu near Bahadurpet village	-
20		Voligonda	Nagaram	11KV	Choutuppal	09.40	11.30	01.50	EL/OL	11 KV Line snapped near Rice mill Voligonda	-
1	MDK	Pati	Pati	11KV	Patancheru	13.40	16.05	02.25		BD due to Pole damaged	-
2		Sangareddy	Filterbed	11KV	Sangareddy	17.38	18.50	01.12		BD due to Heavy Rain, No fault at found	-
1	SDPT	Narayanaraopet	beerappagudi	11KV	Siddipet	05.08	06.00	00.52		BD ( Insulator failure )	-
2		Akkanapet	Akkannapet Town	11KV	Husnabad	19.40	20.30	00.50		LINE SNAPPED	-
1	RR N	Dulapally	IDA-II	11KV	Medchal	00.07	01.14	01.07	BD	100KVA DTR HG Fuse Insulator Failed and Replaced at LN Enginnering Company	-
2		UMCC	Gajularamaram	11KV	Medchal	02.30	03.20	00.50	BD	11KV AB Cable failed at Ushodaya Colony	-
3		ICICI	Bharath Biotech	11KV	Medchal	10.22	11.42	01.20	BD	No Fault	-
1	RR E	AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	17.00	19.40	02.40		But No visible fault	-
2		Narapally	Prathap Singaram	11KV	Keesara	00.30	01.30	01.00		11KV Copper patti cut at Thenuguda Village	-
1	HYD N	I.I.C.T	Deccan	11KV	V	04.45	06.15	01.30	EL,OL	Dry tree fallen on lines & Disc Insulator flash over at Kokila Apts	-
2		Addagutta	Shanthi Nikethan	11KV	C-VI	06.50	08.07	01.17	EL,OL-Bph	Suspected Cable fault	Arranged B/F on 11KV Ravi Colony & 11KV Tukaram Gate feeders
1	HYD C	Zamistanpur	Jamai Osmania	11KV	II	07.05	09.00	01.55	EL	Cable fault at Parsigutta	Arranged B/F on 11KV Boudha Nagar feeder

## TSSPDCL - LMRC / Corporate office

## Circle-wise 33KV Breakdowns

Date: 13.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Kankurthy	33KV	Narayanpet	19.35	20.20	00.45	E/L	Due to 33KV Line Fault		Alternate Supply Arranged to 33KV Damargidda Feeder at 20:20Hrs
1	NLG	Madugulapally	Vishaka Industries	33KV	Miryalaguda	02.30	09.00	06.30	E/L	Jumper cut and Insulator failure		-
1	MDK	Zaheerabad	Hadnoor	33KV	Zaheerabad	10.45	14.50	04.05		BD due to Insulator failed		-