

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	10	2	10	2	10			
7	RR(E)	168	403		9		9		9			
8	Hyd	194	1044		16		16		16			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>35</b>	<b>2</b>	<b>35</b>	<b>2</b>	<b>35</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		5		5		5			
2	NLG	144	988		19		19		19			
3	MDK	107	933		5		5		5			
4	SDPT			2	26	2	26	2	26			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>55</b>	<b>2</b>	<b>55</b>	<b>2</b>	<b>55</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>90</b>	<b>4</b>	<b>90</b>	<b>4</b>	<b>90</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

## Circle-wise 33KV Breakdowns

Date: 14.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Shanigaram	Chalimada	33KV	Husnabad	02.45	10.15	07.30		BD Tree fall on the line	Chalimada	-
2		Duddeda	Medhinipur	33KV	Gajwel	02.38	08.25	05.47		BD Hevey Rain	Medhinipur	-
1	RR N	132KV Chintal	33KV Dulapally	33KV	Medchal	18.15	19.30	01.15		Tree fallen on the Line at Dulapally Road	33KV Dulapally	-
2		132KV LGM Pet	33KV MN Park	33KV	Medchal	00.06	07.30	07.24		Bird fallen on the 33KV Line at SEZ Company	33KV MN Park	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 14.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Krishna	CHEGUNTA	11KV	Narayanpet	10.35	16.20	05.45		Breakdown due to AB switch problem	-
2		MOHAMMADABAD	ANNAREDDYPALLY	11KV	Narayanpet	07.30	10.20	02.50		Breakdown due to DTR fail at julapally vlg	-
3		EKLASPUR	INDL FEEDER	11KV	Narayanpet	00.20	06.00	05.40		Breakdown due to tree branch fallen on 11kv line near sub station	-
4		MARIKAL	TILERU	11KV	Narayanpet	06.00	09.30	03.30		Breakdown due to tree branch fallen on 11kv line near ibrahimpatnam vlg	-
5		MARIKAL	MADWAR	11KV	Narayanpet	05.00	09.10	04.10		Breakdown due to one agl bit cut	-
1	NLG	Nakrekal	Nomula	11KV	Nalgonda	04.06	06.50	02.44	EL	HT/LT	-
2		Nakrekal	Marrur	11KV	Nalgonda	04.47	07.00	02.13	EL	11 KV Line Jumper Cutt	-
3		Kethepally	Inpamulla	11KV	Nalgonda	09.25	09.55	00.30	EL	SS-02 11KV Insulator Failed	-
4		Nakkalapally	Shapally	11KV	Nalgonda	06.00	08.15	02.15	EL	11 KV Line Jumper Cutt	-
5		Adavidevulapally	Ulsaipalem	11KV	Miryalaguda	12.00	14.55	02.55	EL	insulator faild	-
6		Seethya Thanda	Thopucherla	11KV	Miryalaguda	04.35	08.30	03.55	EL	Disc failed at Thopucherla	-
7		Seethya Thanda	Seethya Thanda	11KV	Miryalaguda	05.25	10.25	05.00	EL	Tree branch fallen on line at Ganapathivarigudem	-
8		Halia	Naidupalem	11KV	Miryalaguda	07.00	11.00	04.00	EL	insulator faild	-
9		Settipalem	Vemulapally AGL	11KV	Miryalaguda	06.15	11.20	05.05	EL	Line snapped at Vemulapally	-
10		Velmagudem	Velmagudem	11KV	Miryalaguda	13.45	15.55	02.10	EL	Disc failed	-
11		Rajavaram	Rajavaram	11KV	Miryalaguda	08.00	11.00	03.00	EL	insulator faild	-
12		Mukundapuram	G Kothapally	11KV	Suryapet	03.50	07.20	03.30	EL	Disk failed	-
13		Aipoor	Kotapahad	11KV	Suryapet	06.05	09.20	03.15	EL	Insulator flashover	-
14		Timmareddy gudem	Ganapavaram	11KV	Huzurnagar	06.25	08.00	01.35	EL	11 KV LINE SNAPPED	-
15		Palakeedu	Bothalapalem	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV Jumper cut	-
16		Gaddipally	Kutubshapuram	11KV	Huzurnagar	04.00	07.30	03.30	EL	11 KV LINE SNAPPED	-
17		Bollepally	Surepally	11KV	Bhongir	05.00	10.05	05.05	EL	11 kv Insulator failed at Pallam well near Surepally village	-
18		B.Ramaram	Saiteja Indl	11KV	Bhongir	06.10	07.30	01.20	EL	11kv Insulator Failed near Thumkunta Village	-
19		Ishkilla	Munipampula	11KV	Choutuppal	06.25	09.40	03.15	EL	11 kv Line snapped at Muthyam rao Thota near Munipampula village	-
1	MDK	Ismailkhanpet	Industrial	11KV	Sangareddy	05.18	08.30	03.12		BD due to Insulator failure	-
2		Bollaram-I	Soubhagya	11KV	Patancheru	03.00	07.00	04.00		BD due to Tree branches fallen on the line	-
3		Bollaram-I	Salgutty	11KV	Patancheru	18.20	22.00	03.40		BD due to Insulator failure	-
4		Inole	Pedda Kanjarla	11KV	Patancheru	01.50	07.40	05.50		BD due to Tree branches fallen on the line	-
5		Kistareddypet	Beeramguda	11KV	Patancheru	04.45	06.48	02.03		BD due to Tree branches fallen on the line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDP	Dubbak IPDS	Gandhi feeder	11KV	Siddipet	01.53	08.00	06.07		B/D Tree branch fall on the line	-
2		Komatichervu	Housing Board	11KV	Siddipet	04.00	06.30	02.30		B/D Tree branch fall on the line	-
3		Narmetta	Thimmaipally	11KV	Siddipet	12.20	13.00	00.40		B/D Line Netting	-
4		Thornal	Appanapally	11KV	Siddipet	05.00	09.15	04.15		B/D Insulater fail & LC.No.10365	-
5		Pullur	Pullur	11KV	Siddipet	01.50	06.50	05.00		B/D Tree banch fall on the line	-
6		Chinnagundavelly	Chinnagundavelly	11KV	Siddipet	13.15	15.15	02.00		B/D Insulater fail & LC.No.10222	-
7		Laxmidevipally	Ibrhimpur	11KV	Siddipet	03.00	10.20	07.20		B/D Insulater fail & LC.No.18457	-
8		Ramancha	Gangapur	11KV	Siddipet	06.30	09.30	03.00		B/D Jumper cut	-
9		Ramancha	Ramancha	11KV	Siddipet	07.15	09.40	02.25		B/D line cut	-
10		Machapur	Machapur	11KV	Siddipet	06.00	10.00	04.00		B/D 11 KV wire cut	-
11		Machapur	Gangapur	11KV	Siddipet	06.00	10.00	04.00		B/D 11 KV wire cut	-
12		Thimmapur	Thimmapur	11KV	Siddipet	02.01	04.02	02.01		B/D Disk fail	-
13		Thimmapur	Padmanabampally	11KV	Siddipet	02.01	06.37	04.36		B/D Tree banch fall on the line	-
14		Peddagundavelly	Peddagundavelly I	11KV	Siddipet	07.30	11.30	04.00		B/D 11 KV wire cut	-
15		Peddachikode	Arepally	11KV	Siddipet	02.00	07.00	05.00		B/D Tree banch fall on the line	-
16		Jangapally	Veererreddypally	11KV	Siddipet	09.30	12.00	02.30		B/D Disk fail & LC.No.15509	-
17		Akbarpet	Bhoompally	11KV	Siddipet	03.55	11.55	08.00		B/D HT/LT	-
18		Potharam	Potharan town	11KV	Husnabad	09.30	11.00	01.30		3 ph break down	-
19		Dharmaram	Dharmaram	11KV	Husnabad	04.53	07.10	02.17		Insulator fail	-
20		Shanigaram	Gundareddypally	11KV	Husnabad	00.00	09.00	09.00		Break down	-
21		Baswapur	Baswapur town	11KV	Husnabad	09.15	10.30	01.15		Break down	-
22		Guruvannapet	Guruvannapet	11KV	Husnabad	03.25	09.10	05.45		Line problem	-
23		Gurjakunta	Gurjakunta Agl & town	11KV	Husnabad	06.00	13.40	07.40		Jumper cut	-
24		Komuravelli	Komuravelli Agl & Peddarajpet	11KV	Husnabad	02.40	04.20	01.40		Break down	-
25		Komuravelli	Kistampet	11KV	Husnabad	02.45	04.20	01.35		Break down	-
26		Arjunpatla	Arjunpatla Agl	11KV	Husnabad	02.40	10.40	08.00		3 ph break down	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Subash Nagar	Saibaba Nagar	11KV	Medchal	05.27	06.17	00.50		Tree fallen on the 11KV Line at Vajpei Nagar	-
2		Petbasheerabad	Vaishnavi Enclave	11KV	Medchal	04.30	06.00	01.30		Tree fallen on the 11KV Line at Deccan Chronicle	-
3		Kompally	NCL	11KV	Medchal	18.17	19.10	00.53		Tree fallen on the 11KV Line at Vensai Apartment	-
4		Subhash Nagar	Meenakshi	11KV	Medchal	18.23	19.47	01.24		11KV AB Cable failed (Back feeding from 11KV Ramraj Nagar)	-
5		Petbasheerabad	Vaishnavi Enclave	11KV	Medchal	18.20	19.30	01.10		11KV Line AB Switch opened at Decan concronical (100KVA DTR Insulator Failed)	-
6		Thumkunta	Thumkunta	11KV	Medchal	04.50	08.00	03.10		11KV Pin Insulator failed at Mandaipally Road	-
7		Shameerpet	Shameerpet	11KV	Medchal	08.10	10.45	02.35		11KV Jumper opened at SC Colony ( 5DTR's no supply )	-
8		Aleap	Jagan Studio	11KV	Jeedimetla	04.00	05.40	01.40		Due to Rain	-
9		Aleap	Dr Colony	11KV	Jeedimetla	04.00	05.25	01.25		Due to Rain	-
10		Aleap	Punchavati	11KV	Jeedimetla	04.30	05.30	01.00		Due to Rain	-
1	RR E	Uppal	Bank Colony	11KV	Habsiguda	05.10	06.10	01.00		25KVA Gudesab DTR UG Cable jumper cut at Beerappagadda	-
2		NGRI	St.No.08	11KV	Habsiguda	04.52	07.50	02.58		11KV Pin Insulator failed at CCMB Quarters Opposite Genpact Road	-
3		Techpark	AP Food	11KV	Habsiguda	02.07	03.04	00.57		Line patrolling but no visible fault & Total load B/F supply taken from 11KV Haryanasteel feeder	-
4		Mallapur-2	Narsimha Nagar	11KV	Habsiguda	09.30	10.06	00.36		11KV Disc failed at M S Biryani Point	-
5		Moula-Ali	HCL	11KV	Sainikpuri	04.50	09.32	04.42		11Kv Pin Insuletor fail at Krishna Nagar Road No 5 (Artisan/Raju)	-
6		Anandbagh	BS Nagar	11KV	Sainikpuri	03.47	04.57	01.10		Tree branches fallen on 11Kv line at Saibaba Temple Vishnupuri Colony (LM Babu) Rain & Wind	-
7		Kushaiguda	Kushaiguda	11KV	Sainikpuri	06.15	07.00	00.45		Tree branches fallen on 11Kv line at Kushaiguda Industry (AE/OP)	-
8		Nagaram	S N Colony	11KV	Keesara	02.52	03.40	00.48		Tree branches fallen on 11KV line Rampally 'X' Road	-
9		Nagaram	Gandhi Nagar	11KV	Keesara	19.02	19.56	00.54		Flexi fallen on 11KV line Rampally 'X' Road	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Addagutta	Tukaram Gate	11KV	C-VI	04.20	05.30	01.10	EL	Faulty loads of 11KV Shanthi Niketan feeder	-----
2		Muffakamja College	Nandi Nagar	11KV	X	04.44	06.28	01.44	EL,OL	Pin Insulator flash over at Road No.14	-----
3		Bansilalpet	Nagannakunta	11KV	V	05.00	08.24	03.24	OL-Rph	Pin Insulator flash over at Hanuman Temple	Partial loads added on 11KV Bata feeder
4		K.I.M.S	H.D.F.C	11KV	V	07.02	08.54	01.52	EL,OL-Rph	Pin Insulator flash over at P.G Road	-----
5		Gymkhana	Tadbun Temple	11KV	C-VI	07.05	09.15	02.10	EL	Pin Insulator flash over at Tadbun Chowrastha	07:40 Hrs partial feeder charged stood OK
6		I.I.C.T	Dall Mill	11KV	V	07.30	09.10	01.40	OL	Tree branches on lines on lines at Vaishali Building	-----
7		Clock Tower	Railway Reservation	11KV	V	18.39	20.47	02.08	EL	DTR fault	Arranged B/F on 11KV Rezimental Bazar fdr
8		I.D.P.L	Shivalayam	11KV	VI	18.54	20.35	01.41	EL,OL	Cable fault near SS	Arranged B/F on 11KV Samatha Colony fdr
1	HYD S	Gunj	Palton	11KV	VIII	04.57	06.13	01.16	OL-Yph	No Visible Fault (Due to Rain)	-----
2		Gunj	Hanuman Temple	11KV	VIII	06.35	08.45	02.10	All Indication	2No. Jumpers cut at Cable Raising Point	-----
3		Santosh Nagar	Bhavani Nagar	11KV	VIII	06.49	07.54	01.05	EL,OL-Bph	No Visible Fault (Due to Rain)	Arranged B/F on 11KV Moula-Ka-Chilla fdr
1	HYD C	Bathkammakunta	Ahobilmutt	11KV	II	04.46	06.03	01.17	EL,OL	No Visible Fault (Due to Rain)	-
2		Vittalwadi	Gandhi Kuteer	11KV	II	05.02	07.25	02.23	EL,OL-Rph	Construction Sticks fallen on lines & tree branches fallen on lines at Keshav Memorial School	-
3		Industrial Area	Azamabad I.E	11KV	II	07.40	08.50	01.10	EL,OL-R&Bph	Tree branches on lines on lines at CPM Office	-
4		Asif Nagar	Military	11KV	VII	07.40	08.50	01.10	EL,OL-Rph	Conductor snapped & Tree branches on lines at Piller No.40	-
5		Fever Hosptial	Barkathpura Bus Depot	11KV	II	07.47	09.20	01.33	EL	Jumper cut & Brass Patti B/o at Barkathpura Bus Depot	-