

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		7		7		7			
7	RR(E)	168	403		11		11		11			
8	Hyd	194	1044		8		8		8			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>26</b>	<b>0</b>	<b>26</b>	<b>0</b>	<b>26</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		4		4		4			
2	NLG	144	988		1		1		1			
3	MDK	107	933		2		2		2			
4	SDPT			1	13	1	13	1	13			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>46</b>	<b>1</b>	<b>46</b>	<b>1</b>	<b>46</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 15.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Habsipur	Peddacheekodu	33KV	Siddipet	7:20	8:45	1:25		Tree branch fallen on the 33kv line	Peddacheekodu	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	APPAKPALLY	JAJAPUR	11KV	Narayanpet	13.00	13.15	00.15		Due to 11kv jumper cut at nillugurthy vlg	No
2		MARIKAL	ELIGANDLA	11KV	Narayanpet	08.00	13.40	05.40		11kv jumper cut and fallen on DTR at eligandla vlg	No
3		KONDAPUR	CHARLAPALLY	11KV	Narayanpet	13.20	15.00	01.40		Due to unknown, power supply restored by itself	No
4		MOHAMMADABAD	SHAIKAPALLY	11KV	Narayanpet	5:50	9:21	3:31		Due to 11kv line cut at mukalrabad vlg	No
1	NLG	Jalalpuram	Jalalpuram	11KV	Suryapet	4:10	7:50	3:40	E/L	Conductor snapped	No
1	MDK	Inole	Bayers Corp	11KV	Sangareddy	18:45	19:20	0:35		Jumper cut	No
2		Bollaram - I	Soubagya	11KV	Patancheru	06.50	08.50	02.00		Insulator failure	No
1	SDPT	Musthabad x raod	Kotilingal	11KV	Siddipet	2:00	2:20	0:20		No visible fault	No
2		Thornal	Thornal	11KV	Siddipet	07.00	08.40	01.40		Insulator failed	No
3		Ramancha	Gangapur	11KV	Siddipet	06.15	09.15	03.00		Breakdown due to rain	No
4		Allipur	Allipur	11KV	Siddipet	03.00	15.00	12.00		B/D tree touching Lc no 20147	No
5		Habshipur	habshipur	11KV	Siddipet	07.05	11.00	03.55		Insulator failure	No
6		Kodakandla SS	Rayawaram	11KV	Gajwel	09.50	16.21	06.31		AB Switch Repair	No
7		Singatam SS	Singatam	11KV	Gajwel	08.25	09.55	01.30		Insulator failure	No
8		Markook SS	Markook AGL	11KV	Gajwel	10.40	12.35	01.50		11KV line cut	No
9		Nacharam SS	Nacharam AGL	11KV	Gajwel	06.00	08.00	02.00		Line Phase to Phase	No
10		Nacharam SS	Nacharam AGL	11KV	Gajwel	15.00	16.00	01.00		Line Phase to Phase	No
11		Bandaram SS	Bandaram	11KV	Gajwel	06.54	08.54	02.00		Tree branches fallen on the line	No
12		Pandilla	Potlapally	11KV	Husnabad	13.10	15.55	02.45		Insulator failure	No
13		Guruvannapeta	Guruvannapeta	11KV	Husnabad	01.30	06.30	05.00		Tree branches fallen on the line	No
1	RR N	Bowrampet	Co-ca-cola	11KV	Jeedimetla	17:25	19:00	1:35	EL/OL	Car Dashed the 11kv pole damezed at Nagarau Hotel, Pragathinagar	No
2		Subash Nagar	Bank Colony	11KV	Medchal	19.20	19.50	00.30	EL	11KV Pole damaged at Raghavendra Colony ,Line AB Switch opened at SBI Bank	No
3		Kandalkoya	Anjanna Temple	11KV	Medchal	00.30	01.50	01.20	EL	No visible fault	No
4		Bommarajpet	Ponnal	11KV	Medchal	04.45	14.00	09.15	EL	11KV Pole Damaged and replaced by Lorry at Ponnal Cheruvu	No
5		ICICI	Adama	11KV	Medchal	11.00	13.30	02.30	EL/OL	Tree fallen on the 11KV Line at USP Company	No
6		Shameerpet	Shameerpet	11KV	Medchal	18.45	20.45	02.00	EL	Tree fallen on the 11KV Line at Nuvvula Banda	No
7		Kolthur	Mallannakatta	11KV	Medchal	19:00	20:20	1:20	EL	11KV Pin insulator failed in SS	No
1		Kushaiguda	Kushaiguda	11KV	Sainikpuri	19:00	20:15	1:15		11Kv Pin Insulator damage at Kushaiguda Industry	No
2		Vayupuri	Lakshmipuram	11KV	Sainikpuri	20.20	21.10	00.50		Tree branches fallen on 11Kv line at Anu Tex back side	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
3	RR E	VP Nagar	Officers Colony	11KV	Sainikpuri	18.10	19.50	01.40		11Kv Pin Insulator failed at Eta Nagar	No	
4		Sainikpuri	Eshwarpuri	11KV	Sainikpuri	17.50	22.00	04.10		11Kv Pin Insulator failed at More Super Market	No	
5		Sainikpuri	Kalyan Garden	11KV	Sainikpuri	18.23	20.26	02.03		11Kv Pin Insulator failed at Kalyan Garden	No	
6		Sainikpuri	Saipuri	11KV	Sainikpuri	19.36	20.30	00.54		Tree branches fallen on 11Kv line at Saipuri	No	
7		IICT	Nacharam	11KV	Habsiguda	20.30	21.24	00.54		No visible fault	No	
8		Balaji Nagar	Dental College	11KV	Keesara	10.48	12.26	01.38		Lizard fallen on 11KV line & DTR at Karmika Nagar	No	
9		Pocharam	Jodimetla	11KV	Keesara	18.00	19.15	01.15		11KV Disc failed at Manchavani Colony	No	
10		Cherlapally	Rampally	11KV	Keesara	18.10	19.30	01.20		Tripped on EL due to heavy rain & Gale	No	
11		Cherlapally	Rampally	11KV	Keesara	19:43	21:50	2:07		11KV Pin Insulator failed at Boill Water Plant	No	
1		HYD N	Tirumalagiri	Jupitor Colony	11KV	C-VI	18.00	19.06	01.06	EL	No Visible Fault (due to Rain)	No
2			I.D.P.L	I.E	11KV	VI	18:00	19:45	1:45	EL	No Visible Fault (due to Rain)	No
3	Chinna Thokatta		Old Bowenpally	11KV	VI	18:29	20:45	2:16	OL-Rph	Tree branches fallen on lines at Various Locations	Arranged B/F on 11KV Seetharama Puram & Hasmathpet fdr	
4	Bowenpally		B.B.R Hospital	11KV	VI	18:34	21:23	2:49	All Indication	Cable fault	Arranged B/F on 11KV Raju Colony fdr	
5	H.A.L		Indian Rubber	11KV	VI	18:50	20:30	1:40	All Indication	CT PT fault at Bala Nagar	No	
6	Prashanth Nagar		Sony Complex	11KV	VI	19:00	20:40	1:40	EL,OL	Tree branches fallen on lines at I.I.C Gate	No	
7	Tirumalagiri		Officers Colony	11KV	C-VI	20.56	22.10	01.14	EL	No Visible Fault (due to Rain)	No	
1	HYD C	Z.P.Office	Z.P.Office	11KV	I	18.05	19.22	01.17	EL,OL	DTR Lug & Jumper burnt out at Z.P.Office	No	