

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	12	1	12	1	12			
2	NLG	144	988	2		2		2				
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	13	4	13	4	13	0	0	
	Grand Total	1082	6468	4	16	4	16	4	16	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 17.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanpet	17.55	20.15	02.20	E/L	Tree Fallen on the Line		No
1	NLG	Aitipamula	Aitipamula	33KV	Nalgonda	19.40	21.30	01.50	ELOL	Jumper cut		No
2		Nalgonda	Pazzur	33KV	Nalgonda	18.50	19.50	01.00	ELOL	Alternate taken from 132KV Aitipamula 33KV arlagaddagudem 19:50		Alternate taken from 132KV Aitipamula 33KV arlagaddagudem
1	MDK	Bollaram - I	Town -I	33KV	Patancheru	07.35	09.35	02.00		BD due to Conductor snapped		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 17.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Narwa	Lankal	11KV	Mahabubnagar	17.50	19.00	01.10		11KV line phase to phase at Lankal	-
2		Paspula	Satyaram	11KV	Narayanpet	07.50	10.50	03.00		Breakdown due to 11kv lines got mixed at panchalingala vlg	-
3		KOSGI	Chennaram	11KV	Narayanpet	15.30	16.00	00.30		Breakdown due to heavy gale and wind	-
4		Gundumal	Appaipally	11KV	Narayanpet	09.00	11.00	02.00		Breakdown due to 11kv line cut at balabhadrayyapally vlg	-
5		Vennachedu	Janampally	11KV	Narayanpet	09.53	11.03	01.10		Breakdown due to 11kv line cut at kaplapur vlg	-
6		Vennachedu	Janampally	11KV	Narayanpet	13.20	14.04	00.44		Breakdown due to tree branch fallen on 11kv line cut at janampally vlg	-
7		Kotakonda	Bandagonda	11KV	Narayanpet	14.00	15.30	01.30		Breakdown due to squirrel fallen on 11kv line at ganimoni banda	-
8		Kanukurthy	Kanukurthy	11KV	Narayanpet	16.41	19.00	02.19		Breakdown due to tree branch fallen on 11kv line cut at kanukurthy vlg	-
9		Kyathanpally	Wattugundla	11KV	Narayanpet	16.25	18.39	02.14		Breakdown due to 11kv line cut at kamsanpally vlg	-
10		Dhawada	Mandipally	11KV	Narayanpet	16.30	19.29	02.59		Breakdown due to disc fail at mandipally vlg	-
11		Kondapur	Hanmanpally	11KV	Narayanpet	17.00	19.30	02.30		Breakdown due to heavy gale and wind	-
12		Marikal	P.C.Kunta	11KV	Narayanpet	06.00	08.30	02.30		Breakdown due to agl one bit cut	-
1	MDK	Zaheerabad	Mirzapur B	11KV	Zaheerabad	15.25	18.20	02.55		BD due to Conductor snapped	-
1	RR N	Kandalkoya	Anjanna Temple	11KV	Medchal	02.40	05.05	02.25	BD	Tree Fallen on 11KV Line at Saigeetha	-
2		Kandalkoya	KV Reddy Nagar	11KV	Medchal	11.10	12.00	00.50	BD	11KV Jumper cut and Tree Fallen on 11KV line at Kompally Main Road	-
1	HYD N	Prashanth Nagar	Andhra Jyothi	11KV	VI	02.30	03.35	01.05	OL-Bph	Pin Insulator flash over at R.G.Nagar	-