

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		5		5		5			
2	NLG	144	988		15		15		15			
3	MDK	107	933	3	2	3	2	3	2			
4	SDPT			1	13	1	13	1	13			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	35	4	35	4	35	0	0	
	Grand Total	1082	6468	5	39	5	39	5	39	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 18.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Hadnoor	33KV	Zaheerabad	17.50	19.40	01.50		BD due to Jumper cut	Hadnoor	-
2		Narayankhed	Sirgapur	33KV	Jogipet	07.11	09.30	02.19		BD due to Tree Fallan on line	Sirgapur	-
3		Gummadidala	AFA	33KV	Patancheru	17.51	18.51	01.00		BD due to Tree Fallan on line	AFA	-
1	SDPT	Mustyala	Komuravelly	33KV	Husnabad	07.05	10.20	03.15		Insulator flash over	Komuravelly	-
1	RR N	132KV Chintal	33KV Dulapally	33KV	Medchal	12.14	13.33	01.19	EL	33KV Jumper Cut & Replaced at 33KV Jeedimetla-IV	33KV Dulapally	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Balanagar	Mothiganpur	11KV	Jadcherla	01.12	09.31	08.19		11 KV disk fail near Mothiganpur	-
2		Paspula	SATAYASAI	11KV	Narayanpet	10.50	13.05	02.15		11kv lines got mixed at panchadevpaadu vlg	-
3		Maganoor	WADWAT	11KV	Narayanpet	09.00	10.30	01.30		tree branch fallen on 11kv line cut at wadwat vlg	-
4		DAMARGIDDA	BAPANPALLY	11KV	Narayanpet	16.00	17.00	01.00		tree branch fallen on LT line cut at bapanpally vlg	-
5		KANUKURTHY	KANUKURTHY	11KV	Narayanpet	07.01	07.56	00.55		due to gale and wind	-
1	NLG	Thungathurthy	Velugupally	11KV	Suryapet	03.50	07.30	03.40	E/L	11Kv Insulator failed	-
2		Bollepally	Bollepally	11KV	Bhongir	02.00	08.35	06.35	E/L	11kv Solid core DTR Insulator failed at Vantro well near Bollepally (V)	-
3		Azeempet	Kanchanapally	11KV	Bhongir	19.30	06.00	10.30	E/L	11kv Insulator failed near Kanchanapally (V)	-
4		Jununthala	Palvai	11KV	Devarakonda	07.45	11.50	04.05	E/L	11Kv Jumper Cut	-
5		Teeded	K.Gowraram	11KV	Devarakonda	12.15	14.22	02.07	E/L	11 Kv Conductor Snapped	-
6		Ghanpur	Kodandapuram	11KV	Devarakonda	12.00	13.38	01.38	E/L	11 Kv Insulator failed	-
7		Singarajpally	Vera Boynpally	11KV	Devarakonda	11.12	15.02	03.50	E/L	11Kv Line Tached the LT Line (HT/LT)	-
8		Settipalem	Vemulapally AGL	11KV	Miryalguda	09.00	13.30	04.30	E/L	11Kv Jumper cut and fallen on Cross arm	-
9		Kattangur	Bollepally	11KV	Nalgonda	01.00	10.20	09.20	E/L	11KV line cut	-
10		Kattangur	Mallaram	11KV	Nalgonda	03.30	10.00	06.30	E/L	Thonda died on 11KV died	-
11		Palem	Bopparam	11KV	Nalgonda	08.20	10.24	02.04	E/L	11KV line melting	-
12		Palem	Ogodu	11KV	Nalgonda	15.10	16.30	01.20	E/L	Tree fallen on 11KV line	-
13		Palem	Palem	11KV	Nalgonda	11.50	16.13	04.23	E/L	11KV jumper cut	-
14		Thurkapally	Thurkapally	11KV	Nalgonda	12.00	13.32	01.32	E/L	AB switch open	-
15		Kethepally	Korlapahad	11KV	Nalgonda	12.45	15.00	02.15	E/L	11KV line cut	-
1	MDK	Inole	Bayers Corp	11KV	Patancheru	18.20	22.00	03.40		BD due to 11KV line cut	-
2		Anrich Bollaram	Town-II	11KV	Patancheru	14.20	15.20	01.00		BD due to Brass Patti Cut	-
1	SDPT	MULUGU	NAGIREDDYPALLI	11KV	Gajwel	14.50	17.00	02.10		11KV DISC FAIL	-
2			MULUGU TOWN	11KV	Gajwel	18.00	19.10	01.10		11KV POLE DAMAGED	-
3		SITARAMPALLY	VELUR	11KV	Gajwel	17.50	19.05	01.15		SNAKE FELL OVER 11KV LINE	-
4		RAIPOLE	THIMMAKAPALLY AGL	11KV	Gajwel	13.40	15.00	01.20		INSULATOR FAILED	-
5		DOMMATA	SURAMPALLY	11KV	Gajwel	14.50	15.37	00.47		JUMPER CUT	-
6			INDUSTRIAL	11KV	Gajwel	18.30	19.30	01.00		11KV LINE CUT	-
7		Husnabad-II	Malapally	11KV	Husnabad	13.50	14.20	00.30		Tree branch fallen on the line	-
8		Potharam	Potharam Town	11KV	Husnabad	13.00	13.50	00.50		Jumper Cut	-
9		Gouravelly	Gouravelly Rural	11KV	Husnabad	12.25	14.42	02.17		Tree branch fallen on the line	-
10		Gouravelly	Gubbadi	11KV	Husnabad	09.25	09.55	00.30		Insulator fail	-
11		Komuravelli	Komuravelli AGL	11KV	Husnabad	13.56	15.05	01.09		Tree branch fallen on the line	-
12		Chityala	Dommata	11KV	Husnabad	13.15	17.45	04.30		Disc Fail	-
13		Bekkal	Bekkal Town	11KV	Husnabad	15.45	16.25	00.40		LT/HT Problem	-
1	RR N	Shameerpet	Nalsar	11KV	Medchal	11.05	11.35	00.30	EL	11KV Line AB Switch Opened at Bus Stop(11KV Line Phase to Phase at Hanuman Temple)	-
1	HYD N	Tirumalagiri	Srinagar Colony	11KV	C-VI	19.20	20.45	01.25	EL,OL-Rph	Plastic cover fallen on lines at Pendent Colony	-----
2		Begumpet	Play Ground	11KV	IV	19.00	21.30	02.30	A/R tripped	Cable fault	Arranged B/F on 11KV MCH Market fdr
1	HYD C	Lumbini Park	Lumbini Park	11KV	I	08.23	09.50	01.27	EL	No Visible Fault	Arranged B/F on 11KV NTR Marg feeder