

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>6</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1		1		1				
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>1</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 18.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Jharasangam	33KV	Zaheerabad	14.55	17.40	02.45		B/D Due to Conductor Snapped	Jharasangam	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 18.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	MARIKAL	ELIGANDLA	11KV	Narayanpet	15.50	18.41	02.51		Tree branch fallen on 11kv line cut at eligandla vlg	-
1	NLG	Palem	Ogodu	11KV	Nalgonda	10.00	11.30	01.30	E/L	11KV jumper cut	-
2		Kattangur	Erasanigudem	11KV	Naigonda	08.10	09.55	01.45	E/L	Tree fallen on 11KV line	-
3		Balemla	Balemla	11KV	Suryapet	09.00	11.38	02.38	E/L	Conductor snaped	-
4		T Singaram	T Singaram	11KV	Suryapet	08.00	11.02	03.02	E/L	Insulator failed	-
5		Raigir	Raigir Agl	11KV	Bhongir	02.00	07.55	05.55	E/L	11 kv Insulator failed Raigir village out side ,	-
1	SDP	MARKOOK	BHAVANANDAPUR	11KV	GAJWEL	08.15	09.05	00.50		1-Ph DTR BURNT	-
2		WARDARAJPUR	SHIVAR VENKATAPUR	11KV	GAJWEL	09.50	10.45	00.55		11KV LINE CUT	-
3		GUDIKANDULA	GUDIKANDULA AGL	11KV	GAJWEL	14.15	16.15	02.00		11KV LINE CUT	-
4		Gandipally	Gandipally Rural	11KV	HUSNABAD	02.50	08.00	05.10		Insulator Burst	-
1	RR N	Dulapally	IDA-II	11KV	Medchal	05.20	06.36	01.16	EL	11KV Cable endkit Failed at Chowdary Kanta(Cable removed )	-
2		Gowdavelly	IDA Gowdavelly	11KV	Medchal	06.25	07.15	00.50	EL/OL	Tree Fallen on 11KV at Basaragadi Road	-
3		Kandalkoya	Kandalkoya	11KV	Medchal	10.10	10.45	00.35	EL	11KV Tree Branches fallen on 11KV Line at Cheruvukatta	-
1	RR E	Narapally	Parvathapur	11KV	Keesara	10.25	11.55	01.30		11KV HG Fuse Insulator failed at Nandana Vanam	-
1	HYD S	Miralam	Shaik E Masjid	11KV	III	04.02	06.35	02.33	EL,OL	HT top Jumper cut & Snapped HT line at Diamond Function Hall	-
1	HYD C	Mothi Mahal	M.D Lines	11KV	VII	10.45	12.18	01.33	EL	Pin Insulator flash over at Jamal Kunta Katta	-