

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988	1	5	1	5	1	5			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	8	1	8	1	8	0	0	
	Grand Total	1082	6468	1	15	1	15	1	15	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 21.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Shaligouraram	Nakrekal	33KV	Nalgonda	09.06	14.10	05.04		11KV conductor snapped near 33/11KV Akaram SS		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 21.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mogalmadka	Mogalmadka	11KV	Narayanpet	10.00	12.10	02.10		11KV Jumper cut and fallen on DTR at Suddabanda Thanda	-
2		Appakpally	Appi Reddypally	11KV	Narayanpet	10.09	12.38	02.29		Tree Branch Fallen on 11KV Line at Appi Reddypally(V)	-
1	NLG	Koppole	Bheemaram	11KV	Nalgonda	01.30	07.30	06.00	EL	11KV line cut	-
2		Madgulapally	Indugula	11KV	Nalgonda	12.05	13.50	01.45	EL	11KV jumper cut	-
3		Annaram	Annaram	11KV	Suryapet	05.50	09.20	03.30	EL	Insulator failed	-
4		Varkatpally	Gokaram	11KV	Choutuppal	08.41	09.58	01.17	EL	100kva DTR Failed near Gokaram Market	-
5		Voligonda	Nagaram	11KV	Choutuppal	09.30	12.20	02.50	EL	3no's 11kv Poles Damedged near Nagaram Village Out Side	-
1	SDPT	Chittapur	Mothey	11KV	Siddipet	10.30	15.23	04.53		B/D 11 KV wire cut Icno. 16083	-
1	RR N	Dulapally	Steelcity	11KV	Medchal	09.07	09.55	00.48	BD	11KV Line AB Switch Opened at Sri Sai Balaji Traders(No Fault)	-
1	RR E	Mallapur 2	Surya nagar	11KV	Habsiguda	06.46	08.00	01.14		T/F Brash patti cut at Chandiya nagar	-
2		Vasanthapuri	BJR Nagar	11KV	Sainikpuri	21.38	22.59	01.21		Chameleon fallen on 11Kv two jumers cut at Ragavendra Swamy Temple & Uppalamma Temple (AE/OP)	-
3		Aushapur	Madharam	11KV	Keesara	16.00	16.40	00.40		11KV Jumper cut at Madharam village	-
1	HYD S	Kandikal Gate	Rakshapuram	11KV	Charminar	21.30	23.52	02.22	EL,OL-Rph	4No. Poles felldown near Pariwar Town Ship due to Lorry ramed to Poles	Arranged B/F on 11KV Riyasath Nagar feeder
2		Kandikal Gate	Phool Bagh	11KV	Charminar	23.10	00.25	01.15	EL,OL-Rph	Sparking line AB Switch at Paradise Function Hall	-
1	HYD C	Bathkammakunta	Ayyappa Temple	11KV	Azamabad	01.39	03.10	01.31	EL,OL	Disc Insulvator flash over at Water Works	-