

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	1	1	1	1	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		6		6		6			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	1	10	1	10	1	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	HYD S	132kV Imlibun	Khilwath	33KV	Falaknuma	08.52	09.00	00.08	EL+OL	Tripped on EL OLBph due to old straight through joint kit failed at 33/11KV Salarjung SS. 1No straight through joint kit provided. Idle feeder charged stood ok at 17:25Hrs.	Khilwath	Alternate supply arranged

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	MARIKAL	TILERU	11KV	NARAYANPET	00.05	01.00	00.55		11kv Jumper cut near tileru vlg	No
1	NLG	Aitipamul	Ch.Annaram	11KV	Nalgonda	2:30	6:05	3:35	EL	11KV line cut	No
2		Pamanagundal	A.P.Lingotam	11KV	Nalgonda	01.14	06.00	04.46	EL	11KV line cut	No
3		Kopple	Bheemaram	11KV	Nalgonda	08.10	10.30	02.20	EL	Jumper Cut	No
4		Palem	Ogodu	11KV	Nalgonda	08.45	13.50	05.05	EL	11KV jumper cut	No
5		Dirsincherla	Town-2	11KV	Huzurnagar	06.30	08.00	01.30	EL	11 KV LINE SNAPPED	No
6		Addagudur	Dharmaram	11KV	Bhongiri	12:20	13:10	0:50	EL/OL	11KV Pole Damaged near Laxmidavi kaluva	No
1	MDK	Bollaram - I	Vipla	11KV	Patancheru	6:50	8:45	1:55		Bird fallen on the line	No
1	SDPT	KOKKONDA SS	SINGANNAGUDA	11KV	Gajwel	15:25	17:20	1:55		11KV Line touched to the tipper lorry	No
1	RR E	Moula ali	Kailasagiri	11KV	Sainikpuri	16:20	17:37	1:17		11KV line Snapped at Mangapuram near Vasundhra College	No