

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		10		10		10			
7	RR(E)	168	403		9		9		9			
8	Hyd	194	1044		28		28		28			
	Total	606	3055	0	47	0	47	0	47	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		16		16		16			
3	MDK	107	933		3		3		3			
4	SDPT			3	12	3	12	3	12			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	31	4	31	4	31	0	0	
	Grand Total	1082	6468	4	78	4	78	4	78	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 27.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Chinnamaroor	Kalwarala	33KV	Wanaparthi	10.15	16.05	05.50	E/L	33KV Insulator Replaced at Mysamma Mitta	Kalwarala	-
1	SDPT	Duddeda	Medhinipur	33KV	Gajwel	17.05	03.10	10.05		BD (Heavy rain & Insulator Failure)	Medhinipur	-
2		Habsipur	Pothareddypet	33KV	Siddipet	17.55	20.20	02.25		B/D (33 Kv Line works)	Pothareddypet	-
3		Husnabad	Katkur	33KV	Husnabad	02.45	11.00	08.15		BD (Rain and wind)	Katkur	-
1	RR N	132KV LGM Pet	33KV MN Park	33KV	Medchal	03.48	07.43	03.55	BD	No visible Fault	33KV MN Park	-
2		132KV Medchal	33KV Kandlakoya	33KV	Medchal	14.25	15.50	01.25	BD	No visible Fault	33KV Kandlakoya	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 27.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Arlagaddagudem	Thatikal	11kv	Nalgonda	14.30	16.00	01.30	EL	Jumper cut	-
2		Palem	Ogodu	11kv	Nalgonda	10.00	11.00	01.00	EL	Insulator failed	
3		Kudakuda	MG Nagar Thanda	11kv	Suryapet	11.40	14.38	02.58	EL	Conductor snapped	
4		Penpahd	Dubbathanda	11kv	Suryapet	12.00	15.30	03.30	EL	Disk failed	
5		Kasarabadha	Kasarabadha	11kv	Suryapet	04.35	08.00	03.25	EL	Insulator failed	
6		Raigir	Raigir Indl	11kv	Bhongir	06.30	08.00	01.30	EL/OL	11 kv Insulator failed near Raigir village	
7		Maryala	Wadaparthi	11kv	Bhongir	22.50	06.00	07.10	EL/OL	11 kv Insulator failed near pilliguntla thanda .	
8		Mothkur	Kondagadapa	11kv	Bhongir	02.45	07.50	05.05	EL/OL	11 kv Line snapped at SS-1 Kondagadapa village	
9		Mothkur	Mothkur rural	11kv	Bhongir	06.35	09.45	03.10	EL/OL	11 kv Line snapped at SS-1 Kondagadapa village	
10		Azeempet	Kanchanapally	11kv	Bhongir	07.40	09.20	01.40	EL/OL	11 KV Line snapped near Boddugudem village	
11		Addagudur	Kotamarthy	11kv	Bhongir	06.00	08.35	02.35	EL/OL	11 kv Insulator failed near Chirragudur village	
12		Mandollagudem	Nelapatla	11kv	Choutuppal	05.20	08.23	03.03	EL/OL	11 kv Insulator failed near Nelapatla village	
13		D.Nagaram	Pipalpahad 24	11kv	Choutuppal	07.50	10.35	02.45	EL/OL	11KV Insulator Failed near Pipalpad Village	-
14		Malkapur	Tooprampet Indl	11kv	Choutuppal	05.30	09.55	04.25	EL/OL	11 kv Insulator failed near Tooprampet village	-
15		Vologonda	Mandapuram	11kv	Choutuppal	23.05	08.25	09.20	EL/OL	11 kv Line snapped near Akkampally village.	-
16		Vemulakonda	Vemulakonda	11kv	Choutuppal	01.45	08.20	06.35	EL/OL	11 kv Line snapped near Vemulakonda village out side	-
1	MDK	Inole	Peddakanjarla	11kv	Sangareddy	06.00	12.00	06.00		B/D Due to tree Branch fallen on the line and Insulator Failure	-
2		Patancheru Town	Shanthinagar	11kv	Patancheru	14.55	15.55	01.00		B/D Due tree Branch fallen on the line	-
3		Kistareddypet	Industrial	11kv	Patancheru	14.30	18.00	03.30		B/D Due to Insulator Failure and Jumper Cut	-
1	SDPT	Nangnoor	Akkanapally	11kv	Siddipet	08.30	09.10	00.40		B/D Tree brach fall on the line	-
2		Raghavapur	Raorukula	11kv	Siddipet	14.30	15.29	00.59		B/D for Disk fail LC.No.19096	
3		Raghavapur	Peddalingareddypally	11kv	Siddipet	00.00	09.35	09.35		B/D Insulater fail & LC.No.19095	
4		Laxmidevipally	Ibrahimpur	11kv	Siddipet	06.00	09.30	03.30		B/D insulator failure	
5		Narayanraopet	Beerapagudi	11kv	Siddipet	09.25	13.08	03.43		B/D Tree brach fall on the line Lc.No.18360	
6		Ramancha	Gangapur	11kv	Siddipet	01.55	10.10	08.15		B/D Tree brach fall on the line	
7		Narsapur	Lingareddy Pally	11kv	Siddipet	00.00	09.00	09.00		B/D Insulater fail & LC.No.24369	
8		Kondamraipally	Gatlamalyal	11kv	Siddipet	03.15	07.45	04.30		B/D Tree brach fall on the line	
9		Pandilla	Pandilla Rural	11kv	Husnabad	12.45	13.30	00.45		Jumper cutting	
10		Komuravelly	Kistampet	11kv	Husnabad	17.30	20.25	02.55		Disc fail	
11		Arjunpatla	Arjunpatla AGL	11kv	Husnabad	01.10	09.50	08.40		DTR Fualt	
12		Arjunpatla	kamalaipally	11kv	Husnabad	01.20	07.52	06.32		DTR Fualt	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jagathgirigutta	Shiridihills	11KV	Medchal	14.50	15.40	00.50	BD	Cloth fallen on the 11KV Line at Boodevi hills Road No 6	-
2		Subhash Nagar	Jairam Nagar	11KV	Medchal	14.13	15.10	00.57	BD	No Fault	-
3		Kompally	Aparna	11KV	Medchal	14.03	15.15	01.12	BD	No Fault	-
4		Petbasheerabad	Sanmon Belmor	11KV	Medchal	14.00	16.10	02.10	BD	11KV Pin Insulator failed Near SS	-
5		Kompally	Aparna	11KV	Medchal	17.40	19.15	01.35	BD	11KV Pin Insulator failed at Aparna Gate	-
6		Devarayamjal	DMC	11KV	Medchal	05.30	07.15	01.45	BD	11KV Conductor snapped and replaced at Arkalaguda Village	-
7		Devarayamjal	Pothaipally	11KV	Medchal	05.50	07.10	01.20	BD	No Fault	-
8		Medchal	Checkpost	11KV	Medchal	04.40	05.55	01.15	BD	11KV Pin Insulator failed at Checkpost	-
9		Medchal	Victory	11KV	Medchal	04.25	06.10	01.45	BD	2No 11KV Pin Insulators failed at Sumangali Company	-
10		Nuthankal	Bharathi	11KV	Medchal	19.20	21.50	02.30	BD	11KV Pin Insulator and Disc failed at Cheruvukatta	-
1	RR E	NGRI	Kalyanpuri	11KV	Habsiguda	15.20	17.08	01.48		11KV jumper cut & Tree branches fallen on 11kv line at Azmad nagar	-
2		Idauppall	LN nagar	11KV	Habsiguda	14.30	16.20	01.50		Insulator fail at Janapriya appt	-
3		Boduppall	Anjaneey nagar	11KV	Habsiguda	16.16	17.54	01.38		Insulator fail at Sudhakunnta	-
4		Kushaiguda	Saibaba Temple	11KV	Sainikpuri	03.20	04.25	01.05		Ground petrolling done but no visible fault found due to AB Switch Open at ECIL Chourastha	-
5		Malkajgiri	Uttam Nagar	11KV	Sainikpuri	14.26	15.34	01.08		Tree branches fallen and removed from 11kv line at Goutham Nagar Due to Heavy Rain	-
6		VP Nagar	Brundhavan Colony	11KV	Sainikpuri	15.47	16.50	01.03		Tree branches fallen on 11KV line at Brundhavan Colony	-
7		Moula ali	Kailasagiri	11KV	Sainikpuri	14.10	18.05	03.55		Tree branches fallen on 11KV line at Yadav Reddy T/F and 11KV Disk failed at Navodhaya Nagar near Bondal Gadd and Due to Heavy Rain	-
8		Yapral	Pradhampuri	11KV	Sainikpuri	17.40	19.14	01.34		11KV Pin Insulator failed at Bhavani Heights	-
9		Narapally	P.Singaram	11KV	Keesara	05.05	05.35	00.30		11KV AB switch repair at Chowdariguda	-
1	HYD N	Bansilalpet	N.T.P.C.	11KV	V	14.40	15.50	01.10	EL,OL-Bph	HG fuse blowoff at N.T.P.C.	----
2		Addagutta	Addagutta	11KV	V	15.20	16.30	01.10	EL	No Visible Fault (Due to Rain)	----
3		Lalaguda	Tarnaka	11KV	V	15.15	17.15	02.00	EL,OL-Rph	Cable fault at Balaji Apts	Partial fdr charged & remaining loads added on 11KV Deccan fdr
4		Gymkhana	Vikrampuri	11KV	C-VI	17.50	19.15	01.25	EL,OL-Bph	Post type Insulator flash over at SS	----
5		Green Lands	Hindu	11KV	IV	17.45	19.20	01.35	EL,OL-Rph	UG Cable fault	Partial fdr charged & remaining loads added on 11KV Ameerpet fdr
1	HYD S	Panjasha	Gowlipura	11KV	III	05.10	06.15	01.05	EL,OL	Kite Stick fallen on lines at Mekala Mandi	----
2		Panjasha	Sulthan Shahi	11KV	III	05.18	06.35	01.17	EL	No Visible Fault (Due to Rain)	----
3		Kandikal Gate	Ashamabad	11KV	III	06.15	07.50	01.35	EL	2No. HT Jumpers cut at Kabestan	----
4		Santosh Nagar	Chandra Huts	11KV	VIII	15.05	16.25	01.20	EL	No Visible Fault (Due to Rain)	----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD C	Gudimalkapur	Amba Garden	11KV	VII	04.12	05.52	01.40	OL-Rph	No Visible Fault (Due to Rain)	-----
2		I.T.I Mallepally	Indira Nagar	11KV	VII	05.05	06.40	01.35	EL	Cable fault at Feerzodi Masjid	-----
3		Chilkaiguda	Bholakpur	11KV	I	05.10	07.15	02.05	EL,OL-Rph	3No. HG fuse blown & Foreign material fallen on lines at Musheerabad X-Rd	Arranged B/F on 11KV Kawadiguda feeder
4		Chilkaiguda	Musheerabad	11KV	I	05.10	07.35	02.25	EL,OL-Rph	Foreign material fallen on lines at Musheerabad X-Rd	Arranged B/F on 11KV Post Office feeder
5		Golconda	Vinobha Nagar	11KV	VII	05.55	07.20	01.25	EL	DTR fault at Glass Factory O.U.Colony	-----
6		Golconda	Vinobha Nagar	11KV	VII	14.40	16.20	01.40	EL	No Visible Fault (Due to Rain)	-----
7		Nizam College	Galaxy Hotel	11KV	I	14.45	16.35	01.50	EL,OL-Rph	Line AB Switch Insulator flash over at Rukmini Apts	-----
8		Nizam College	Big Bazar	11KV	I	15.42	16.49	01.07	EL,OL-Rph	Tree branches fallen on lines & Jumper cut at Jaya International Hotel	-----
9		Industrial Area	Azamabad I.E.	11KV	II	15.44	17.10	01.26	EL,OL	Tree branches fallen on lines at Vidya Nagar Post Office	-----
10		Chilkaiguda	Golconda X Road	11KV	II	16.06	17.38	01.32	EL,OL-Bph	No Visible Fault (Due to Rain)	-----
11		Bathamma Kunta	Ahobilmutt	11KV	II	14.28	17.47	03.19	EL,OL,	Pin Insulator flash over at Ahobilmutt Temple	-----
12		Nizam College	Galaxy Hotel	11KV	I	16.48	18.16	01.28	EL,OL-Rph	Tree branches fallen on lines, 2Nos. HT Lines snapped & 2Nos. Pin Insulators flash over at Madina Galli	-----
13		Jawahar Nagar	Ashok Nagar	11KV	I	15.25	18.15	02.50	EL,OL-Rph	Tree branches fallen on lines at Jana Priya & Pin Insulator at Ashok Nagar	-----
14		Indira Park	Ambedkar Nagar	11KV	I	16.30	18.20	01.50	EL,OL	2Nos. HG fuses blowoff at Dikshith Towers	-----
15		Narayanguda	Narayanguda	11KV	II	18.52	20.00	01.08	EL	Tree branches fallen on lines at Sundaraiah Park	-----
16		Chilkaiguda	Golconda X Road	11KV	II	18.34	20.18	01.44	OL-R&Bph	No Visible Fault (Due to Rain)	-----
17		Industrial Area	RTC X Road	11KV	II	15.05	20.40	05.35	EL,OL-Rph	Pin Insulator flash over at 1st line AB Switch & Tree branches fallen on lines at Fire Station	-----
18		Chilkaiguda	Parsi Gutta	11KV	II	18.57	21.33	02.36	OL-Bph	Pin Insulator flash over at Hanuman Temple	-----
19		Hussain Sagar	NTR Marg	11KV	I	21.38	22.40	01.02	All Indication	11KV Breaker Limb flash over at SS	Arranged B/F on 11KV Governer Banglaw fdr