

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2		2		2				
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	2	9	2	9	2	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		4		4		4			
3	MDK	107	933		1		1		1			
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	11	1	11	1	11	0	0	
	Grand Total	1082	6468	3	20	3	20	3	20	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 29.06.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Angadikistapur	Wardarajpur	33KV	Gajwel	14.40	15.10	00.30		Tripped on EL		-
1	RR N	132KV Medchal	33KV Petbasheerabad	33KV	Medchal	21.06	21.50	00.44		Back feeding arranged from 33KV Jeedimetla -III		-
2		132KV Medchal	33KV Steel Mill	33KV	Medchal	15.13	15.46	00.33		R Phase CT Clamp Blast at Sarvottam Company		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 29.06.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Town	11KV	Jadcherla	09.55	11.30	01.35		11KV Wire cut near HBL Company Side	-
2		Mohammedabad	Shaikpally	11KV	Narayanpet	10.30	15.10	04.40		11KV Line cut at Mogalrabad AGL	-
3		Kondapur	Kistapur	11KV	Narayanpet	02.00	07.00	05.00		11KV Insulator fail at Kistapur(V)	-
1	NLG	Angadipeta	Rangtareddy Gudem	11KV	Devarakonda	11.40	14.00	02.20	E/L	11 KV Jumper cuut	-
2		Anneparthy	Anneparthy	11KV	Nalgonda	06.25	08.15	01.50	E/L	11 KV Jumper cuut	-
3		Munagala	Barakathgudem	11KV	Huzurnagar	05.00	07.45	02.45	EL	11 KV LINE SNAPPED	-
4		Ravipahad	Appanagudem	11KV	Huzurnagar	05.40	07.00	01.20	EL	11 KV Jumper cut	-
1	MDK	Patancheru Town	Town Indl.	11KV	Patancheru	05.05	05.50	00.45		11 KV Jumper cut	-
1	SDPT	Raghvapur	Bachaipally	11KV	Siddipet	10.40	15.50	05.10		B/D for Due to bird LC No.17406	-
2		Mustyal	Gadithota	11KV	Husnabad	08.20	14.20	22.40		LT LINE SNAPPED	-
3		Akunoor	Rampoor	11KV	Husnabad	16.40	18.30	11.10		bird died on line	-
1	RR E	Sainikpuri	Sainikpuri	11KV	Sainikpuri	18.00	18.50	00.50		11KV Pin Insulator failed at Sainikpuri (AE)	-
2		Vayupuri	RKH Colony	11KV	Sainikpuri	16.38	18.56	02.18		11Kv Disk failed at Astha Lakshmi Temple (LM Narshima)	-
3		Sainikpuri	Eshwarapuri	11KV	Sainikpuri	20.10	21.00	00.50		11KV Pin Insulator failed at Classic Enclave (AE)	-
4		Malkajgiri	Dayand Nagar	11KV	Sainikpuri	21.15	22.30	01.15		Tree fallen on 11KV line at RK Nagar and Due to Heavy Rain (Artisian Kumar)	-
1	HYD N	Monda Market	Gandhi Nagar PS	11KV	V	18.45	20.40	01.55	EL,OL-Rph	No Visible Fault	-
1	HYD S	Exhibition	Seetharampet	11KV	IX	12.44	14.18	01.34	EL	No Visible Fault	Arranged B/F on 11KV Hindi Nagar fdr
1	HYD C	Industrial Area	Azamabad I.E	11KV	II	14.55	16.19	01.24	EL	Pin Insulator flash over at Gayatri Apts	-
2		Hussain Sagar	Lake Plaza	11KV	I	16.27	17.55	01.28	EL,OL-Rph	AB Cable melt and touch to Channel at Bakery	-
3		Bathkamma Kunta	Saibaba Temple	11KV	II	17.21	18.34	01.13	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Ahobilmutt fdr