

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	6	2	6	2	6			
2	NLG	144	988		2		2		2			
3	MDK	107	933		1		1		1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	2	15	2	15	2	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Maddur	33KV	Narayanapet	10.35	11.30	00.55	E/L	Pin Baining Failed	Maddur	-
2		Marikal	Koukuntla	33KV	Narayanapet	07.10	12.25	05.15	O/L	Jumpering Work near Marikal	Koukuntla	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Chinthaldinne	11KV	Narayanapet	07.30	08.25	00.55		Breakdown Due to 11KV Disc fail at Nagireddypally vg	-
2		Pallerla	Parsapur	11KV	Narayanapet	06.55	07.58	01.03		Breakdown Due to 11KV Disc fail & jumper cut at Pallerla vg	-
3		Venneched	Janampally	11KV	Narayanapet	08.00	10.21	02.21		Breakdown Due to 11KV Jumper	-
4		Mohammadabad	Annareddypally	11KV	Narayanapet	09.30	10.30	01.00		Breakdown Due to 11KV Jumper at Annareddypally vg	-
5		Kolpur	PARAMONDODDI	11KV	Narayanapet	02.00	06.00	04.00		Breakdown Due to 11Kv cond cut at pujanoor vlg	-
6		MARIKAL	PC KUNTA	11KV	Narayanapet	14.10	14.25	00.15		BREAKDOWN DECLARED, LATER IT WITHSTAND BY ITSELF	-
1	NLG	Ponugodu	Kothaguden	11KV	Huzurnagar	06.15	08.30	02.15	EL	11 KV LINE SNAPPED	-
2		Voligonda	Voligonda town	11KV	Choutuppal	00.40	07.30	06.50	EL/OL	Lorry accident 11 kv Pole dammage at Hero honda showroom Voligonda town	-
1	MDK	Inole	Sathyasai	11KV	Patancheru	05.12	10.38	05.26		B/D due to Tree branches fallen on the line	-
1	SDP	Nangnoor	Nangnoor	11KV	Siddipet	08.40	09.35	00.55		B/D Bush Problem Lcno.23573	-
2		Dharamjipetq	Lachapet	11KV	Siddipet	00.00	07.00	07.00		B/D Tree Braches problem lcno. 3495	-
3		Gandipally	Gandipally	11KV	Husnabad	07.05	08.40	01.35		Line cut	-
4		Komuravelli	Komuravelli Agl	11KV	Husnabad	16.25	18.00	01.35		3-Ph Break down	-
1	RR N	Nuthankal	Lingapur	11KV	Medchal	16.20	17.25	01.05	BD	Bird fallen on the 11KV Line near Lingapur	-
1	HYD C	Erramanzil	Red Rose	11KV	I	15.04	16.10	01.06	EL	Pin Insulator flash over & B/O HG fuse at RTO Office	-