

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	1	2	1	2	1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		4		4		4			
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 05.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	132KV Medchal	33KV Aliabad	33KV	Medchal	15.55	16.34	00.39	BD	No Fault		-
2		132KV Medchal	33KV Keshavaram	33KV	Medchal	15.55	17.15	01.20	BD	Tree fallen on 33KV Line at 220KVA Medchal SS		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 05.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gudeballore	Khandoodi	11KV	Narayanpet	10.00	11.00	01.00		Break Down Due to 11K cond cut at khandoddi vlg	-
2		Kolpur	Paramondoddi	11KV	Narayanpet	04.00	07.10	03.10		Break Down Due to 11K cond cut at mudumal vlg	-
3		Sarjkanpet	Hakeempet	11KV	Narayanpet	07.30	08.30	01.00		Break Down Due to tree branch fallen on 11kv line near hakeempet vlg	-
4		Vennachedu	Janampally	11KV	Narayanpet	07.30	09.10	01.40		Break Down Due to 11KV disc failure at janampally vlg	-
1	NLG	Mandollagudem	Nelapatla	11KV	Choutuppal	06.46	07.45	00.59	E/L	25kva DTR Post off insulator failed at Dora. Shankaraiah well near Nelapatla (V)	-
1	SDPT	Thigul SS	Thigul AGL LC: 4643	11KV	Gajwel	11.52	12.35	00.43		11 KV line Cut	-
2		Gowraram SS	Pamulaparthi	11KV	Gajwel	09.10	11.18	02.08		11 KV line Cut	-
3		Gowraram SS	Gowraram town II	11KV	Gajwel	13.35	14.20	00.45		Tree Branch Fallen	-
4		Mulugu SS	All Feeders	11KV	Gajwel	11.20	13.30	02.10		Shut Down	-
5		Mubaraspur Ss	Thirmalapur LC: 4584	11KV	Gajwel	19.34	19.38	00.04		11 KV line cut	-
6		Thadkapally	Thadkapally	11KV	Siddipet	19.35	08.35	13.00		B/D (11 KV Wire cutting )	-
7		Gagillapur	Vallampatla	11KV	Husnabad	07.26	08.45	01.19		DTR fault	-
8		Bekkal	Kondapur	11KV	Husnabad	10.00	10.30	00.30		fallen on tree	-
1	RR N	Jeedimetla-I	Shapurnagar	11KV	Jeedimetla	14.15	15.30	01.15	EL/OL	AB Cable Failed at Kalavathi nagar	-
1	HYD S	E.N.T	Rang Mahal	11KV	Begumbazar	12.16	13.25	01.09	EL,OL	No Visible Fault	Arranged B/F on 11KV Sultan Bazar feeder