

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		1		1		1			
3	MDK	107	933		1		1		1			
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 08.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR		NIL				NIL					-
2	NLG		NIL				NIL					-
3	MDK		NIL				NIL					-
4	RR S		NIL				NIL					-
5	RR N		NIL				NIL					-
6	RR E		NIL				NIL					-
7	HYD		NIL				NIL					-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 08.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Paladugu	Duppally	11KV	Bhongir	23.21	08.55	09.34	EL	11kv Line snapped near Bodda banda Village	-
1	MDK	Bollaram - II	Kottam	11KV	Patancheru	04.10	05.30	01.20		B/D Due to tree branch fallen on the line	-
1	SDPT	Guruvannapet	Guruvannapet	11KV	Husnabad	11.05	11.30	00.25		Bird fallen on line	-
1	RR N	HMT	Ganesh Nagar	11KV	Medchal	18.55	19.30	00.35	BD	No Fault	-
1	HYD N	Kalyan Nagar	Vengal Rao Nagar	11KV	X	23.40	01.15	01.35	E,OL-Rph	No Visible Fault	(00:05 Hrs) partial feeder charged & Arranged B/F on 11KV Vishwa Bharathi feeder