

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		1		1		1			
3	MDK	107	933	1		1		1				
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	6	1	6	1	6	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Gummadidala	GPSS-2	33KV	Patancheru	02.20	04.50	02.30		BD due to Jumper cut		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 17.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gudeballore	Satya Sai & Lift	11KV	Narayanpet	08.20	10.40	02.20		11KV conductor cut at crusher	-
2		Makthal	Kahanpur	11KV	Narayanpet	13.30	16.30	03.00		Jumper cut and Fallen on 11KV Tapping cross at Ersanpally(V)	-
1	NLG	Velugupally	Keshavapuram	11KV	Suryapet	02.40	06.30	03.50	E/L	11Kv Jumper cut	-
1	SDPT	Dharmaram	Potharam(J)	11KV	Husnabad	09.15	09.55	00.40		Tree fallen in line	-
2		Gagillapur	Vallampatla	11KV	Husnabad	08.25	08.55	00.30		Tree fallen in line	-
3		Pregnapur SS	Akkaram LC: 19929 Nagaraju CL	11KV	Gajwel	11.08	11.37	00.29		Cunductor cut	-
1	RR N	Jeedimetla -II	Uttam Biscuti	11KV	Jeedimetla	00.12	01.25	01.13	OL	11kv AB cable Failure at Gati Transport	-
2		Sampanbole	Jaganguda	11KV	Medchal	13.30	15.05	01.35	EL	Tree Branch fallen on the 11KV Line at Jaganguda Village	-