

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988									
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>1</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>1</b>	<b>11</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 18.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	16.00	18.25	02.25		AB Switch Open at Nakkalapally & Peddakarpamula Supply Stood OK	Peddakothapally	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 18.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Bhogaram	11KV	Narayanpet	08.45	11.00	02.15		11KV Conductor cut at Near Kadampally(V)	-
1	SDP	MULUGU SS	NARSAMPALLY	11KV	Gajwel	14.55	16.00	01.05		11KV POLE DAMAGED	-
2		THUNKIBOLLARAM SS	NARSAPUR	11KV	Gajwel	15.30	16.20	00.50		11KV LINE CUT	-
3		LINGAPUR SS	LINGAPUR	11KV	Gajwel	17.18	18.50	01.32		DISK FAILED	-
1	RR S	Vattinagulapally	Movie Tower	11KV	Ibrabimbagh	01.50	03.32	01.42	BD	11KV Cable kit failed at Movie tower	-
1	RR N	Chintal	Surya Nagar	11KV	Medchal	07.30	08.25	00.55		11KV Line Cut & Replaced at Ramreddy Nagar	-
2		Shameerpet	NTRO	11KV	Medchal	17.40	19.40	02.00		Breaker Mechanical Problem in SS(Backfeeding arranged from 11KV Nalsar Feeder)	-
1	RR E	IDA Uppal	Airtel	11KV	Habsiguda	15.30	21.29	05.59		11KV UG Cable damaged due to JCB Road work at Dumping Yard & B/F from 11KV Srikrishna Feeder	-
2		St.No.08	Laxmi Nagar	11KV	Habsiguda	20.33	21.44	01.11		11KV 2Nos Jumper cut at NMDC Main Road	-
3		VP Nagar	Brundavan Colony	11KV	Sainikpuri	15.25	16.30	01.05		Tree branches fall on Remoove at Brundavan Colony (LM Chandra Shekar)	-
1	HYD C	Nampally	FAPCCI	11KV	VII	11.33	12.45	01.12	EL	Auto Recloser burnt out at Bazarghat Chowrasta	-