

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	4	3	4	3	4			
2	NLG	144	988		1		1		1			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>3</b>	<b>6</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 26.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Mogalmdaka	33KV	Mahabubnagar	21.10	21.25	00.15	E/L	Due to Heavy Wind Gale	Mahabubnagar	-
2		Puttapahad	Nancherla	33KV	Narayanapet	15.50	16.55	01.05	O/L	Disc Insulator Failed at Nancherla Village	Narayanapet	-
3		Kosgi	Kosgi	33KV	Narayanapet	21.40	21.55	00.15	E/L	Due to Heavy Wind Gale	Narayanapet	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	KANUKURTHY	DAMARGIDDA	11KV	Narayanapet	09.30	10.12	00.42		Due to 11Kv insulator failure	-
2		KANUKURTHY	KANUKURTHY	11KV	Narayanapet	08.35	09.44	01.09		Due to 11kv line binding fallen on DTR at ulligundam vlg	-
3		PALLERLA	NADIPAD	11KV	Narayanapet	10.34	11.05	00.31		Due to squirrel fallen on 11kv line at nandipad vlg	-
4		KOSGI	BHAKTIMALLA (HANMANPALLI)	11KV	Narayanapet	11.30	14.02	02.32		Due to squirrel fallen on 11kv line at masaipally vlg	-
1	NLG	Ramanthapur	Vailakol	11KV	Devarakonda	12.10	13.08	00.58		11 KV Insulator Failed	-
1	SDP	Narsapur	Lingareddypally	11KV	Siddipet	10.05	13.05	03.00		B/D-Tree bunches fallen on line-Now rectified	-
1	MDK	Bollaram - I	Soubagya	11KV	Patancheru	19.30	20.30	01.00		BD Due to Bird fallan on line	-
1	RR N	Gowdavelly	IDA Gowdavelly	11KV	Medchal	20.05	20.45	00.40	BD	100KVA T/F Cable failed at HP Petrol Pump, Basaragadi Village	-
1	RR E	Ramanthapur	Venkat reddy nagar	11KV	Habsiguda	09.20	10.00	00.40		Tree branches fallen on 11kv line at Mahesh bank line	-
1	HYD N	Chinna Thokatta	Hasmathpet	11KV	VI	07.50	09.30	01.40	All Indication	Street Light Pole fallen on lines at Hasmathpet Cheruvu Katta	-