

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT				7		7		7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	16	1	16	1	16	0	0	
	Grand Total	1082	6468	1	21	1	21	1	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.03.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanapur	Solipur	33KV	Wanaparthi	04.01	08.05	04.04	O/L	Conductor Fallen on the Crossaram at Ghanapur (V)	Solipur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.03.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	KYATHANPALLY	WATTUGUNDLA	11KV	NARAYANPET	14.53	17.44	02.51		Due to 11kv line touched to channel	-
2		KANUKURTHY	KANUKURTHY 24 HRS. FEEDER	11KV	NARAYANPET	08.47	11.57	03.10		Due to pin binding fallen on DTR at Kanukurthy vlg	-
3		MARIKAL	TILERU	11KV	NARAYANPET	08.05	08.45	00.40		Due to line fault	-
1	NLG	Jalapuram	Gottiparthi	11KV	Suryapet	03.30	06.55	03.25	EL	Jumper cut	-
2		Eduloor	Munukuntla	11KV	Nalgonda	12.05	13.00	00.55	EL	11KV Jumper cut	-
3		Rajupeta	Bandlavarigudem	11KV	Nalgonda	12.35	16.30	03.55	EL	11KV Jumper cut	-
4		Koppole	Bheemaram	11KV	Nalgonda	13.15	15.27	02.12	EL	Tree branch fallen on 11KV line	-
5		Rajapeta	Namila Agl	11KV	Bhongir	13.30	14.55	01.25	EL/OL	11kv Insulator Failed near Namila Village	-
6		Chada	Nancharepeta	11KV	Bhongir	11.20	14.30	03.10	EL/OL	11kv Insulator Failed near Nanchrepeta Village	-
1	SDP	Cherial Town	Rollabanda	11KV	Husnabad	14.20	16.20	02.00		DTR Problem	-
2		Musthyala	Gaddithota	11KV	Husnabad	13.20	17.50	04.30		Tree branch fallen on the Line	-
3		Nagapuri	Pothireddipalli	11KV	Husnabad	09.40	10.39	00.59		Tree branch fallen on the Line	-
4		Komuravelli	Komuravelli 24Hrs	11KV	Husnabad	11.50	13.46	01.56		Insulator Fail	-
5		Komuravelli	Inapur24Hrs	11KV	Husnabad	12.40	13.44	01.04		Insulator Fail	-
6		Akkannapeta	Gollakunta	11KV	Husnabad	15.25	18.45	03.20		DTR Problem	-
7		Thornal	Appanapally	11KV	Siddipet	12.50	13.30	00.40		Jumper cut	-
1	RR N	Gagillapur	F-II	11KV	Jeedimetla	14.55	16.50	01.55	EL/OL	Pin Insulater failed at Dobule bed room Gagillapur	-
2		Medchal	IDA-I	11KV	Medchal	15.55	16.50	00.55	BD	11KV Line cut and replaced at Flywood Company	-
3		Aliabad	LGM Pet	11KV	Medchal	16.10	17.20	01.10	BD	Tree branches fallen on the 11KV Line at LGM Pet Village	-
1	RR E	Narapally	Pravathapur	11KV	Keesara	12.30	14.08	01.38		11KV line cut at shalini hotel narapally	-
2		Narapally	Narapally	11KV	Keesara	12.35	13.20	00.45		Tree branches fallen on 11kv line at narapally main road	-