

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>1</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 02.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Hadnoor	33KV	Zaheerabad	15:50	17:30	1:40		Insulator failure	Hadnoor	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Thadakamalla	Adarsha lift	11KV	Miryalaguda	14:29	15:55	1:26	EL	Conductor snapped	No
2		Kodur	Kodur	11KV	Suryapet	07.30	11.00	03.30	EL	Insulator flashover	No
1	MDK	Patancheru Town	Town	11KV	Patancheru	7:20	8:15	0:55		Jumper Cut	No
1	SDPT	Markook SS	Sneha Industrial	11KV	Gajwel	9:10	11:55	3:15		Insularor failed	No
2		Mulugu SS	Mulugu AGL	11KV	Gajwel	19.30	12.40	17.10		11 KV Insulator failed & Disc failed	No
3		Pallepahad SS	Vemulaghat	11KV	Gajwel	03.20	11.15	07.55		Pole Damaged	No
4		Jangapally	Veerareddypally	11KV	Siddipet	13.35	17.38	04.03		B/D (AB SWITCH Reipar)	No
1	RR N	Shameerpet	Devarayamajal	11KV	Medchal	13:20	16:40	3:20		Bird fallen on the 11KV Line at ORR	No
2		GP Pally	Maisammaguda	11KV	Medchal	16.45	17.30	00.45		Bird fallen on the 11KV Line at St Peter College	No