

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	27	1	27	1	27			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		7		7		7			
	Total	606	3055	1	37	1	37	1	37	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988		2		2		2			
3	MDK	107	933		4		4		4			
4	SDPT				16		16		16			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	25	1	25	1	25	0	0	
	Grand Total	1082	6468	2	62	2	62	2	62	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 05.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Nawabpet	33KV	Mahabubnagar	18.35	20.45	02.10	OL	for Tree Branch Fallen on the line near Town-III	Nawabpet	-
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	16.24	18.20	01.56	BD	No Fault	33KV Kompally	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 05.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jadcherla	Nagasala	11KV	Jadcherla	08.00	09.35	01.35		BD 11KV Wire cut near Nasurlabad	-
2		Jadcherla	Gangapur	11KV	Jadcherla	12.10	13.10	01.00		BD 11KV Wire cut near Aloor (v)	-
3		Boothpur	Amistapur Agl	11KV	Jadcherla	07.25	09.54	02.29		BD Phase to Phase near Seripally B	-
1	NLG	Munagala	Kokkereni-2	11KV	Huzumagar	07.25	09.00	01.35	EL	11 KV LINE SNAPPED	-
2		Angadipeta	Gudipally	11KV	Devarakonda	07.55	10.15	02.20	EL	B/D Of 11KV Line Cutt	-
1	MDK	EPIP-II	Srinivasa Costing	11KV	Sangareddy	16.20	17.45	01.25		BD Due to Tree Fallen on line	-
2		Kistareddypet	Industrial	11KV	Patancheru	17.40	20.50	03.10		BD Due to line AB Switch Failed	-
3		Bollaram - II	Kottam	11KV	Patancheru	16.18	23.28	07.10		BD Due to Tree Fallen on line	-
4		Bollaram - II	Rupa	11KV	Patancheru	16.18	23.25	07.07		BD Due to Tree Fallen on line	-
1	SDP	Nangunoor	Akkanepally	11KV	Siddipet	12.40	14.40	02.00		B/D-HT/LT line problem Icno. 18004	-
2		Thornal	Thornal	11KV	Siddipet	14.45	19.00	04.15		B/D-Middle pole problem Icno. 10317	-
3		Thimmapur	Padamabampally	11KV	Siddipet	14.25	15.15	00.50		B/D- Insulater problem Icno. 0950	-
4		Chittapur	Chowderpally	11KV	Siddipet	14.55	16.57	02.02		B/D - heave wind and rain 16058	-
5		Dubbak	Dubbak	11KV	Siddipet	15.12	16.00	00.48		BD- Jumper problem Icno. 15642	-
6		Akbarpet	Bhoomapally	11KV	Siddipet	15.30	17.50	02.20		B/D-Middle pole problem Icno. 0847	-
7		GAJWEL	JALIGAMA	11KV	Gajwel	15.50	16.50	01.00		TREE BRANCH FELL ON 11KV LINE	-
8		JAGADEVPUR	ALIRAJPET	11KV	Gajwel	16.05	18.40	02.35		POLE TOUCH TO 11 KV LINE	-
9		MARKOOK	AGL	11KV	Gajwel	17:05	17:35	00.30		DISC FAILED	-
10		WARGAL	TOWN	11KV	Gajwel	17.30	19.20	01.50		TREE BRANCH FELL ON 11KV LINE	-
11		DOMMATA	GAJULAPALLY	11KV	Gajwel	16.20	17.00	00.40		11KV INSULATOR FAIL	-
12		DOMMATA	DOMMATA	11KV	Gajwel	17.20	18.30	01.10		DISC FAILED	-
13		Begumpet	Laxmipur	11KV	Husnabad	10.57	11.37	00.40		Line cut	-
14		Koheda	Venkateshwarapally	11KV	Husnabad	10.30	12.30	02.00		Line cut	-
15		Maddur	Maddur town	11KV	Husnabad	14.15	14.55	00.40		Line cut	-
16		Chityala	Dhommata	11KV	Husnabad	18.45	20.15	01.30		Line problem	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	UMCC	Gajulamaram	11KV	Medchal	16.30	18.20	01.50	BD	11KV Line cut and replaced at Chihtaramma Temple	-
2		Jagathgirigutta	Venkateswara Nagar	11KV	Medchal	17.25	19.20	01.55	BD	11KV Disc failed at Church Road	-
3		Subash Nagar	Pragha Tools	11KV	Medchal	07.50	09.10	01.20	BD	11KV Cable End Kit failed at Pipe Line Road	-
4		Dulapally	Dulapally Village	11KV	Medchal	16.35	17.25	00.50	BD	11KV Pin Insulator failed at Thuliph Bakery	-
5		Jeedimetla-II	Apuroopacolony	11KV	Jeedimetla	16.20	17.20	01.00	EL	Due to Rain	-
6		Jeedimetla-II	Excells	11KV	Jeedimetla	16.20	17.30	01.10	EL	Due to Rain	-
7		Jeedimetla-II	Phase-IV	11KV	Jeedimetla	16.25	18.25	02.00	EL	Due to Rain	-
8		Jeedimetla-II	N R S A	11KV	Jeedimetla	16.25	18.10	01.45	EL/OL	Due to Rain	-
9		Jeedimetla-II	Phasel-V	11KV	Jeedimetla	16.25	18.30	02.05	OL	11kv Pin insultor failure At Jetl	-
10		Jeedimetla-III	Ram reddy Nagar	11KV	Jeedimetla	16.22	17.40	01.18	EL	Due to Rain	-
11		Jeedimetla-III	Fox sagar	11KV	Jeedimetla	16.20	17.25	01.05	EL	Due to Rain	-
12		Jeedimetla-III	Pipe line road	11KV	Jeedimetla	18.35	22.30	03.55	EL/OL	11kv AB cable failure Near Sub station	-
13		Jeedimetla-III	Andhrapolymer	11KV	Jeedimetla	18.45	19.45	01.00	EL	11kv enDY Kit Failure sri laxmi industrie	-
14		Bowrampet	AGL	11KV	Jeedimetla	16.08	18.10	02.02	EL	Due to Rain	-
15		Bowrampet	CoCo-cola	11KV	Jeedimetla	16.40	18.05	01.25	EL	Due to Rain	-
16		Bowrampet	Bowrampet Village	11KV	Jeedimetla	16.15	19.20	03.05	EL	Due to Rain	-
17		Bowrampet	Junnrm	11KV	Jeedimetla	16.17	19.10	02.53	EL	Due to Rain	-
18		JeedimetlaIV	Tagorea	11KV	Jeedimetla	16.40	17.45	01.05	EL	Due to Rain	-
19		JeedimetlaIV	Aai Matha	11KV	Jeedimetla	16.45	17.50	01.05	EL	Tree branches Fallen On the 11kv Line At subasha Nagar	-
20		Suraram	Rajavi gaqndhinagar	11KV	Jeedimetla	16.15	17.15	01.00	EL/OL	Due to Rain	-
21		Suraram	Sai Baba	11KV	Jeedimetla	16.17	17.17	01.00	/OL	Due to Rain	-
22		Suraram	Sree Ram nagar	11KV	Jeedimetla	16.17	17.17	01.00	EL	Due to Rain	-
23		Suraram	Matrix	11KV	Jeedimetla	16.20	17.25	01.05	EL	Due to Rain	-
24		Jeedimetla_I ,	Phase-I	11KV	Jeedimetla	18.00	19.10	01.10	EL	11kv Ab cable failure At Phase-I	-
25		Dp Pally-II	Millinenum	11KV	Jeedimetla	16.10	19.40	03.30	EL	11kv pin Insultor Failure At Ice Factor	-
26		Dp Pally-II	INDo Fab	11KV	Jeedimetla	16.20	19.30	03.10	EL	Due to Rain	-
27		Dp Pally-II	Tech Maindhira	11KV	Jeedimetla	16.40	18.20	01.40	EL	T/F HG Fuse Failure touched To Channel At Ahland Unite -li	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal	Nava Bharath	11KV	Habsiguda	02.15	07.45	05.30		11KV line touched to Lorry(Container) & Container burnt at Modern Bread Company(75% of Load Charged) & 11KV Jumper connected at NRB Bearings(Full Load Charged at 11:50)	-
2		Malkajiri	Bhavani Nagar	11KV	Sainikpuri	17.10	18.08	00.58		Brass Patti cut on Touched HG fuse set at Sai Nagar (AE/OP)	-
3		P&T Colony	Canara Nagar	11KV	Keesara	17.20	18.10	00.50		11KV Jumper cut at Canara Nagar Orange Super Market	-
1	HYD N	Madhapur	Pathrika Nagar	11KV	X	16.35	17.45	01.10	EL	Pin Insulator flash over at Milani Tower	-
2		Allwal	Dharam Kanta	11KV	C-VI	17.03	18.18	01.15	EL,OL	Pin Insulator flash over CJR Function Hall	-
3		Road No.2	Devara Konda Basti	11KV	X	17.26	18.30	01.04	EL,OL	Tree branches fallen on lines at Maruthi Apts	-
4		Madhapur	Value Lab	11KV	X	16.35	18.50	02.15	All Indication	Tree branches fallen on lines at Vijaya-6 Building	-
1	HYD S	Kulshumpura	Rahimpura	11KV	IX	16.49	17.58	01.09	All Indication	No Visible Fault	-
1	HYD C	Asif Nagar	Kakatiya Nagar	11KV	VII	17.45	19.05	01.20	EL,OL-Rph	Tree branches fallen on lines at Morine Bakery	----
2		Aditya Towers	Neeraja Colony	11KV	VII	11.19	12.20	01.01	EL	No Visible Fault	Arranged B/F on 11KV NSF Colony fdr