

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	3		3		3				
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	3	1	3	1	3	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		6		6		6			
2	NLG	144	988		3		3		3			
3	MDK	107	933		2		2		2			
4	SDPT			2	6	2	6	2	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	17	2	17	2	17	0	0	
	Grand Total	1082	6468	5	18	5	18	5	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Husnabad	Dharmaram	33KV	Husnabad	13:10	16:20	3:10		AB Switch open at Banreupally Village	Dharmaram	No
2		Mustyala	Nagapuri	33KV	Husnabad	05.30	07.30	02.00		Tree branchh fallen on the line	Nagapuri	No
1	RR N	132KV Malkaram	Ratnalayam	33KV	Medchal	9:26	12:05	2:39		No visible fault	Ratnalayam	No
2		132KV Medchal	Keshavaram	33KV	Medchal	15.50	16.55	01.05		Tree branch fallen on the 33KV line at Pudur	Keshavaram	No
3		132KV Malkaram	Ratnalayam	33KV	Medchal	17.25	18.45	01.20		No visible fault	Ratnalayam	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Uttoor	PAGIDIMARRY	11KV	Narayanapet	08.15	15.10	06.55		Breakdown due to HT/LT at rice mill	No
2		Krishna	CHEGUNTA	11KV	Narayanapet	03.00	07.20	04.20		Breakdown due to not stable on E/L at kulsi vlg	No
3		KYATHANPALLY	AYYAWARIPALLY	11KV	Narayanapet	08.12	09.04	00.52		Breakdown due to 11kv jumper cut at moosapet vlg	No
4		MOGALMADKA	ANNASAGAR	11KV	Narayanapet	9:00	14:00	5:00		Breakdown due to 11kv line earth fault at narsapur vlg	No
5		KONDAPUR	CHARLAPALLY	11KV	Narayanapet	22:00	10:00	12:00		Breakdown due to tree branch fallen on 11 kv line at charlapally vlg	No
6		EKLASPUR	JINNARAM	11KV	Narayanapet	01.00	07.55	06.55		Breakdown due to 11kv lines got mixed one another at jinnaram vlg	No
1	NLG	Gondiryala	Chimiryala	11KV	Huzurnagar	5:00	7:30	2:30	E/L	11Kv Line Snapped	No
2		Kodad Indoor	Huzurnagar x Road	11KV	Huzurnagar	00.30	01.30	01.00	E/L	11Kv Jumper Cut	No
3		Pulicherla	Gaddameedi Thanda	11KV	Miryalguda	11.20	15.03	03.43	E/L	Tree branches fallen on 11Kv line	No
1	MDK	SOL	BMF	11KV	Sangareddy	18:00	18:50	0:50		Tree branch fallen on the line	No
2		Bollaram - II	Rupa	11KV	Patancheru	11.40	14.20	02.40		Jumper Cut	No
1	SDPT	Nangnoor	Akkanapally	11KV	Siddipet	12:00	13:40	1:40		11Kv Jumper Cut	No
2		GAJWEL & PREGNA	GAJWEL & PREGNAPUR	11KV	Gajwel	17:15	18:30	1:15		SHUT DOWN	No
3		JAGADEVPUR	ETKYALA	11KV	Gajwel	07.50	10.03	02.13		INSULATOR FAILED	No
4		DHAMARAKUNTA	DHAMARAKUNTA	11KV	Gajwel	18:00	20:20	02.20		11 KV LINE CUT	No
5		GOWRARAM	TOWN-2	11KV	Gajwel	09.30	10.03	00.33		LT lines twisted	No
6		RAMPUR	ZAPTHILINGAREDDY PALLY	11KV	Gajwel	11:00	12:20	1:20		INSULATOR FAILED	No
1	RR E	Polytechnic	Srinivasapuram	11KV	Habsiguda	2:05	3:55	1:50		Coconut tree branches fallen on 11KV line at St.No.04, Srinivasapuram	B/F supply taken from 11KV Ram Reddy Nagar feeder at 3:22 hrs.