

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	8	2	8	2	8	0	0	
	Grand Total	1082	6468	2	8	2	8	2	8	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 07.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Chinnamaroor	33KV	Wanaparthi	16.00	17.45	01.45	EL	Due to Conductor Snapped	Chinnamaroor	-
1	SIDDIPET	SIDDIPET	THORNALA	33KV	SIDDIPET	06.40	07.00	00.20		BREKERS FAIL	THORNALA	ALternate To Chittapur feeder

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 07.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	PERAPALLA	PERAPALLA AGL	11KV	Narayanapet	12.49	14.00	01.11		11KV Insulator Fault at Maddelbeedu Road	-
2		KOSGI	MUSRIFFA (VITTALAPUR)	11KV	Narayanapet	12.30	16.00	03.30		Due to DTR Failed at mungimalla Village	-
1	NLG	Angadipeta	Gudipally	11KV	Devarakonda	07.55	10.15	02.20	EL	11KV Line Cutt	-
2		Munagala	Kokkereni-2	11KV	Huzurnagar	04.00	07.30	03.30	EL	11 KV LINE SNAPPED	-
3		Addagudur	Kotamarthy	11KV	Bhongir	05.00	07.15	02.15	EL	11 kv Insulator failed at SS - 3 Near Chirragudur village.	-
1	SDPT	Mittapally	Mittapally	11KV	SIDDIPET	08.30	09.30	01.00		B/D Tree Branches folldown	-
2		Cherial Town	Rollabanda Agl	11KV	HUSNABAD	10.15	17.10	06.55		Line snapped, same rectified	-
3		Komuravelly	Kadavergu	11KV	HUSNABAD	01.35	06.37	05.02		Line folt, same rectified	-