

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	5	2	5	2	5			
2	NLG	144	988	1	20	1	20	1	20			
3	MDK	107	933		1		1		1			
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	28	4	28	4	28	0	0	
	Grand Total	1082	6468	4	34	4	34	4	34	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 12.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kosgi	Mirzapur	33KV	Mahabubnagar	03.41	06.05	02.24	E/L	Due to Wind		Alternate Supply Taken to 33Kv Parllerla Feeder at 6:05Hrs
2		Ghanapur	Lattupally	33KV	Wanaparthi	00.00	09.17	09.17	E/L	33KV Insulator Failed		NO
1	NLG	Mattampally	Raghunadapalem	33KV	Huzurnagar	00.00	09.00	09.00	EL/OL	33kv Pole damages		-
1	SDPT	Thukkapur	Mettu	33KV	Gajwel	01.30	06.15	04.45		BD (Tree fallen on 33kv line)		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 12.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Polepally	Vallur	11KV	Jadcherla	10.00	12.50	02.50		Jumper Cut Near KTR Plant Back Side	-
2		Karkonda	Karkonda	11KV	Jadcherla	04.48	09.11	04.23		11KV Disc Failure & 11KV wire Cut Near Udandapur Dam Side.	-
3		Ponnakal	Rachala	11KV	Jadcherla	10.33	13.30	02.57		11KV Insulator Failure NearPonnakal SS Side.	-
4		Vemula Addakal	Vemula	11KV	Jadcherla	01.00	04.35	03.35		Due To Rain	-
5		Thangadi	Thangadi	11KV	Narayanpet	11.26	12.46	01.20		11KV Jumper cut at Thangadi(V)	-
1	NLG	Jalalpuram	Velishala	11KV	Suryapet	07.10	10.26	03.16	E/L	11Kv Disk failed	-
2		Ravulapally	Kukkadam	11KV	Suryapet	10.20	12.55	02.35	E/L	11Kv Insulator flashover	
3		Balemla	Balemla	11KV	Suryapet	05.00	07.52	02.52	E/L	11Kv Insulator failed	
4		Nagaram	Machireddy Pally	11KV	Suryapet	09.35	12.35	03.00	E/L	11Kv Conductor snapped	
5		Thungathurthy	Vempaty	11KV	Suryapet	08.30	12.00	03.30	E/L	11Kv Insulator failed	
6		Keethavarigudem	Rainigudem	11KV	Huzurnagar	04.00	08.00	04.00	E/L	11Kv Conductor snapped	
7		Alingapuram	Raghavapuram	11KV	Huzurnagar	05.00	07.30	02.30	E/L	11KV JUMPER CUT	
8		BNL Thanda	Pathanda	11KV	Huzurnagar	06.00	09.30	03.30	E/L	11KV POLE DAMAGED	
9		Munagala	Kokkereni-2	11KV	Huzurnagar	06.35	09.00	02.25	E/L	11Kv Conductor snapped	
10		Chilukur	Kondapuram	11KV	Huzurnagar	06.00	08.45	02.45	E/L	11KV POLE DAMAGED	
11		Bollepally	Indriyal	11KV	Bhongir	18.00	11.45	17.45	EL/OL	11kv Poles Damedged Agl 5DTR's OFF	
12		Suddala	Threyala	11KV	Bhongir	12.40	14.30	01.50	EL/OL	11KV Pole Damedged near Threyala (V)	
13		S.Lingotam	Lingojigudem	11KV	Choutuppal	01.00	10.19	09.19	EL/OL	11KV Line Snapped near Ramalingam (V)	
14		Nakrekal	Maroor	11KV	Nalgonda	10.05	12.25	02.20	E/L	Tree branches Fallen on the 11Kv Line	
15		Velugupally	G.K.Annaram	11KV	Nalgonda	11.00	12.00	01.00	E/L	11Kv Insulator failed	
16		Damercherla	Watchya GP	11KV	Miryalguda	20.00	05.00	09.00	E/L	Heavy gale & wind tree branches fallen on line near (V)	
17		Kopple	Aregudem	11KV	Devarakonda	19.10	10.05	09.05	E/L	11Kv Conductor Snapped & Pin insulator failed	
18		Kopple	LD Gudem	11KV	Devarakonda	19.10	10.02	09.08	E/L	11Kv Conductor Snapped	-
19		Kopple	Bollaram	11KV	Devarakonda	19.10	10.25	08.45	E/L	11Kv pin insulator failed	-
20		D.B.Pally	S.P.Thanda	11KV	Devarakonda	05.00	12.10	07.10	E/L	11Kv pin insulator failed	-
1	MDK	EPIP-III	Ufoam	11KV	Patancheru	01.30	06.53	05.23		BD due to Disk failed and Conductor snapped	-
1	SDPT	Jagdevpur SS	Itikyal Feeder LC.No.5891	11KV	Gajwel	14.20	18.00	03.40		11KV Jumper Cut	-
2		Komuravelly	Inapur	11KV	Husnabad	10.10	12.10	02.00		DISC INSULATOR FAILURE	-
1	RR N	Kandlakoya	Kandlakoya	11KV	Medchal	05.05	06.00	00.55		Tree Branch fallen on the 11KV Line at Kandlakoya Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	07.28	08.34	01.06		Chunni fallen on 11Kv line on Moula-Ali feeder & Gayathri Nagar load add to Ganthi Nagar (due to line AB Switch Open at Gandhi Nagar feeder charged OK AE/OP)	-
2		Vasanthapuri	Ganesh Temple	11KV	Sainikpuri	13.50	15.37	01.47		11Kv Cable failed at Vasanthapuri Colony & Ganesh Temple feeder load add to Ragavendra & BJR Nagar feeder (AE/OP) due to AB Switch Open	-
1	HYD N	Jamestreet	Chikoti Complex	NT	V	17.55	19.15	01.20	EL,OL	AB Switch Disc flash over at Kalasiguda	-
1	HYD C	Bathkammakunta	Ahobilmutt	CEN	II	05.17	07.00	01.43	EL,OL-Rph	Bird fault on lines at Ahobilmutt	At 05:55Hrs partial fdr charged after removing partial loads of 11KV Saibaba Temple fdr, remaining loads added on 11KV C.E.Colony fdr
2		Golnaka	Bharman Hostel	CEN	II	19.52	22.00	02.08	EL	2no Pin Insulator flash over at Happy Home Apartment	No supply to 11KV Ramalayam feeder due to B/F