

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	4	2	4	2	4			
7	RR(E)	168	403		8		8		8			
8	Hyd	194	1044		92		92		92			
	Total	606	3055	2	104	2	104	2	104	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	5	2	5	2	5			
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	14	2	14	2	14	0	0	
	Grand Total	1082	6468	4	118	4	118	4	118	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 13.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Thomidirekula	33KV	Jadcherla	15.00	19.10	04.10	EL&OL	33KV Nava Durga feeder conductor cut fallen on the 33KV Thomiodirekula line	Thomidirekula	-
2		Balanagar	Nava Durga	33KV	Jadcherla	15.00	19.10	04.10	EL&OL	33KV Nava Durga feeder conductor cut fallen on the 33KV Thomiodirekula line	Nava Durga	-
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	18.47	20.34	01.47	BD	33KV Line AB Switch Opened at Kompally Bridge	33KV Kompally	-
2		132KV Medchal	33KV Devarayamjal	33KV	Medchal	04.25	10.30	06.05	BD	33KV Pole Damaged at SVR Funcation Hall, Saigeetha Road (backfeeding arranged from 33KV Ratnalayam Feeder(132KV Malkaram SS) Time 05:00)	33KV Devarayamjal	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 13.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Ponnakal	Ponnakal	11KV	Jadcherla	06.50	11.30	04.40		Phase to phase near Bhavani maatha temple due to heavy wind LC taken by Anji Artisan for tree cutting 6301259496	-
2		Kanukurthy	Lokurthy	11KV	Narayanpet	08.40	10.33	01.53		Breakdown due to 3 phase not stable at mallereddypally vlg	-
3		Kothapally	Booneed	11KV	Narayanpet	08.40	09.05	00.25		Breakdown due to 11kv line cut at booneed vlg	-
4		Kothapally	Mannapur	11KV	Narayanpet	15.30	16.00	00.30		Breakdown due to disc failed at mannapur vlg	-
5		Nancherla	Nancharla	11KV	Narayanpet	03.06	06.26	03.20		Breakdown due to tree branch fallen on 11kv line at nancherla vlg	-
1	NLG	Penpahad	SR Palem	11KV	Suryapet	07.05	09.32	02.27	EL	Insulator flashover	-
2		Bibigudem	Chivvemla AGL	11KV	Suryapet	05.40	08.20	02.40	EL	Conductor snapped	-
3		Nuthankal	Errapaahd	11KV	Suryapet	04.20	07.40	03.20	EL	Insulator failed	-
4		Ananthagiri	Mogalaikota	11KV	Huzurnagar	03.50	04.50	01.00	EL	11 KV LINE SNAPPED	-
5		Sirikonda	Balluthanda	11KV	Huzurnagar	06.00	07.45	01.45	EL	11 KV LINE SNAPPED	-
6		Repala	Repala	11KV	Huzurnagar	04.00	07.30	03.30	EL	11 KV JUMPER CUT	-
7		Pamanagundla	Pittampally	11KV	Nalgonda	09.00	10.30	01.30	EL	Tree branches fallen on the line	-
8		Choutuppal IPDS	Dhamera Agl	11KV	Choutuppal	05.44	07.58	02.14	EL/OL	11kv Disc Failed near Damera Village	-
9		Juloor	Peddagudem	11KV	Choutuppal	04.20	07.20	03.00	EL/OL	11kv Pole Damedged near Peddagudem Village	-
1	RR N	HMT	Gandhi Nagar	11KV	Medchal	18.15	19.15	01.00	BD	Tripped on EL Indication (Due to Heavy wind and rain)No Fault	-
2		Devarayamjal	DMC	11KV	Medchal	05.10	06.40	01.30	BD	33KV Pole Damaged and fallen on 11KV Line at Liquior Godham	-
3		Shameerpet	33KV Leo Meridian	11KV	Medchal	18.45	20.05	01.20	BD	Tripped on EL Indication (Due to Heavy wind and rain)No Fault	-
4		Kandlakoya	Saigeetha Asramam	11KV	Medchal	18.26	19.34	01.08	BD	Tripped on EL Indication (Due to Heavy wind and rain)No Fault	-
1	RR E	NGRI	Kalyanipuri	11KV	Habsiguda	02.57	04.20	01.23		11KV Insulator failed at Shivalayam temple	-
2		VP Nagar	Deen Dayal Nagar	11KV	Sainikpuri	19.25	20.35	01.10		End Cable Kit failed at Hill Colony and Deen Dayal Nagar load added on Officers Colony (L.Insp Anil)	-
3		Moula ali	Malkajgiri	11KV	Sainikpuri	20.05	21.05	01.00		Tree fallen on 11Kv line at Gosha Majid	-
4		Moula ali	Spectra	11KV	Sainikpuri	20.05	21.45	01.40		2nd AB Switch sparked and repaired at Kamenine Pharmacy (Artisian Narshima Reddy)	-
5		Keesara	Vardhana	11KV	Keesara	02.00	02.40	00.40		11KV AB Switch blade cut near SS Yard	-
6		Keesara	Anki Reddy Pally	11KV	Keesara	05.58	06.38	00.40		11KV line cut at Shamirpet Road Dharmakanta	-
7		Aushapur	Bokkenguda	11KV	Keesara	13.25	14.44	01.19		11KV line cut at Ghanapur	-
8		Narapally	Prathap Singaram	11KV	Keesara	04.15	06.15	02.00		Tree branches fallen on 11KV line at J.K Garden	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Green Lands	Hindu	11KV	IV	00.02	02.30	02.28	EL	Cable End Kit failed at Hindu	At 01:52 Hrs partial loads added on 11KV Ameerpet fdr & remaining loads added on 11KV Topaz Building fdr
2		Prakash Nagar	Prakash Nagar Extension	11KV	IV	00.07	01.40	01.33	EL	Tree branches fallen on lines near E-Seva	-----
3		K.I.M.S	Mani Anjaiah	11KV	V	00.19	01.30	01.11	EL	Pin Insulator flash over at Opp: Sindhi Bank	-----
4		Nehru Nagar	L.I.C Colony	11KV	C-VI	01.05	03.10	02.05	EL	Pin Insulator flash over at LIC Colony	-----
5		Toli Chowki	Road No.86	11KV	X	01.38	04.50	03.12	EL	No Visible Fault (due to Rain)	Arranged B/F on 11KV Lotus Pond fdr
6		Prashasan Nagar	Arogya Sree	11KV	X	01.40	03.44	02.04	EL,OL	Tree branches fallen on lines at Various Places	-----
7		Prashasan Nagar	B.N.R Hills	11KV	X	01.40	03.57	02.17	EL,OL	Tree branches fallen on lines at Various Places	-----
8		Prashasan Nagar	Navya Vihar	11KV	X	01.40	04.00	02.20	EL,OL	Tree branches fallen on lines at Various Places	-----
9		LV Prasad Marg	Gymkhana Club	11KV	X	01.46	10.40	08.54	EL	Sparking AB Switch at Cream Stone back side	At 02:14Hrs partial fdr charged
10		Muffakamza College	Eye Drusti	11KV	X	01.52	04.30	02.38	EL,OL	Coconut tree branches fallen on lines at Srinagar Colony	-----
11		Muffakamza College	Meridian	11KV	X	01.54	03.32	01.38	EL,OL	Pole damaged & DTR fallen from Plinth at Meridian (1No. DTR kept off)	-----
12		MLA Colony	K.B.R Park	11KV	X	02.20	03.30	01.10	All Indication	No Visible Fault (due to Rain)	-----
13		Prashasan Nagar	Ashwini Heights	11KV	X	02.23	04.05	01.42	EL,OL	Tree branches fallen on lines at Prashasan Nagar	-----
14		Chilkaiguda	P.R Nagar	11KV	V	02.25	04.15	01.50	EL	No Visible Fault (due to Rain)	Arranged B/F on 11KV S.P College feeder
15		Film Nagar	Rama Naidu Studio	11KV	X	02.55	06.10	03.15	EL,OL	Tree branches fallen on lines at Rama Naidu Studio	-----
16		Film Nagar	Ambedkar Colony	11KV	X	02.55	07.10	04.15	EL,OL	Tree branches fallen on lines at Saideep Bank	-----
17		Film Nagar	MLA Colony	11KV	X	02.55	07.10	04.15	EL,OL	Tree branches fallen on lines at Saideep Bank	-----
18		Film Nagar	Apollo	11KV	X	02.55	08.00	05.05	All Indication	Tree branches fallen on lines at Film Chambers	-----
19		Film Nagar	Padmalaya Sutido	11KV	X	02.55	07.00	04.05	All Indication	Tree branches fallen on lines at Various Places	Arranged B/F on 11KV Nyaya Vihar fdr
20		Osm. University	Ravindra Nagar	11KV	V	03.35	05.10	01.35	All Indication	Tree branches fallen on lines at Ravindra Nagar	-----
21		MLA Colony	Cine Ghar	11KV	X	09.30	11.35	02.05	EL	Tree branches fallen on lines at SBI Galli	-----
22		MLA Colony	V.L.C.C	11KV	X	10.30	12.15	01.45	EL,OL-Rph	Tree branches fallen on lines at Omega Hospital	-----
23		Jubilee Hills	Film Nagar	11KV	X	10.45	12.30	01.45	OL-Rph	Tree branches fallen on lines at Road No.20	-----
24		Clock Tower	Anjali	11KV	V	12.39	14.15	01.36	EL,OL-Bph	-----	Arranged B/F on 11KV Old Jaikhana fdr

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Chanchalguda	Chowni	11KV	VIII	00.00	01.10	01.10	OL	Pin Insulator flash over at 82 Bus Stop	-----
2		Santosh Nagar	Jyothi Bagh	11KV	VIII	00.02	01.05	01.03	EL	Tree branches fallen on lines at Banaka	-----
3		Petlaburz	Ghansi Bazar	11KV	III	00.20	03.00	02.40	EL	Cable fault at High Court Post Office	-----
4		Attapur	Kishanbagh OH	11KV	III	01.44	03.30	01.46	EL	No Visible Fault (due to Rain)	-----
5		Salarjung	Q.Q.Stadium	11KV	III	01.50	03.50	02.00	EL	No Visible Fault (due to Rain)	Arranged B/F on 11KV Hussaini Alam feeder
6		Ch' Baradari	Fire Station	11KV	III	01.54	03.10	01.16	EL,OL	Faulty loads of 11KV ITI Colony fdr	-----
7		Ch' Baradari	Ch' Baradari	11KV	III	01.54	03.30	01.36	EL,OL	No Visible Fault (due to Rain)	-----
8		Gunj	Hanuman Temple	11KV	VIII	01.59	04.16	02.17	EL,OL-R&Yph	No Visible Fault (due to Rain)	-----
9		Miralam	Hasan Nagar	11KV	III	02.20	03.55	01.35	EL	No Visible Fault (due to Rain)	-----
10		Miralam	Ranjan Colony	11KV	III	02.21	03.55	01.34	EL,OL	Tree branches fallen on lines at Ranjan Colony	-----
11		Miralam	Teegalakunta	11KV	III	02.21	04.20	01.59	EL	Tree branches fallen on lines & Twisted lines at S.K Garden	-----
12		Miralam	Zoo Park	11KV	III	02.22	03.56	01.34	EL	Tree branches fallen on lines at Masjid Khana	-----
13		Aliyabad	Shemsheergunj	11KV	III	02.27	03.50	01.23	EL	No Visible Fault (due to Rain)	-----
14		Jiyaguda	Kamela	11KV	IX	02.30	03.31	01.01	EL	Tree branches fallen on lines at Kamela	-----
15		Panjasha	Sultan Shahi	11KV	III	02.30	05.45	03.15	EL	Tree branches fallen on lines at Mir-Ka-Zahira	-----
16		Panjasha	Metharwadi	11KV	III	02.32	06.10	03.38	All Indication	No Visible Fault (due to Rain)	-----
17		C.R.P.F	Salala	11KV	III	02.35	06.20	03.45	EL,OL-Rph	Disc Insulator flash over at Salala	-----
18		Miralam	N.S Kunta	11KV	III	04.40	06.15	01.35	EL,OL-Rph	Twisted HT lines at Gudi-Ka-Dawakhana	-----
1	Golconda	Golconda	Q.Q.Toombs	11KV	VII	01.35	02.40	01.05	EL,OL-R&Bph	No Visible Fault (due to Rain)	-----
2		Golconda	Shaikpet W.W	11KV	VII	01.35	10.42	09.07	EL,OL-R&Bph	Tree branches fallen on lines at Jaihind Nagar	At 05:45Hrs partial fdr charged
3		Golconda	Narayanamma College	11KV	VII	01.35	11.50	10.15	EL,OL-R&Yph	Tree branches fallen on lines at Various Places	At 11:24Hrs partial loads added on 11KV Brindavan Colony fdr & remaining loads added on 11KV Darga Cable fdr
4		Aditya Towers	Sabza Colony	11KV	VII	01.40	09.40	08.00	EL	Tree branches fallen on lines at Brindavan Apts	-----
5		Golconda	Brindavan Colony	11KV	VII	01.40	09.56	08.16	EL,OL-Yph	Tree branches fallen on lines at O.S.R Colony	-----
6		Golconda	Mothi Mahal	11KV	VII	01.40	04.30	02.50	EL,OL-R&Yph	No Visible Fault (due to Rain)	-----
7		Mothi Mahal	Hakeemsha	11KV	VII	01.40	03.50	02.10	EL,OL	Tree branches fallen on lines at Abu Bakar Masjid	-----
8		Mothi Mahal	M.D Lines	11KV	VII	01.40	03.18	01.38	EL	No Visible Fault (due to Rain)	-----
9		Mothi Mahal	Risala Bazar	11KV	VII	01.40	03.01	01.21	EL	No Visible Fault (due to Rain)	-----
10		Langer House	Pensionpura	11KV	VII	01.40	05.20	03.40	EL	Tree branches fallen on lines at HUDA Park	-----
11		Golconda	Golconda OH	11KV	VII	01.40	05.15	03.35	All Indication	No Visible Fault (due to Rain)	Arranged B/F on 11KV Golconda Cable fdr
12		Golconda	O.U Colony	11KV	VII	01.40	03.35	01.55	EL,OL-Rph	No Visible Fault (due to Rain)	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
13		Golconda	Aditya Nagar OH	11KV	VII	01.40	05.40	04.00	EL,OL-R&Bph	No Visible Fault (due to Rain)	-----

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
14	HYD C	Golconda	Darga OH	11KV	VII	01.40	05.30	03.50	EL,OL-B&Yph	No Visible Fault (due to Rain)	----
15		Mothi Mahal	Saleh Nagar	11KV	VII	01.40	06.20	04.40	EL	Twisted HT lines at Chella PT	----
16		Toli Chowki	B.S.N.L	11KV	VII	01.41	03.08	01.27	EL	5Nos. LT Poles damaged at Hakimpet (5Nos. DTR's kept off)	----
17		Aditya Towers	Surya Nagar	11KV	VII	01.41	05.39	03.58	EL	Tree branches fallen on lines at Surya Nagar	----
18		S.D Hospital	Crescent Hospital	11KV	VII	01.43	02.47	01.04	EL,OL-Rph	No Visible Fault (due to Rain)	----
19		Asif Nagar	Kakatiya Nagar	11KV	VII	01.43	07.15	05.32	EL,OL	3Nos. DTRs fault at Kakatiya Nagar	----
20		Toli Chowki	Ameena Masjid	11KV	VII	01.44	02.52	01.08	EL	No Visible Fault (due to Rain)	----
21		Asif Nagar	Hakimpet	11KV	VII	01.44	05.00	03.16	EL	Tree branches fallen on lines at Hakimpet	----
22		Aditya Towers	Delux Colony	11KV	VII	01.45	04.30	02.45	EL	No Visible Fault (due to Rain)	----
23		Asif Nagar	N.S.F Colony	11KV	VII	01.45	06.35	04.50	EL	Tree branches fallen on lines at Various Places	----
24		Asif Nagar	Avalon	11KV	VII	01.46	04.25	02.39	EL	Tree branches fallen on lines at Mehdipatnam	----
25		Langer House	Maruthi Nagar	11KV	VII	01.47	03.25	01.38	EL,OL	Tree branches fallen on lines at Maruthi Nagar	----
26		Mothi Mahal	Company Bagh	11KV	VII	01.47	03.17	01.30	EL	No Visible Fault (due to Rain)	----
27		Gudimalkapur	Amba Garden	11KV	VII	01.48	06.46	04.58	EL,OL-Rph	Tree branches fallen on lines at Arvinda Eye Hospital	----
28		Langer House	Military Hospital	11KV	VII	01.48	05.30	03.42	EL,OL	CT PT fault at Military Hospital	----
29		Gudimalkapur	Sri Ram Nagar	11KV	VII	01.50	04.04	02.14	EL	No Visible Fault (due to Rain)	----
30		S.D Hospital	Police Mess	11KV	VII	01.50	02.57	01.07	EL	No Visible Fault (due to Rain)	----
31		Asif Nagar	Military	11KV	VII	01.50	04.20	02.30	EL	Tree branches fallen on lines at Military Area	----
32		Golnaka	Brahman Hostel	11KV	II	01.51	03.25	01.34	EL	Faulty loads of 11KV Ramalayam feeder	----
33		Nampally	Red Hills	11KV	VII	01.51	03.57	02.06	EL	HT Jumper cut at Nisha Hospital	----
34		ITI Mallepally	Zaheera Masjid	11KV	VII	01.53	05.03	03.10	EL,OL	No Visible Fault (due to Rain)	----
35		ITI Mallepally	P.S Nagar	11KV	VII	01.54	06.25	04.31	EL,OL	Tree branches fallen on lines at P.S Nagar	----
36		A.C Guards	N.M.D.C	11KV	VII	01.55	05.25	03.30	EL	No Visible Fault (due to Rain)	----
37		ITI Mallepally	Indira Nagar	11KV	VII	01.58	05.15	03.17	EL,OL	Tree branches fallen on lines at Indira Nagar	----
38		ITI Mallepally	Iliyas Road	11KV	VII	01.59	06.15	04.16	EL,OL	Big tree fallen on lines at Police Quarters	----
39		Fever Hospital	Sri Ram Nagar	11KV	II	00.40	00.45	00.05	EL	No Visible Fault (due to Rain)	----
40		Fever Hospital	Sri Ram Nagar	11KV	II	02.00	02.10	00.10	EL	No Visible Fault (due to Rain)	----
41		Bathkammakunta	Ahobilmutt	11KV	II	02.05	04.45	02.40	EL	Cable End Kit failed at Sagarika Apts	----
42		Lake View	Vijaya Hospital	11KV	I	02.05	04.00	01.55	EL	Tree branches fallen on lines at Wipro Residency	Arranged B/F on 11KV Dilkusha fdr
43		Lumbini Park	Avanthi Nagar	11KV	I	02.10	04.44	02.34	EL	Moisture formed in RMU at Basheerbagh	----
44	Narayanguda	City Central Library	11KV	I	02.10	03.50	01.40	EL,OL	No Visible Fault (due to Rain)	----	
45	Industrial Area	Ram Nagar	11KV	II	02.10	03.30	01.20	EL,OL	No Visible Fault (due to Rain)	----	
46	Industrial Area	Mother Dairy	11KV	II	02.16	03.20	01.04	EL,OL-Rph	No Visible Fault (due to Rain)	----	
47	Hussain Sagar	Adarsh Nagar	11KV	I	02.25	03.40	01.15	EL	Tree branches fallen on lines at Adarsh Nagar	----	
48	Osm. University	Boudha Nagar	11KV	II	02.30	06.15	03.45	EL	No Visible Fault (due to Rain)	----	
49	Narayanguda	Narayanguda	11KV	II	03.20	05.40	02.20	EL,OL-Rph	O/G Yph Jumper cut at SS	----	
50	Asif Nagar	Mehdipatnam OH	11KV	VII	03.30	05.22	01.52	EL,OL	No Visible Fault (due to Rain)	Arranged B/F on 11KV Mehdipatnam Cable fdr	