

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | 2 | 10 | 2 | 10 | 2 | 10 | | | |
| 7 | RR(E) | 168 | 403 | | 5 | | 5 | | 5 | | | |
| 8 | Hyd | 194 | 1044 | 2 | 8 | 2 | 8 | 2 | 8 | | | |
| | Total | 606 | 3055 | 4 | 23 | 4 | 23 | 4 | 23 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | 3 | 8 | 3 | 8 | 3 | 8 | | | |
| 2 | NLG | 144 | 988 | | 11 | | 11 | | 11 | | | |
| 3 | MDK | 107 | 933 | 2 | 6 | 2 | 6 | 2 | 6 | | | |
| 4 | SDPT | | | 2 | 28 | 2 | 28 | 2 | 28 | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 7 | 53 | 7 | 53 | 7 | 53 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 11 | 76 | 11 | 76 | 11 | 76 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 15.05.2021

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|-----------------------|---------------------------|
| 1 | MBNR | Mahabubnagar | Machanpally | 33KV | Mahabubnagar | 20.18 | 20.45 | 00.27 | OL | 33KV Line Fault | Machanpally | - |
| 2 | | Maddur | Vepoor | 33KV | Narayanpet | 16.20 | 18.40 | 02.20 | EL&OL | Tree Branch Follen on the line near Thanda | Vepoor | - |
| 3 | | Maddur | Pallerla | 33KV | Narayanpet | 22.00 | 22.35 | 00.35 | E/L | Due to Rain | Pallerla | - |
| 1 | MDK | Gummadidala | Dundigal | 33KV | Patancheru | 16.51 | 18.50 | 01.59 | | BD due to tree branches fallen on line | Dundigal | - |
| 2 | | Gummadidala | AFA | 33KV | Patancheru | 14.35 | 18.55 | 04.20 | | BD due to tree branches fallen on line | AFA | - |
| 1 | SDPT | Mustyala | Nagapuri | 33KV | Husnabad | 14.50 | 17.55 | 03.05 | | branches fallen on 33KV line Tree | Nagapuri | - |
| 2 | | Husnabad | Dharmaram | 33KV | Husnabad | 00.00 | 15.00 | 15.00 | | Insulator failure | Dharmaram | - |
| 1 | RR N | 132KV Medchal | 33KV Shantha Biotech | 33KV | Medchal | 09.31 | 14.00 | 04.29 | | 33KV Line AB Switch Opened(Backfeeding arranged from 33KV Nuthankal feeder(132KV Medchal) | 33KV Shantha Biotech | - |
| 2 | | 132KV Medchal | 33KV Aliabad | 33KV | Medchal | 17.30 | 18.05 | 00.35 | | 33KV Line AB Switch Opened at Forest Area | 33KV Aliabad | - |
| 1 | HYD S | 132KV Moosarambagh | Teegalaguda | 33KV | Malakpet | 06.01 | 06.46 | 00.45 | OL,R-ph | Due to end kit failed beside petrolpump near Moosarambagh | Teegalaguda | - |
| 1 | HYD C | 132KV Asifnagar | Gudimalkapur | 33KV | Mehdipatnam | 09.53 | 09.57 | 00.04 | OL,R-ph | Cable damaged by GHMC at Pillar No.,49 | Gudimalkapur | - |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 15.05.2021

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|---------------------------|
| 1 | MBNR | Mustipally | ANUGONDA | 11kv | Narayanpet | 14.43 | 16.03 | 01.20 | | Due to 11kv line not stable due to wind & gale at anugonda vlg | - |
| 2 | | Manthangoud | KATHWAR | 11kv | Narayanpet | 11.25 | 12.00 | 00.35 | | Due to 11kv line not stable due to wind & gale at kathwar vlg | - |
| 3 | | Thangadi | KUSMURTHY | 11kv | Narayanpet | 09.00 | 10.27 | 01.27 | | Due to 11kv jumper cut and fallen on DTR at kusmurthy vlg | - |
| 4 | | MARIKAL | ELIGANDLA | 11kv | Narayanpet | 13.36 | 13.50 | 00.14 | | Due to 11kv jumper cut and fallen on DTR at Eligandla vlg | - |
| 5 | | DHANWADA | KAMSANPALLY | 11kv | Narayanpet | 09.05 | 09.40 | 00.35 | | Due to LT/HT | - |
| 6 | | GOTUR | GOTUR | 11kv | Narayanpet | 16.00 | 17.30 | 01.30 | | Due to insulator fail at gotur vlg | - |
| 7 | | MADDUR | KHAJIPUR | 11kv | Narayanpet | 16.10 | 17.44 | 01.34 | | Due to 11kv line not stable due to wind & gale at Khajipur vlg | - |
| 8 | | SALKARPET | REDDY PALLY | 11kv | Narayanpet | 14.30 | 18.10 | 03.40 | | Due to LT/HT | - |
| 1 | NLG | Penpahad | Dubbathanda | 11kv | Suryapet | 10.40 | 13.10 | 02.30 | E/L | 11Kv Copper patti cut | - |
| 2 | | Ch.Annaram | Chervuannaram | 11kv | Nalgonda | 09.15 | 10.10 | 00.55 | E/L | 11KV Line Jumper Cut | - |
| 3 | | Settipalem | Settipalem Town | 11kv | Miryalguda | 04.50 | 06.08 | 01.18 | E/L | 11Kv Disc failed | |
| 4 | | Settipalem | Settipalem Town -II | 11kv | Miryalguda | 05.10 | 07.00 | 01.50 | E/L | 11KV Jumper cut | |
| 5 | | Haliya | Ibrahimpet | 11kv | Miryalguda | 10.20 | 12.00 | 01.40 | E/L | 11KV Jumper cut and Lugs failed near SS | |
| 6 | | Guntipally | Yerrabelli | 11kv | Miryalguda | 16.10 | 18.00 | 01.50 | E/L | 11KV Disc insulator failed at SS | |
| 7 | | Gudipally | SIBC | 11kv | Devarakonda | 12.10 | 16.31 | 04.21 | E/L | 11Kv Conductor Snapped & Pin insulator failed | |
| 8 | | Chepur | Tharatigudem | 11kv | Devarakonda | 15.45 | 16.00 | 00.15 | E/L | 11Kv Conductor Snapped | - |
| 9 | | Gurrampode | Chamled | 11kv | Devarakonda | 14.30 | 18.00 | 03.30 | E/L | 11Kv Pin insulator failed | - |
| 10 | | Gurrampode | Chepur | 11kv | Devarakonda | 15.04 | 18.10 | 03.06 | E/L | 11Kv Pin insulator failed | - |
| 11 | | Pochampally | Chinnamandhapuram | 11kv | Devarakonda | 16.23 | 18.15 | 01.52 | E/L | 11Kv Conductor Snapped & Pin insulator failed | - |
| 1 | MDK | EPIP-II | Padmapower | 11kv | Sangareddy | 12.20 | 13.02 | 00.42 | | Bd due to Tree branches fallen on line | - |
| 2 | | MIG | MIG-II | 11kv | Patancheru | 12.45 | 13.00 | 00.15 | | Bd due to Tree branches fallen on line | - |
| 3 | | MIG | Railway Qtrs | 11kv | Patancheru | 15.15 | 17.00 | 01.45 | | Bd due to Tree branches fallen on line | - |
| 4 | | Kistareddypet | Bheeramguda | 11kv | Patancheru | 12.30 | 13.50 | 01.20 | | BD due to Insulator failed | - |
| 5 | | Bollaram - I | Arobindow | 11kv | Patancheru | 19.45 | 23.05 | 03.20 | | BD due to Conductor snapped | - |
| 6 | | Bollaram - I | Town -I | 11kv | Patancheru | 19.10 | 21.45 | 02.35 | | BD due to Insulator failed | - |

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | SDPT | Komaticheruvu | Kushal Nagar | 11kv | Siddipet | 10.39 | 13.15 | 02.36 | | B/D - Tree branches fallen on the line, LC No. 2530 | - |
| 2 | | Mustabad X-Road | Nagadevatha X-road | 11kv | Siddipet | 12.00 | 13.20 | 01.20 | | B/D- HT/LT line face to face | |
| 3 | | Mustabad X-Road | Nagadevatha X-road | 11kv | Siddipet | 17.00 | 18.05 | 01.05 | | B/D- HT/LT line face to face | |
| 4 | | Ragothampally | Ragothampally | 11kv | Siddipet | 02.00 | 08.52 | 06.52 | | B/D - Tree branches fallen on the line | |
| 5 | | Ragothampally | Gosanpally | 11kv | Siddipet | 02.00 | 13.30 | 11.30 | | B/D - Jumper cut, LC No. 15360 | |
| 6 | | Dharmajipet | Dharmajipet | 11kv | Siddipet | 00.00 | 12.15 | 12.15 | | B/D - Tree branches fallen on the line LC No. 22390 | |
| 7 | | Dharmajipet | Lachapet | 11kv | Siddipet | 12.45 | 15.50 | 03.05 | | B/D - Heavy wind & gale | |
| 8 | | Jangapally | Jangapally | 11kv | Siddipet | 11.00 | 13.30 | 02.30 | | B/D - Copper patti failed, LC No. 15506 | |
| 9 | | Husnabad-II | Malapally | 11kv | Husnabad | 14.40 | 18.00 | 03.20 | | Jumper Cut | |
| 10 | | Husnabad | Madatha | 11kv | Husnabad | 07.00 | 08.40 | 01.40 | | Tree banch fallen on line, same rectified | |
| 11 | | Akkannapet | Akkannapet Rural | 11kv | Husnabad | 08.15 | 09.35 | 01.20 | | Tree banch fallen on line, same rectified | |
| 12 | | Gurjakunta | Gurjakunta Agl | 11kv | Husnabad | 12.50 | 14.05 | 01.15 | | Tree banch fallen on line, same rectified | |
| 13 | | Komuravelly | Komuravelly Agl | 11kv | Husnabad | 00.10 | 07.40 | 07.30 | | Insulator failure, same rectified | |
| 14 | | MARKOOK | BHAVANANDAPUR | 11kv | Gajwel | 13:45 | 14:45 | 01.00 | | 11 KV LINE CUT | |
| 15 | | GANESHPALLY | ANGADI KISTAPUR AGL | 11kv | Gajwel | 14:50 | 16:10 | 01.20 | | 11 KV LINE CUT | |
| 16 | | GOWRARAM | TOWN-2 | 11kv | Gajwel | 8:00 | 8:30 | 0:30 | | TREE BRANCHES FELL ON 11 KV LINE | |
| 17 | | THIMMAREDDYPALLY | LAKUDARAM | 11kv | Gajwel | 11:30 | 13:50 | 2:20 | | TREE BRANCH FELL ON 11 KV LINE | |
| 18 | | THIMMAREDDYPALLY | LAKUDARAM | 11kv | Gajwel | 15:15 | 17:15 | 2:50 | | DISC FAILED | |
| 19 | | DOULTHABAD | SHERPALLY BANDARAM | 11kv | Gajwel | 11:23 | 12:50 | 1:27 | | 11 KV LINE PHASE TO PHASE | |
| 20 | | DOULTHABAD | LINGARAJPALLY | 11kv | Gajwel | 14:26 | 14:48 | 0:22 | | TREE BRANCH FELL ON 11 KV LINE | |
| 21 | | DOMMATA | DOMMATA | 11kv | Gajwel | 8:05 | 9:08 | 01.03 | | 11 KV JUMPER CUT | |
| 22 | | GOVINDAPUR | UPPARPALLY | 11kv | Gajwel | 15:10 | 18:16 | 03.16 | | COPPER PATTY CUT | |
| 23 | | GOVINDAPUR | GOVINDAPUR | 11kv | Gajwel | 13:15 | 15:20 | 02.05 | | INSULATOR FAILED | |
| 24 | | GOVINDAPUR | GOVINDAPUR | 11kv | Gajwel | 19:00 | 20:45 | 01.47 | | 11 KV DISC FAILED | |
| 25 | | ANAJIPUR | ANAJIPUR | 11kv | Gajwel | 13.22 | 14.35 | 01.13 | | LT LINE SATT POLE TOUCH | |
| 26 | | GURRALASOFA | RAMARAM | 11kv | Gajwel | 12.45 | 14.40 | 1;55 | | DTR REPAIR | |
| 27 | | METTU | PEDDAMASANPALLY | 11kv | Gajwel | 19:00 | 21:50 | 2:15 | | TREE BRANCH FELL ON 11 KV LINE | |
| 28 | | THUKKAPUR | TS | 11kv | Gajwel | 11:20 | 13:20 | 2:05 | | TREE BRANCH FELL ON 11 KV LINE | |

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | RR N | Subhash Nagar | Gayatri Nagar | 11kv | Medchal | 08.35 | 09.25 | 00.50 | | LT Cable touched the 11KV Line at Gayatri Nagar | - |
| 2 | | Pudur | Pudur | 11kv | Medchal | 12.20 | 13.55 | 01.35 | | Tree Fallen on 11KV Line at Goshaiguda | - |
| 3 | | Devarayamjal | Pothaipally | 11kv | Medchal | 11.30 | 13.30 | 02.00 | | 11KV HG Fuse Insulator Failed at MPP Bavi, Yamjal | - |
| 4 | | Bommarajpet | Ponnal | 11kv | Medchal | 14.08 | 15.28 | 01.20 | | 11KV Copper Patti cut and replaced at Lalitha Garden, Ponnal | - |
| 5 | | Keshavaram | Keshavaram | 11kv | Medchal | 14.10 | 15.20 | 01.10 | | Tree Fallen on 11KV Line at Potharam X Road | |
| 6 | | Laxmapur | Narayanpur | 11kv | Medchal | 13.20 | 17.35 | 04.15 | | Tree Fallen on 11KV Line and 11KV Pin Insulator Failed at narayanpur Village | |
| 7 | | Thumkunta | Thumkunta | 11kv | Medchal | 11.20 | 15.00 | 03.40 | | 11KV Line AB Switch opened at Rajender Dhaba(No Fault) | |
| 8 | | Shameerpet | Devarayamjal | 11kv | Medchal | 15.40 | 16.45 | 01.05 | | No Fault | - |
| 9 | | Ravalkole | IDA Ganapathi | 11kv | Medchal | 06.00 | 07.40 | 01.40 | | Tree Fallen on 11KV Line at Solar Plant | - |
| 10 | | Prshanth Hills | Srinivasa colony | 11kv | Kukatpally | 13.40 | 14.40 | 01.00 | | Garden Lizard fall in on the AB Switch at Balaji water plant | - |
| 1 | RR E | Uppal | Navbharath | 11kv | Habsiguda | 20.30 | 00.25 | 03.55 | | Tree fallen on 11kv line at Aparna redymix, Morder Amruthanjan company & jumper cut at Toyota company | - |
| 2 | | Narapally | Parvathapur | 11kv | Keesara | 11.10 | 15.30 | 04.20 | | Tree branches fallen on 11KV line at Sathi Reddy AGL T/F | - |
| 3 | | Nagaram | Gandhi Nagar | 11kv | Keesara | 10.02 | 12.24 | 02.22 | | Tree fallen on 11KV line at BMR Enclave | - |
| 4 | | Nagaram | Gandhi Nagar | 11kv | Keesara | 13.08 | 14.28 | 01.20 | | 11KV line touched to LT Pole at Pragathi Nagar | - |
| 5 | | Nagaram | Bandlaguda | 11kv | Keesara | 14.34 | 15.50 | 01.16 | | Tree fallen on 11KV line at Hanuman Temple | - |
| 1 | HYD N | R.P Nilayam | Saraswathi Nagar | 11kv | C-VI | 10.15 | 11.20 | 01.05 | EL,OL-Rph | Street Light wire fallen on HT Lines at Malla Reddy Nagar | |
| 2 | | Alwal | Retreat Colony | 11kv | C-VI | 10.55 | 12.05 | 01.10 | EL,OL-Rph | HG fuse blown & HT Jumper cut at Retreat Colony | |
| 3 | | Gunrock | Lalbazar | 11kv | C-VI | 15.10 | 16.21 | 01.11 | OL | No Visible Fault | |
| 4 | | Hakimpet | Hakimpet Airforce | 11kv | C-VI | 12.00 | 15.48 | 03.48 | EI,OL | Tree fallen on lines | |
| 5 | | Chinna Thokatta | Central Excise | 11kv | VI | 15.11 | 16.25 | 01.14 | EL | Tree branches fallen on lines & HT Jumper cut at Vaishanavi Matha | |
| 6 | | H.M.T | Sri Sai Colony | 11kv | VI | 18.45 | 21.00 | 02.15 | EL | Cable fault at IDPL | |
| 1 | HYD C | Industrial Area | Ram Nagar | 11kv | II | 03.40 | 04.47 | 01.07 | EL | No Visible Fault | |
| 2 | | Industrial Area | Mother Dairy | 11kv | II | 03.40 | 04.47 | 01.07 | EL | No Visible Fault | |